	ola County Building onit Expires One Year From the I	
APPLICANT LINDA RODER		ONE 752-2281
ADDRESS 387 SW KEMP COURT	LAKE CITY	FL 32024
OWNER ED & DIANE WHITE	PH	ONE
ADDRESS 7018 SW STATE ROAD		FL 32024
CONTRACTOR ISAAC CONSTRUCTION		ONE <u>719-7143</u>
LOCATION OF PROPERTY 47S, 1 MI	LE PAST WALTER AVE ON RIGHT	
TYPE DEVELOPMENT ADDITION TO S	SFD ESTIMATED COST	OF CONSTRUCTION .00
HEATED FLOOR AREA 2440.00	TOTAL AREA 2440.00	HEIGHT00 STORIES 2
FOUNDATION CONC WAL	LS FRAMED ROOF PITCH	3/12 FLOOR SLAB
LAND USE & ZONING A-3		MAX. HEIGHT 32
Minimum Set Back Requirments: STREET-	FRONT 30.00 RE	AR 25.00 SIDE 25.00
NO. EX.D.U. 0 FLOOD ZONE	X DEVELOPMEN	T PERMIT NO.
PARCEL ID 02-5S-16-03443-002	SUBDIVISION	
LOT BLOCK PHASE	UNIT	TOTAL ACRES
EXISTING 05-0461-N Driveway Connection Septic Tank Number	Contractor's License Number BK LU & Zoning checked by	Applicant/Owner/Contractor N Approved for Issuance New Resident
COMMENTS: ONE FOOT ABOVE THE ROA	LD, NOC ON FILE	Check # or Cash 807
		MENT ONLY
FOR BU	JILDING & ZONING DEPARTN	MENT ONLY (footer/Slab)
		MENT ONLY (footer/Slab)
Temporary Power date/app. by Under slab rough-in plumbing	Foundation date/app. by	MENT ONLY (footer/Slab) Monolithic date/app. by Sheathing/Nailing
Temporary Power date/app. by Under slab rough-in plumbing date/ap	Foundation date/app. by Slab date/app. by	MENT ONLY (footer/Slab) Monolithic date/app. by Sheathing/Nailing date/app. by
Temporary Power date/app. by Under slab rough-in plumbing	Foundation date/app. by Slab date/app. by	MENT ONLY (footer/Slab) Monolithic date/app. by Sheathing/Nailing date/app. by
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in	Foundation date/app. by Slab date/app. by	MENT ONLY (footer/Slab) Monolithic date/app. by Sheathing/Nailing y date/app. by w wood floor date/app. by Peri. beam (Lintel)
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by	Foundation Slab p. by Rough-in plumbing above slab and below Heat & Air Duct date/app. by date/app. by	MENT ONLY Monolithic date/app. by Sheathing/Nailing y date/app. by w wood floor date/app. by Peri. beam (Lintel) date/app. by
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in	Foundation Slab p. by Rough-in plumbing above slab and below Heat & Air Duct	MENT ONLY (footer/Slab) Monolithic date/app. by Sheathing/Nailing y date/app. by w wood floor date/app. by Peri. beam (Lintel)
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by Permanent power	Foundation Slab P. by Rough-in plumbing above slab and below Heat & Air Duct date/app. by C.O. Final date/app. by	MENT ONLY Monolithic date/app. by Sheathing/Nailing y date/app. by w wood floor date/app. by Peri. beam (Lintel) date/app. by Culvert date/app. by Pool
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by Permanent power date/app. by	Foundation Slab p. by Rough-in plumbing above slab and below Heat & Air Duct date/app. by C.O. Final date/app. by date/app. by	MENT ONLY Monolithic date/app. by
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by Permanent power date/app. by M/H tie downs, blocking, electricity and plumbing Reconnection date/app. by	Foundation Slab Poundation Slab Co. Final Slab	MENT ONLY Monolithic date/app. by Sheathing/Nailing w wood floor date/app. by Peri. beam (Lintel) Culvert date/app. by Pool date/app. by date/app. by
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by Permanent power date/app. by M/H tie downs, blocking, electricity and plumbing Reconnection date/app. by	Foundation Slab p. by Rough-in plumbing above slab and below Heat & Air Duct date/app. by C.O. Final date/app. by date/app. by Uti	MENT ONLY Monolithic date/app. by Sheathing/Nailing date/app. by w wood floor date/app. by Peri. beam (Lintel) date/app. by Culvert date/app. by Pool date/app. by
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by Permanent power date/app. by M/H tie downs, blocking, electricity and plumbing Reconnection date/app. by M/H Pole Tra	Foundation Slab	MENT ONLY Monolithic
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by Permanent power date/app. by M/H tie downs, blocking, electricity and plumbing Reconnection date/app. by M/H Pole date/app. by BUILDING PERMIT FEE \$ 950.00	Foundation Slab Poundation Slab S	MENT ONLY Monolithic
Temporary Power date/app. by Under slab rough-in plumbing date/app Framing date/app. by Electrical rough-in date/app. by Permanent power date/app. by M/H tie downs, blocking, electricity and plumbing Reconnection date/app. by M/H Pole date/app. by BUILDING PERMIT FEE \$ 950.00	Foundation Slab Slab Poundation Slab S	MENT ONLY Monolithic

NOTICE: IN ADDITION TO THE REQUIREMENTS OF THIS PERMIT, THERE MAY BE ADDITIONAL RESTRICTIONS APPLICABLE TO THIS PROPERTY THAT MAY BE FOUND IN THE PUBLIC RECORDS OF THIS COUNTY. AND THERE MAY BE ADDITIONAL PERMITS REQUIRED FROM OTHER GOVERNMENTAL ENTITIES SUCH AS WATER MANAGEMENT DISTRICTS, STATE AGENCIES, OR FEDERAL AGENCIES.

"WARNING TO OWNER: YOUR FAILURE TO RECORD A NOTICE OF COMMENCEMENT MAY RESULT IN YOUR PAYING TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. IF YOU INTEND TO OBTAIN FINANCING, CONSULT WITH YOUR LENDER OR AN ATTORNEY BEFORE RECORDING YOUR NOTICE OF COMMENCEMENT."

This Permit Must Be Prominently Posted on Premises During Construction

PLEASE NOTIFY THE COLUMBIA COUNTY BUILDING DEPARTMENT AT LEAST 24 HOURS IN ADVANCE OF EACH INSPECTION, IN ORDER THAT IT MAY BE MADE WITHOUT DELAY OR INCONVIENCE, PHONE 758-1008. THIS PERMIT IS NOT VALID UNLESS THE WORK AUTHORIZED BY IT IS COMMENCED WITHIN 6 MONTHS AFTER ISSUANCE.

Edward C White Diane Bishop White P O Box 2111 Lake City, FL 32056 386-758-9486

July 28, 2006

John Kerce, Building Official Columbia County Building and Zoning Department 135 NE Hernando Avenue Suite B21 Lake City, Florida 32055

Dear Mr. Kerce;

In compliance with the directive that I received from Mr. Joe Haltiwanger issued with regard to my property at 7018 SW SR 47 on December 13, 2005, I am reporting to you on results of structural evaluations on a residential home at the above listed address. According to the professional engineers that examined this structure, your inspectors were indeed correct with regard to structural deficiencies in this project. Additionally, during an inspection yesterday, a structural engineer pointed out that completed work seriously deviated from permitted plans. To him, this constitutes a serious violation of the permit obtained for this project.

Based on this latest information, I feel that your department should conduct an additional inspection of this job site. If it is found that the permit was, in fact, violated, I would expect appropriate actions to be taken to include written documentation of the permit violations.

This has been a long and painful process for my wife and I at a time when we lost our parents to painful illness and tried to transition to our family home here in Lake City. Your immediate attention to this prolonged process would be most appreciated.

Respectfully,

Ed White

FEAGLE & FEAGLE, ATTORNEYS, P.A.
ATTORNEYS AT LAW
153 NE MADISON STREET
POST OFFICE BOX 1653
LAKE CITY, FLORIDA 32056-1653
(386) 752-7191
Fax: (386) 758-0950

Marlin M. Feagle e-mail: leagle@bellsouth.net

August 24, 2006

Mark E. Feagle e-mail: mefeagle@bellsouth.net

Mr. Joe Haltiwanger
Plan Examiner
Columbia County Building Department
135 NE Hernando Avenue, Suite B21
Lake City, Florida 32055

Re: Edward C. White and his wife, Diane Bishop White

Dear Joe:

This will confirm our recent office conference where we discussed the letter from Edward White dated July 28, 2006 addressed to John Kerce, a copy of which is enclosed for your reference. In his letter Mr. White describes that according to the professional engineers that examined the structure, his home, structural deficiencies were noted. Mr. White also points out that during an inspection the structural engineer pointed out that completed work deviated from permitted plans.

Mr. White will need to have his structural engineer and/or architect complete their inspection and investigation. Then, they will need to provide the County with a specific corrective action plan. Based upon this corrective action plan which may include modification of the original construction plans, the County should be in a position to review the same and issue a second permit to either the owner or a state certified licensed building contractor. The County cannot issue a second permit until this information is provided to the County.

If Mr. White believes his state licensed contractor failed to complete the work in a professional manner, his complaint and recourse should be directed to the State of Florida, Department of Business and Professional Regulations, which regulates licensed contractors.

If you need anything further in this regard, please do not hesitate to give me a call.

Very truly yours,

MMF:dse



161 N.W. Madison St., Suite 102 Lake City, Florida 32055 Tel: 386-758-4209

Fax: 386-758-4290

7/28/2006

Ed White P. O. Box 1376 Lake City, FL. 32056

Re: Structural Inspection

Dear Mr. White,

I have completed the structural inspection and have reviewed the original plans and the following evidence is evident:

The plans call for an exterior bearing wall height of 9'0". The exterior bearing walls were constructed at an 8'0" height. The ceiling height of the master bedroom is shown as a 9'0" ceiling height but was constructed as a 10'0" ceiling height. During construction the roof of the first floor interfered with the floor level of the second floor since the wall was constructed 1'0" too short and the floor level 1'0" too high. This caused a problem with floor joist layout as indicated on the plans. Since the floor joists interfered with the incorrectly placed roof system, the floor joists were altered so that they were no longer bearing on the walls as indicated on the plans. The plans did indicate structural load bearing walls to support the upper floor joist system, however, by shifting the bearing locations to new non-structural walls there was no provision for a structural foundation or structural headers. This could cause failure in the slab and wall components.

The two-story portion of the house was not constructed to the proper wall height as indicated on the plans. The original design called for a set of four (4) beams to run continuous from front to rear of the structure. The exterior walls were constructed in this manor to perform as a post and beam system. The beams are intended to span a certain distance and then bear on a post which has a structural footing directly underneath. The exterior walls on the two story portion were altered to bring the height up according to the original design. When this was done, the structural beam was removed in order to build a new knee wall above the original wall that was built too low. This created two main problems. When the beam was removed, the post-beam structure became a continuous load-bearing wall. There is no interior structural footing to carry the load along the entire length of wall. When the knee wall was constructed to extend the

wall height per design, a hinge point was created in the wall. This could likely fail when wind pressure is applied to the wall.

A new wall was constructed on top of the original house. At this point, there is no evidence that the exterior wall is resting on anything structural. The weight of the wall and the roof trusses are only bearing on the existing roof decking and is showing signs of excessive deflection. The load-bearing wall needs to have a continuous load path from the foundation, up to the roof.

In order to solve the issues discussed above the structure would need to be dismantled. A redesign of the project should be accomplished taking into account the correct pitch of the existing roof. It should contain detail for the joining of the new and the old structure and foundation requirements to support changes in the correct plans. Because the structure could not be completed the trusses have now been exposed to the weather for nearly a year and have shown signs of twisting and buckling.

If you have any questions, you may contact me at (386) 758-4209.

Sincerely,

William Freeman, P.E.

Willest Freen

From: The Columbia County Building Department

Plans Review

135 NE Hernando Av.

P. O Box 1529

Lake City Florida, 32056-1529

Dear Mr. Ed White

On December 13, 2005 per your request Mr. Randy Jones Assistant Building Official, Mr. Harry Dicks Building Inspector and I as the Plans Examiner accompanied you with a structural inspection of your resident at 7018 SW SR 47. The inspection pertains to Building permit number 23411 issued July 25, 2005 to ISAAC. This build permit was to construct an addition on to an existing single family dwelling.

You requested that we inspect the structural framing which has been completed thus far for building code compliance. The Columbia County Building Department has several concerns which are:

1. Mr. Robert Taylor Architect, of Associated Florida Architects, Inc. 802 NW 23rd
Avenue Gainesville Florida, State of Florida Registration Number AR-0007526
filed a letter with the Columbia County Building Department on July 22, 2005
which stated that Associated Florida Architects, Inc. were the architects of record
for the construction of a addition on to your single family dwelling. Mr. Robert
Taylor in this letter also stated that certain structural issues which I as the plan
examiner had would be addressed once the construction of this addition was
started. Mr. Robert Taylor stated that within forty-five (45) days of commencing
with construction a written structural report addressing the needed issues would
be filed with the Columbia County Building Department. No reports have been

filed with the Columbia County Building Department by Mr. Taylor or Associated Florida Architects.

- 2. An example of one of the issues which was not addressed was the use of an exterior load bearing foundations and shear walls which was used to construct a second story load bearing wall without the contractor and the architect confirming that the foundation and the structural walls could safely support the additional structural load-bearing weight which has been applied to the foundation and walls for of a second story and a roof truss system.
- 3. The addition onto the structure of 3,044 square feet incorporated a first and second floor, using wood frame structural walls. Within the first floor several exterior and interior load bearing walls have been created to provide support for the second floor, flooring and roof truss system. Several first floor walls lack sufficient structural strength to properly support the second floor.
- The roof trusses have been modified by the contractor, the truss designer will be required to assess the trusses system to certify that the trusses system meet the original truss system design.


In order to continue work on this structure, a structural evaluation by a professional architect or engineer is needed to comply with the Florida Building Codes 2001. If you should have any additional question please contact me.


Thank you,


Joe Haltiwanger Plan Examiner


Columbia County Building Department





















































































a

associated florida architects, inc.

florida registration AA-C001907 802 nw 23rd avenue • gainesville, florida 32609-3534 352 375-3005 • 352 378-2523 • 352 375-5397 fax

July 22, 2005

Columbia County Building Department 135 NE Hernando Ave.

Lake City, FL 32055

Re: Ed & Diane Bishop-white Residence

To Whom It May Concern:

We are the architects for the referenced project. We have a full service contract with the owners including contract administration.

Due to the fact that this is an addition we will be able to do the discovery work on the existing residence when construction commences.

We will write a report with findings and recommendations within forty-five (45) days of start of construction. As per 3401.8.2.3.1, 3401.8.2.3.2 and 3401.8.2.3.3 of 2001 Florida Building Code.

Robert S. Taylor, Sr. Architect

Florida Registration AR-0007526



associated florida architects, inc.

florida registration AA-C001907 802 nw 23rd avenue • gainesville, florida 32609-3534 352 375-3005 • 352 378-2523 • 352 375-5397 fax

July 22, 2005

Isaac Construction Lake City, Florida 34474

ADDENDUM NUMBER ONE:

Contract Drawings – Dated 09 May 05 Revision Date 21 July 2005 Architect's File Number 0317

The following changes, revisions or deletions to the original Drawings, or previously issued Addenda shall be made by this Addendum.

This Addendum is issued to revise and clarify items addressed by a Letter from the Columbia County Building & Zoning Department dated 08 July 2005 dealing with Plan Review.

- 1.) REPLACE EXISTING FLOOR PLAN SHEET WITH NEW FLOOR PLAN (SHOWING DOOR SIZES)
- REPLACE EXISTING FRAMING PLAN SHEET WITH NEW FRAMING PLAN SHEET.
- 3.) REPLACE EXISTING ELEVATION SHEET WITH NEW ELEVATION SHEET.
- 4.) ADD SHEETS S-1 (STRUCTURAL NOTES) AND S-2 (STRUCTURAL DETAILS.
- 5.) PROVIDE G.F.C.I. OUTLETS IN ALL SLEEPING ROOMS AS PER 2001 FLORIDA BUILDING CODE.
- 6.) PROVIDE SMOKE DETECTORS AS PER 2001 FLORIDA BUILDING CODE
- 7.) ALL GLASS WITH 18 INCHES ABOVE THE FLOOR SHALL AND THE GARDEN TUB SHALL BE SAFETY GLAZING AS PER 2405.2.4. OF THE 2001 FLORIDA BUILDING CODE.

Robert S. Taylor, Sr. - Architect Florida Registration AR-0007526

Date	Inspection	Inspect.	Owner	Pass	Location	Permit
08/09/05	Temp Service	Randy	Issac Bratkovich - White	OK	7018 SW SR 47	23411
08/15/05	Rough Plumbing	Randy	Issac Bratkovich - White	OK	7018 SW SR 47	23411
09/06/05	Mono Slab	Randy	Issac Bratkovich - White	OK	7018 SW SR 47	23411
09/06/05	Set Backs	Randy	Issac Bratkovich - White	OK	7018 SW SR 47	23411
12/13/05	Complaint	HD-RJ-JH	Issac Bratkovich - White	Met With	7018 SW SR 47	23411

New Construction Subterranean Termite Soil Treatment Record

OMB Approval No. 2502-0525 (exp. 10/31/2005)

This form is completed by the licensed Pest Control Company.

Public reporting burden for this collection of information is estimated to average 15 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is mandatory and is required to obtain benefits. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

Section 24 CFR 200.926d(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires the builder to certify that an authorized Pest Control company performed all required treatment for termites, and that the builder guarantees the treated area against infestation for one year. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential.


This report is submitted for informational purposes to the builder on proposed (new) construction cases when soil treatment for prevention of subterranean termite infestation is specified by the builder, architect, or required by the lender, architect, FHA, or VA.

All contracts for services are between the Pest Control Operator and builder, unless stated otherwise.

#23411

ction 1: General Information (Treating Company Information)	: 100 HTM : 100
Company Name: Aspen Pest Control, Inc. Company Address: 301 NW Cole Terrace	Letra City FL 32035
Company Address: 301 NW Cole Terrace Company Business License No. JB109476	City State Zip
Company Business License No.	Company Phone No.
FHA/VA Case No. (if any)	
ction 2: Builder Information	
Company Name: I saar tony t	Company Phone No.
ection 3: Property Information	
Location of Structure(s) Treated (Street Address or Legal Descrip	ption, City, State and Zip) 701% 5.W State And 97
Type of Construction (More than one box may be checked) Approximate Depth of Footing: Outside	Slab Basement Crawl Other Type of Fill
ection 4: Treatment Information	
Deced Name of Braduat/o) Hood Surryady	7
EPA Registration No. Approximate Final Mix Solution %	
Approximate Final Mix Solution %	Linear ft Linear ft, of Masonry Voids
Approximate Total Gallons of Solution Applied	Linear ft Linear ft. of Masonry Voids
Was treatment completed on exterior? ☐ Yes ☐ No	
Service Agreement Available?	
Note: Some state laws require service agreements to be issued	d. This form does not preempt state law.
Attachments (List)	
Comments 2 9 40 5, ZX Mc	no Action to South sud
of home	
of home	JE104376
	Certification No. (if required by State law)
ame of Applicator(s)	Certification No. (if required by State law)
ame of Applicator(s)	JE104376
ame of Applicator(s) ne applicator has used a product in accordance with the product label	Certification No. (if required by State law)
ame of Applicator(s) The applicator has used a product in accordance with the product label derail regulations. Suthorized Signature	Certification No. (if required by State law) and state requirements. All treatment materials and methods used comply with state Date
ame of Applicator(s) The applicator has used a product in accordance with the product label derail regulations. Suthorized Signature	Certification No. (if required by State law) and state requirements. All treatment materials and methods used comply with state

3,72,7203		
CF Mg (0.004754004 53:01 30PAP851P8	BLDG ARD KUNUNG	PASE 91
Columbia County Buil	ding Permit Application	Revised 9-23-04
	Date Received 6/28/05 By Ju P	2341
For Office Use Only Application # 0506-88	Date Received 9 19(1) By 111 Date Date 3,07.05 Plans Examiner 0/	MATH Date 7-22-05
	Date 13.0 Plans Examines 1/1	o Catagoo 4-3
Flood Zone Development Permit	Zoning A-3 Land Use Plan Ma	b catagor)
Comments		- 7.
-NOC-NEEDED -		
Applicants Name Linda Or Melanie R	oda Phone 75	1855-7
Address 387 S.W. Kemp G. Cak	ecity FC SZOZY	The second secon
Owners Name Ed & Diane White	Phone	77221
911 Address 7018 Sow. State R	197 Cake City PC	32024
Contractors Name Isaac Construct	on. Dnc . Phone	719-7143
Address 1005 S.W. Walter A	ve,	- Annual Control of the Control of t
Fee Simple Owner Name & Address		A STATE OF THE STA
Bonding Co. Name & Address		100
Architect/Engineer Name & Address ASSOCIO	ted Plorida Hychitect	s/Work Disosman
Mortgoge Lenders Name & Address Columb	a County Bank	
Circle the correct power company - FL Power & Lig	ht - Clay Elec - Suwannee Valley I	Hec Progressive Energy
Property ID Number 02-55-16-03943	002 Estimated Cost of Construct	ion 190,000 Char
Subdivision Name	Lot Block	Unit Phase
on R- tratiste driven	post Walter ave s	er Isaacsign
Type of Construction SFD addition	Number of Existing Dwellings	on Property
Total Acreage 10 Lot Size Do you nee		
		000 Reg 500
Actual Distance of Structure from Property Lines - Fro Total Building Height 32 an Number of Stories	2 300 Side - 100 3000 3090	130 Roof Pitch 3-12
Total Building Height Number of Storie	os 6991400	
Application is hereby made to obtain a permit to do vinstallation has commenced prior to the issuance of all laws regulating construction in this jurisdiction.	vork and installations as indicated. I ce a permit and that all work be performed	rtify that no work or i to meet the standards of
OWNERS AFFIDAVIT: I hereby certify that all the fore compliance with all applicable laws and regulating co	onstruction and zoning.	
WARNING TO OWNER: YOUR FAILURE TO RECORD TWICE FOR IMPROVEMENTS TO YOUR PROPERTY. LENDER OR ATTORNEY BEFORE RECORDING YOU	IF YOU INTEND TO OBTAIN FINANCIN	G, CONSULT WITH YOUR
Owner Builder or Agent (Including Cont Batthara C.	Webster Contractor Signature	PRI NEGZO
STATE OF FLORIDA COUNTY OF COLUMBIA COUNTY OF COLUMBIA COUNTY OF COLUMBIA COUNTY OF COLUMBIA	DD329279 Contractors License Numb	
Sworn to (or affirmed) and subscribed before me		1.1012



.

j. 1

THIS DOCUMENT WAS PREPARED WITHOUT BENEFIT OF TITLE SEARCH.

FOR RECORDER

THIS INSTRUMENT WAS PREPARED BY: Krista L. Waldron, Esquire (PES) Fisher, Tousey, Leas & Ball, P.A. 818 North A1A, Suite 104 Ponte Vedra Beach, Florida 32082

hst:2003008855 Date:04/29/2003 Time:09:29 oc Stamp-Deed : 0.70 DC, P. DeWitt Cason, Columbia County B:981 P:2183

SPECIAL WARRANTY DEED

, 2003, between VIRGINIA H. THIS INDENTURE, made this 28 day of APRIL BISHOP, as Trustee of the Virginia H. Bishop Living Trust, whose address is P. O. Box 1298, Lake City, Florida 32056, party of the first part, and EDWARD C. WHITE, JR. and DIANE B. WHITE, husband and wife, whose address is 80 Cliffcreek Trace, Atlanta, Georgia 30350, parties of the second part.

WITNESSETH:

That the said party of the first part, in consideration of love and affection, has granted, bargained, and convoyed to the said parties of the second part, their heirs, successors and assigns forever, her remaining one-half interest in the following described lands, situate, lying and being in Columbia County, Florida, to wit:

Commence at the Southwest Corner of the Southwest 1/4 of Northwest 1/4 of Section 2, Township 5 South, Range 16 East and run thence North 0 degrees 49 minutes West along the West line of said Section 2, 652.91 feet for Point of Beginning; thence continue North 0 degrees 49 minutes West along the West line of said Section 2, 500 feet; thence run South 65 degrees 59 minutes 30 seconds East, 1000.05 feet to the Northerly line of State Road No. 47; thence run South 40 degrees 53 minutes West along the West line of State Road No. 47 a distance of 474.23 feet; thence run North 65 degrees 59 minutes 30 seconds West, a distance of 652.5 feet more or less to the Point of Beginning, said land lying in the Southwest 1/4 of the Northwest 1/4 of Section 2, Township 5 South, Range 16 East, Columbia County, Florida, containing 10 acres, more or less.

Real Estate Assessment No: 02-5S-16-03443-002

Subject to covenants, restrictions, easements, mortgages and all other encumbrances of record and taxes assessed subsequent to December 31, 2002; provided, however, this reference will not serve to reimpose any such covenants, restrictions or easements.

		29	Time: 09: 2	29/200	3008855 Date: 04/2	nst: 200	
. De Ba							
p-2184	8-991	Complex	a-1bia	70	p-Deed: 0.7	oc Stam	
A . MAY »	D. 792	I come	COTORDIA	t Caso	E DC, P. DeWitt	THE	
	10.2			28			
	- 1			,		i	
8				2, K		4	
						a	

And the said party of the first part does hereby fully warrant the title to said land, and will defend the same against the lawful claims of all persons whomsoever claiming by, through or under the said party of the first part, but not otherwise.

IN WITNESS WHEREOF, the undersigned has hereunto set her hand and seal as of the day and year first above written.

Signed and Sealed in Our Presence:

Print Name:

VIRGINIA H. BISHOP, as Trustee of the V rginia H. Bishop Living Trust

Print Name:

STATE OF FLORIDA COUNTY OF COLUMBIA

Colored to the Colored Sta

The foregoing instrument was acknowledged before mc this 28 day of WARL, 2003, by VIRGINIA H. BISHOP, as Trustee of the Virginia H. Bishop Living Trust, (notary must check one box): Who is personally known to me or () who has produced _ (State) driver's license No. as identification.


NOTARY PUBLIC, State of


Commission Number:



Notes:

Application for Onsite Sewage Disposal System Construction Permit. Part II Site Plan Permit Application Number: 05-046/N





FAX

Date: 7-12-05

To: Brian Luprer

From: Linda

North Florida Permit Services, INC. Ph; 386-752-2281 Fax: 386-752-2282


* Pages: >

Attn: Brian

Here is revised site Plan for Edwhite.

Columbia County Property Appraiser - Map Printed on 7/12/2005 1:13:10 PM

Page 1 of 1



This information, GIS Map Updated: 6/2/2005, was derived from data which was compiled by the Columbia County Property Appraiser
Office solely for the governmental purpose of property assessment. This information should not be relied upon by anyone as a
determination of the ownership of property or market value. No warranties, expressed or implied, are provided for the accuracy of the data
herein, it's use, or it's interpretation. Although it is periodically updated, this information may not reflect the data currently on file in the
Property Appraiser's office. The assessed values are NOT certified values and therefore are subject to change before being finalized for ad
valorem assessment purposes.

http://appraiser.columbiacountyfla.com/GIS/Print_Map.asp?pjbnlkplhgmeclpofffddhfachd... 7/12/2005

HALL'S PUMP & WELL SERVICE, INC.

SPECIALIZING IN 4"-6" WELLS



DONALD AND MARY HALL OWNERS

PHONE (904) 752-1854 FAX (904) 755-7022 MEANORY & FIRST STREET X LAKE CITY, FLORIDA 32055 904 NW Main Blvd.


June 12, 2002

NOTICE TO ALL CONTRACTORS

Please be advised that due to the new building codes we will use a large capacity diaphram tank on all new wells. This will insure a minimum of one (1) minute draw down or one (1) minute refill. If a smaller diaphram tank is used then we will install a cycle stop valve which will produce the same results.

If you have any questions please feel free to call our office anytime.

play Ha Donald D. Hall DDH/jk





This information, GIS Map Updated: 4/4/2005, was derived from data which was compiled by the Columbia County Property Appraiser Office solely for the governmental purpose of property assessment. This information should not be relied upon by anyone as a determination of the ownership of property or market value. No warranties, expressed or implied, are provided for the accuracy of the data herein, it's use, or it's interpretation. Although it is periodically updated, this information may not reflect the data currently on file in the Property Appraiser's office. The assessed values are NOT certified values and therefore are subject to change before being finalized for ad valorem assessment purposes.

http://appraiser.columbiacountyfla.com/GIS/Print_Map.asp?pjbnlkplhgmeclpofffddhfacbd... 4/28/2005

Application for Onsite Sewage Disposal System Construction Permit. Part II Site Plan Permit Application Number: 05-046/N

ALL CHANGES MUST BE APPROVED BY THE COUNTY HEALTH UNIT





This information, GIS Map Updated: 4/4/2005, was derived from data which was compiled by the Columbia County Property Appraiser
Office solely for the governmental purpose of property assessment. This information should not be relied upon by anyone as a
determination of the ownership of property or market value. No warranties, expressed or implied, are provided for the accuracy of the data
herein, it's use, or it's interpretation. Although it is periodically updated, this information may not reflect the data currently on file in the
Property Appraiser's office. The assessed values are NOT certified values and therefore are subject to change before being finalized for ad
valorem assessment purposes.

http://appraiser.columbiacountyfla.com/GIS/Print_Map.asp?pjbnlkplhgmeclpofffddhfacbd... 4/28/2005

FORM 600B-01

AND ADDRESS:

FLORIDA ENERGY EFFICIENCY CODE FOR BUILDING CONSTRUCTION Residential Component Prescriptive Method B

NORTH 123

Compliance with Method B Chapter 6 of the Florida Energy Efficiency Code may be demonstrated by the use of Form 600B for single and multifamily residences of 3 stories or less in height, and additions to existing residential buildings. To comply, a building must meet or exceed all of the energy efficiency prescriptives in any one of the prescriptive component packages and comply with the prescriptive measures listed in Table 68-1 of this form. An alternative method is provided for additions of 600 square feet or less by use of Form 600C. If a building does not comply with this method, it may still comply under other sections in Chapter 6 of the Code. PROJECT NAME: 15,3 Lop White BUILDER:

0	WNER:	21.3	Dr 0	R-1 1	11 c) P	PERMIT NO.:	<u> </u>	T I	Marc	oun	ZONE: 1	2	3	
GEN	ERAL DIREC	TIONS	Drane						1.		JURISDICTION NO.:			
. Ne	ew constructio	on including add	itions which incorporates a	y of the following leatures	cannol comply using	this mathed at	ol at d	ollo circi		No.	construction, or skylights or of			1
. a	hoose one of the	he component	packages "A" through "E" in	mTable 6B-1 by which you	intend to comply with	the Code. Circ	de the col	alis, single lumn of th	e assembly e nackada	root/ceiling	construction, or skylights or of	her non-ve	rtical roof	glass.
					information requested	All To Be Ins	talled" val	ues must	be equal to	or more of	hosen. ficient than the required levels.		.0.2	
i. Re	ad Minimum	Requirements	"To Be Installed" column in for All Packages", Table 68	ormation.		£ 100 d	200	2 44			undir und required levels.			
Re	ead, sign and o	date the "Prepa	red By" certification statement	nt at the bottom of page 1	The owner or owner	comply with all a	applicable	items.	o low-		, MARKET 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	i nin		
-		The state of	5 7	- F-54 (1	- The of United	, agoin intol d	ov sign a	NU UNIE IN	e IOM.	7 T SHE	and the second second			
	Comp	liance r	ackage chose	n (A.E)	* 11	11 87					Please Print	1.5		CK
2.	New	onstruc	tion or addition	n (A-F)		i de la compania. No servicio	3.77	1.	4)		2		
					The state of	5.1	9-14	2.	895	1141	The same of the contractions		1	
i.	H Mills	lfamilie	detached or N	untiramily atte	ched		- min	3.	201	· Fa	M.,			y -
· ·	le this	a were	-No. of units t case? (yes / i	covered by th	is submiss	ion		4.	=		<u> </u>		4	
i.	Condi	tioned 4	loor see /	10)				5.	N	0				-
	Prede	minent	loor area (sq.	τ.)		111 2		6.	30	44			2	
	Gleec	tune e-	eave overhand d area :) (n.)		and from		7.	3	\$	a transference in	SLET	38	PS.
•		Clear			lege a market		1		Single	Pane	Double P	ane	25	-
	a. b.			es la milione	MILEL CONTR	Segs tour	Senie	8a.			sq. ft	_sq. 1	1.	
		nini, ili	m or solar scre	en				8b.			sq. ft. 634	_sq. 1	100	8
	Floor	hage of	glass to floor	area		and District Control	4-100	9.	30		%	a and		*1
U.	rioor 1	type, are	ea or perimete	r, and insulati	on:		1,000	ti cari	State.	- ap 35			34 -	
	a.	SIAD O	n grade (R-valu	ie)				10a.	R=	0) of the second	in. ft.	1 a	
	p.	wood,	raised (R-value	9)	gerendiken jaring. Dan seletan kanana	10 ST	Constitution of the Consti	10b.	R=			g. ft.	-	1
	C.	Wood,	common (R-va	lue)	and the second		.00	10c.	R=	ria risez		q. ft.	1-	
			te, raised (R-v		With State	Supplied to	PETAGE	10d.	R=	F.S. 41		q. ft.	1-	-
	е.	.Concre	ite, common (F	-value)	de représenta	San Sir mire	ALC: N	10e.	R=	al 5			1-	-
1.	Wall ty		and insulation		ting to be the	A Paris	pale f	PETER MELENE		A 20	- 441	q. ft.	-	-
	a.	Exterio	r: 1. Masonry	(Insulation R-v	alue)	ardy make	-10	11a-1	R=	of Films	n na santani njema 1926. Tito politika injektora 202	~ 4	a ore a	- 12
	STATE OF THE		2. Wood fra	me (Insulation	R-value)	i, tiletose		11a-2		11	16110	q. ft.	-	
	b.	Adjace	nt: 1. Masonry	(Insulation R-v	alue)	NO PERSONAL PROPERTY.	400	11b-1	100000	-/-/		q. ft.	1-	-
			2. Wood fra	me (Insulation	R-value)	rapas yras		11b-2		7		q. ft.	Taken	-
2.	Ceiling	j type, a	rea and insula	tion:	HOUSE HELD	They are in the sixt	777	Telep -	e e	(X 10)	_ x-9 \$	q. ft.	100	
	a.	Under	attic (Insulation	R-value)	erengi (r.), este jihan	Julieria Joy Joseph		12a.	P-	30	2440s	reju iri	green.	
	b.	Single a	assembly (Insu	ation R-value)	reserve and the		SECTION CO	12b.	R=	-	영어 바닷글 나라 그 이 이 사람이 되었다.	200	-	
3.	Air Dis	tributio	1 System: Duc	t insulation, le	ocation	19. 		3.		0		1. ft.	-	-
1	Tes	st report	(attach if requ	red)		1917 tu	41-2555 w No.	Study Line	rypex				-	-
. (Cooling	g syster	n.,	dulette kalendari	e de felo per est				SEER/			<u> </u>	-	-
	(Тур	es: centra	, room unit, packa	ge terminal A.C. o	as, none)	energiae de la composition della composition del							_	
. 1	Heating	systen	New contract of		tive but	in intellige		50	oapa(2 7	STON		1	
			elec. strip, nat. gas			? none\		Sh.	Type:	NOCE !	AT rum,	0	-	
		eria Marijana	an Algalitya Jasharen		A STATE OF THE STA	o, none)					AFUE:	100	57.5	
. 1		ter syste		day one basing	har - He social	लयसम्बद्धाः स्थापन्ति । जिल्लाहरू		JC. (-apac	ity:	OOK,		1 (90)	10
	100000	at the state of the second	as, L.P. gas, solar,	heat rec. dod be	at nume att	deprises				C1	ect. HR	U	-	
1		e jaly	infine	near rec., ded. ne	at pump, otner	, none)	1	6b. I	5E: <u>3</u> <u>6</u>	4		. Add	1	
nere	by certify th	nat the plans	and specifications cover	ed by the calculation	and the state of t	102 / 21 B	Oviou of	place :	1 (7 , 198)	201-		14:a.t.	150 mg	
		ode		2 strategiation and	e in compliance wit	and the second					ered by this calculation indi- ruction is completed, this bui	ding will	pliance v	with
REP	by ceftily the	at this building	, as designed, is in comp	0 7 D	ATE: 6 - 6	00		dive in a	CCOTOMICE	with Sec	tion 553.908, F.S.	Janey Wild	-c mapec	eu.
WIT	ER AGENT:	No	ide Puzzle	1 N	1 -	011			AL:				-cirl-	40%
CONTRACT		-	DE — BUILDING		ATE O	1 C 1 D	ATE: _	12000	e-bayersky	BELL !	The state of the s	S. There's	10 CH	sil

	T
1	-
١	Ŕ
١	L
	L
	Г
	ı
	8
	B.
	ı
	ı.
	B
	۱
	1
	ı
	ı
	ı
	ă
	8
	1
	1
	1
	1
	1
	.1
	1
	١
	١
	-
	- 1
	- 1
	1
	3
•	

COMP	ONENTS		PACKAGES F	OR NEW CONST	RUCTION				
in the said	arther a first transfer of		В	C. C.		E. D.			
\neg	Max.%of glass to Floor Area	15%	15%	20%	20%	. 25%			
GLASS	Туре	Double Clear (DC)	Double Clear (DC)	Double Clear (DC)	Double Clear (DC)	Double Tint (DT)			
	Overhang	1'4"	2'	2'	2'	2'			
	Masonry	onservity (EXTERIOR AND A	DJACENT MASON		2740 1200 1200 1200 1200 1200			
WALLS	Wood Frame	EX	EXTERIOR, ADJACENT, AND COMMON WOOD FRAME WALLS R-11						
CEILINGS		R-30	R-30 (NO SINGLE AS	R-30 SEMBLY CEILING	R-30 SS ALLOWED)	R-30			
-LOORS	Slab-On-Grade								
	Raised Wood	R-19 (ONLY STEM WALL CONSTRUCTION ALLOWED EXCEPT PACKAGE C)							
F	Raised Concrete	Andrews and a grant of the R-7							
DUCT	rs	R-6	R-6	R-6, TESTED	R-6	R-6, TESTED			
SPAC	E COOLING (SEER)	12.0	10.5	12.0	11.0	12.0			
A	Elect. (HSPF)	7.9	7.1	7.4	7.4	7.4			
HEAT	Gas/Oil (AFUE)		4.75 1.000						
WATER	Electric Resistance**	EF .88	NOT ALLOWED (SEE BELOW)	EF .91 NOT ALLOWED (SEE BELOW)		EF .91			
	Gas & Oil **		MINIMUM E	F OF .54		NATURAL GAS ON (SEE BELOW)			
HOT	Other	Any of the follow	wing are allowed: d	ledicated heat pun	np, heat recovery u	ınit or solar syster			

7	A 4	Zone		23
	O BE IN			4.1
DC: 🗹	20			%
DC:		DT: [and the second
-6	4		FEET	
EXT:	R = _	200		1
ADJ:				_
COM:	R=_			
EXT:	R=_	13	P	2
ADJ:	R=_	_		
	R=_			_
	ATTIC		30	_
R =	0	ele su		_
R=_	7,200	SEM SE		10.14
R=_				
R = _	0	CON	ID.	
SEER	- 1	2.	0	
COP=		7, 9	L	
AFUE	=			
EF=	No.	1760		110
EF=	- 1	ř.,		
DHP: HRU: SOLA		EF		_

Single package units minimum SEER=9.7, HSPF = 6.6.

DESCRIPTION OF BUILDING COMPONENTS LISTED

Percent of Glass to Floor Area: This percentage is calculated by dividing the total of all glass areas by the total conditioned floor area.

Overhang: The overhang is the distance the roof or soffit projects out horizontally from the face of the glass. All glass areas shall be under an overhang of at least the prescribed length with the following exceptions: 1) glass on the gabled ends of a house and 2) the glass in the lower stories of a multi-story house.

Wall, Ceiling and Floor Insulation Values: The R-values indicated represent the minimum acceptable insulation level added to the structural components of the wall, ceiling or floor. The R-value of the structural building materials shall not be included in this calculation. "Common" components are those separating conditioned tenancies in a multifamily building. "Adjacent" components separate conditioned space from unconditioned but enclosed space. "Exterior" components separate conditioned space from unconditioned and unenclosed space.

Floor: Slab-on-grade floors without edge insulation are acceptable. Raised wood floors shall have continuous stem walls with insulation placed on the stem wall or under the floor except Package C.

Prior: State-on-grade noors without edge insulation are acceptable. In assed wood noors shall have continuous stem walls with insulation placed on the stem wall or under the noor except Package C.

Ducts: "TESTED" shall mean the ducts have less than 5% leakage based on a certified test report by a State-approved tester.

Space Cooling System: Cooling systems shall have a Seasonal Energy Efficiency Ratio (SEER) for central units or Energy Efficiency Ratio (EER) for room units or PTAC's equal to or greater than the prescribed value.

Electric Space Heating Option: Heat pump systems shall be rated with a Heating Seasonal Performance Factor (HSPF) equal to or greater than the prescribed HSPF. Heat pump systems may contain electric strip backups meeting the criteria of section 608.1.ABC.3.2.1.2. No electric resistance space heat is allowed for these packages.

Electric Resistance Hot Water Option: For packages designated "Not Allowed", an electric resistance hot water system may be installed only in conjunction with one of the "Other Hot Water System Options". See below.

Other Hot Water System Options: Any dedicated heat pump, heat recovery unit, or solar hot water system may be installed. Solar systems must have an EF of 1.5 or higher. Electric resistance systems having an EF of .88 or greater, or natural gas systems with EF .54 or greater may be used in conjunction with these systems.

COMPONENTS	SECTION	REQUIREMENTS	CHECK
Exterior Joints & Cracks	606.1	To be caulked, gasketed, weather-stripped or otherwise sealed.	1/
Exterior Windows & Doors	606.1	Max .3 cfm/sq.ft. window area; .5 cfm/sq.ft. door area.	1
Sole & Top Plates	606.1	Sole plates and penetrations through top plates of exterior walls must be sealed.	1/
Recessed Lighting	606.1	Type IC rated with no penetrations (two alternatives allowed).	2
Multi-story Houses	606.1	Air barrier on perimeter of floor cavity between floors.	-
Exhaust Fans	606.1	Exhaust fans vented to unconditioned space shall have dampers, except for combustion devices with integral exhaust ductwork.	/
Water Heaters	612.1	Comply with efficiency requirements in Table 6-12. Switch or clearly marked circuit breaker (electric) or cutoff (gas) must be provided. External or built-in heat trap required for vertical pipe risers.	/
Swimming Pools & Spas	612.1	Spas & heated pools must have covers (except solar heated). Non-commercial pools must have a pump timer. Gas spa & pool heaters must have minimum thermal efficiency of 78%.	/
Hot Water Pipes	612.1	Insulation is required for hot water circulating systems (including heat recovery units).	V
Shower Heads	612.1	Water flow must be restricted to no more than 2.5 gallons per minute at 80 PSIG.	
HVAC Duct Construction, Insulation & Installation	610.1	All ducts, fittings, mechanical equipment and plenum chambers shall be mechanically attached, sealed, insulated and installed in accordance with the criteria of Section 610.1. Ducts in attics must be insulated to a minimum of R-6.	/
HVAC Controls	607.1	Separate readily accessible manual or automatic thermostat for each system.	-


Minimum efficiencies for gas and electric hot water systems apply to to 40 gallon water heaters. Refer to Table 6-12 for minimum Code efficiencies for oil water heaters and other sizes.

white Kosidena BOOZER QTY 90° CORNERS (BUH GLAZED) 80" TAIL 36" X 80" STORE FRONT 84" x 72" STOREFRONT PENTAGON 90° Corners (But glazed) 80" TAIL (1) 84" X 80" STORE FRONT 96" × 108" STORE FRONT THIS MUST BE Split into apes. 90° CORNERS (BUH glAZED). 108" TAIL 84" X 108" STORE FRONT THIS MUST BE Split into Zpes. 60" X 48" STORE FRONT 1-RIGHT

386-454-0395

Chris Whitefield

May 26 05 07:24a



1/8"= 1 Foot To Scale

386-454-986

Chris Whitfield

645:70 80 85 80"

FORM 600B-01

FLORIDA ENERGY EFFICIENCY CODE FOR BUILDING CONSTRUCTION Residential Component Prescriptive Method B

NORTH 123

Compliance with Method B Chapter 6 of the Florida Energy Efficiency Code may be demonstrated by the use of Form 600B for single and multifamily residences of 3 stories or less in height, and additions to existing residential buildings. To comply, a building must meet or exceed all of the energy efficiency prescriptives in any one of the prescriptive component packages and comply with the prescriptive measures listed in Table 6B-1 of this form. An alternative method is provided for additions of 600 square feet or less by use of Form 600C. If a building does not comply with this method, it may still comply under other sections in Chapter 6 of the Code.

PROJECT NAME:

BUILDER:

•	ND ADDRESS:	PERMITTING	CLIMATE	1.111/
		OFFICE: Colmbra Co	CLIMATE ZONE: 1 2	2/
0	WHER: EJ & Drane Brohop White	DEDINE NO FILE	JURISDICTION NO.: Z 7	3 /
N	ERAL DIRECTIONS	PERMIT NO.: 23 411	TOWN NO.: 22/	000
Ve	w construction including additions which incorporates any of the following leatures cannot comply up	sing this mathod steel shad walls single seconds.	n. T.	1.7
				al roof glass.
, m	in all the applicable spaces of the 10 be installed column on Table 68-1 with the information require	ested. All "To Be Installed" values must be equal to or i	nore efficient than the required levels.	- 1
-	nplete page 1 based on the "To Be Installed" column information. ad "Minimum Requirements for All Packages", Table 6B-2 and check each box to indicate your inter			
Re	ad, sign and date the "Prepared By" certification statement at the bottom of page 1. The owner or or	it to comply with all applicable items. Viner's agent must also sign and date the form		
-				
	Compliance neckage shares (A.E.)		Please Print	СК
	Compliance package chosen (A-F) New construction or addition	1.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
•			410N	
	Single family detached or Multifamily attached		town.	
· ·	If Multifamily—No. of units covered by this submi	State of the Control	at the state of th	
	Is this a worst case? (yes / no) Conditioned floor area (sq. ft.)	5. <u>N</u> C) 	1
	Predominant eave overhang (ft.)	6. <u>30</u>	44	1
	Glass type and area:	73		10
•	a. Clear glass	Single F		14
	b. Tint, film or solar screen		sq. ft sq. ft.	-
	Percentage of glass to floor area	8b	sq. ft. <u>639</u> sq. ft.	
	Floor type, area or perimeter, and insulation:	9. 20	%	
٠.	a. Slab on grade (R-value)		The state of the s	200
	b. Wood, raised (R-value)	The state of the s	lin. ft.	100
	c. Wood, raised (N-value)		sq. ft.	
	d. Concrete, raised (R-value)		sq. ft.	Line 1
	eConcrete, common (R-value)		sq. ft.	117
1.	Wall type, area and insulation:	10e. R= _	sq. ft.	
	a. Exterior: 1. Masonry (Insulation R-value)		the same of the public	0-12
	2. Wood frame (Insulation R-value)	11a-1 R= _	sq. ft.	
	b. Adjacent: 1. Masonry (Insulation R-value)		// 1749 sq. ft.	_
	Wood frame (Insulation R-value)	11b-1 R= _	sq. ft.	H <u>araka</u>
2.	Ceiling type, area and insulation:	11b-2 R= _	sq. ft.	75. W
	a. Under attic (Insulation R-value)	12a. R= 3	0 0000	
	b. Single assembly (Insulation R-value)	12b. R=	30 2440 sq. ft.	-
3.	Air Distribution System: Duct insulation, location	13. R=	sq. ft.	-
	Test report (attach if required)	14a. Type:	21/20/	
1.	Cooling system	14b. SEER/E		
	(Types: central, room unit, package terminal A.C., gas, none)		ty: 5 Tox	
i.	Heating system:	15a. Type:		× 7
-	Types: heat pump, elec. strip, nat. gas, L.P. gas, gas h.p., room or F	PTAC, none) 15b. HSPF/C		
		15c. Capaci		
. 1	Hot water system:	16a. Type:		
	Types: elec., nat. gas, L.P. gas, solar, heat rec., ded. heat pump, o	ther, none) 16b. EF:	-1CE11/4/	
	Paris, Pa	TOD. EF.		

I hereby certify that this building, as designed, is in compliance with the Florida Energy Code.

OWNER AGENT: DATE:

DAT

13.195

White Rosidera


			800	ZER
#	QTY	ange to pass		
1.)	(2) 90° co	ORNERS (BUH GLA	zep) = 30"	; "
3.)	(2) 36" x (1) 84 "	80" STORE FROM	PENTAGON 1	**************************************
4.)	(2) 90° C	BO" TAIL) 48" 6C"	
5.) (1) 84 " x 8	80" STORE FRON	T .	
6.) (2) 96" x	108" STORE FROM	THIS MUST of	3E Spiri
7.) (2	90° COR	NERS (Butt glAZE)	9) 48"	
8) () 89" x /	08" STORE FRON	THIS MUST Split i	BE into Zpcs.
9.) (2) 60" X 48	" STORE FRONT T I-RIGHT		


2 · d

386-454-0395

Chris Whitfield

May 26 05 07:24a





388-424-0388

6 · d

Chris Whitfield

645:70 30 3≥ cbi

NOTICE OF COMMENCEMENT FORM COLUMBIA COUNTY, FLORIDA

Description of property: (legal description of the property and streat address or \$11 address) 7018 SN SC 47 Lace and Street 10:33 Inst: 2005016124 Date: 07/08/2005 Time: 10:33 DC, P. DeWitt Cason, Columbia County B: Description of improvement: Single Family Duelling Country B: Description of improvement: Single Family Duelling Description of Improvement: Single Pamily Duelling Description of Improvement: One Single Pamily Duelling Description o	ime:10:33 pmbia County B:1051 P:653 (386)-719-7/43
Inst: 2005016124 Date: 07/08/2005 Time: 10:33 July DC, P. Dewitt Cason, Columbia County B: Demoral description of improvement: Single Family Duelling Downer Name & Address Ed and Diane White P.O. 60x 28439 Attanta GA 30558 Interest in Property Name & Address of Fee Simple Owner (if other than owner): Contractor Name Isaac Construction Isa. Phone Number 380-715 Address 144 SW Waterford Ct. Lake City Fl. 32025 Surety Holders Name N/A Phone Number Address Amount of Bond N/A Lender Name N/A Phone Number Phone Number Address Persons within the State of Florida designated by the Owner upon whom notices or other documents are provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/A Phone Number Address In addition to himself/herself the owner designates N/A to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	ime:10:33 Imbia County B:1051 P:653 (386)-719-7143
Seneral description of improvement: Single Family Duetling Downer Name & Address Ed and Diane White P.O. & 28639 Attanto GA 30358 Interest in Property Name & Address of Fee Simple Owner (if other than owner): Contractor Name Tsaac Construction Tae. Phone Number (386)-715 Address 144 SW Waterford Ct. Lake City Fl. 32025 Surety Holders Name N/A Phone Number Address Amount of Bond N/A Lender Name N/A Phone Number Address Persons within the State of Florida designated by the Owner upon whom notices or other documents as provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/A Phone Number Address In addition to himself/herself the owner designates N/A to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	(386)-719-7/43
Owner Name & Address Ed and Diane White P.O. Sox 28429 Atlanta GA 30358 Interest in Property Name & Address of Fee Simple Owner (if other than owner): Contractor Name TSAAC Construction Jac. Phone Number (384)—714 Address 144 SN Waterford Ct. Lake City FI. 32025 Surety Holders Name N/A Phone Number Address Amount of Bond N/A Lender Name N/A Phone Number Address Persons within the State of Florida designated by the Owner upon whom notices or other documents as provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/A Phone Number Address In addition to himself/herself the owner designates N/A to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	(386)-719-7143 S
Dwner Name & Address Ed and Diane White P.O. Box 28439 Attauta GA 30358 Interest in Property Name & Address of Fee Simple Owner (if other than owner): Contractor Name Tsaac Construction Tsc. Phone Number (384)-714 Address 144 SW Waterford Ct. Lake City Fl. 32025 Surety Holders Name N/R Phone Number Address Amount of Bond N/R Lendér Name N/R Persons within the State of Florida designated by the Owner upon whom notices or other documents are provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/R Address In addition to himself/herself the owner designates N/R to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	(386)-719-7143 S
Dwner Name & Address Ed and Diane White P.O. Box 28439 Attauta GA 30358 Interest in Property Name & Address of Fee Simple Owner (if other than owner): Contractor Name Tsaac Construction Tsc. Phone Number (384)-714 Address 144 SW Waterford Ct. Lake City Fl. 32025 Surety Holders Name N/R Phone Number Address Amount of Bond N/R Lendér Name N/R Persons within the State of Florida designated by the Owner upon whom notices or other documents are provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/R Address In addition to himself/herself the owner designates N/R to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	(386)-719-7143 S
Name & Address of Fee Simple Owner (if other than owner): Contractor Name	(386)-719-7143 S
Interest in Property Jame & Address of Fee Simple Owner (if other than owner): Contractor Name	(386)-719-7143 S
Contractor Name	(386)-719-7143 S
Address 144 SW Waterford Ct. Lake City Fl. 32025 Surety Holders Name N/A Phone Number Address Amount of Bond N/A Lender Name N/A Phone Number Address Persons within the State of Florida designated by the Owner upon whom notices or other documents as provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/A Phone Number Address In addition to himself/herself the owner designates N/A to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	<u>\$</u>
Address 144 SW Waterford Ct. Lake City Fl. 32025 Surety Holders Name N/A Phone Number Address Amount of Bond N/A Lender Name N/A Phone Number Address Persons within the State of Florida designated by the Owner upon whom notices or other documents as provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/A Phone Number Address In addition to himself/herself the owner designates N/A to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	<u>S</u>
Address Amount of Bond N/A Lender Name N/A Phone Number Phone Number Phone Number Address Persons within the State of Florida designated by the Owner upon whom notices or other documents as provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/A Phone Number Phone Number Address In addition to himself/herself the owner designates to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
Amount of Bond N/A Phone Number Lender Name N/A Phone Number Address Persons within the State of Florida designated by the Owner upon whom notices or other documents as provided by section 718.13 (1)(a) 7; Florida Statutes: Name N/A Phone Number Address In addition to himself/herself the owner designates N/A to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
Persons within the State of Florida designated by the Owner upon whom notices or other documents yed as provided by section 718.13 (1)(a) 7; Florida Statutes: Name NA Phone Number In addition to himself/herself the owner designates NA to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
Persons within the State of Florida designated by the Owner upon whom notices or other documents yed as provided by section 718.13 (1)(a) 7; Florida Statutes: Name NA Phone Number In addition to himself/herself the owner designates NA to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
Persons within the State of Florida designated by the Owner upon whom notices or other documents yed as provided by section 718.13 (1)(a) 7; Florida Statutes: Name NA Phone Number In addition to himself/herself the owner designates NA to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
Persons within the State of Florida designated by the Owner upon whom notices or other documents yed as provided by section 718.13 (1)(a) 7; Florida Statutes: Name NA Phone Number In addition to himself/herself the owner designates NA to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
to receive a copy of the Lienor's Notice as provided in Section (a) 7. Phone Number of the designee Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
(a) 7. Phone Number of the designee	ied in Section 713.13 (1)
Expiration date of the Notice of Commencement (the expiration date is 1 (one) year from the date of	
10 No. 10	om the date of recording
(Unless a different date is specified)	

TICE AS PER CHAPTER 713. Florida Statutes:	elan in hie/her stead.
owner must sign the notice of commencement and no one else may be permitted to sign in his/her	
Sworn to (or affirmed) and subscrib	
Signature of Owner Barbara C. Webster NOTARY STAMP/SEAL Signature of Owner DD329279 Signature of Owner DD329279	and subscribed before, 2000
Cor Pub Bended Troy Pain - Insurgence, Inc. 800-466-7019	and subscribed before, 2000
Sarvaral Webs	and subscribed before, 2000
	and subscribed before
Signature of Notary	and subscribed before 2000

ISAAC Construction Inc.

Remodel & Addition of a single family dwelling Property owner Edward & Diane White

Application for building permit # 0506-88 date file 6/28/05

July 21, 2005 a meeting at the Columbia County Building Department with

Robert Taylor (Associated Florida Architects Inc). Edward White (Property
owner) Isaac Bratkovich (ISAAC Construction Inc.) Joe Haltiwanger

(Columbia County Building Department Plan Examiner) to review structural
plans as presented with application for permit number 0506-88.

July 22, 2005 Robert Taylor (Associated Florida Architects Inc) submits a letter of discovery, filed with application for permit number 0506-88.

July 22, 2005 Addendum Number One submitted from: Robert Taylor (Associated Florida Architects Inc) to application for permit number 0506-88.

July 25, 2005 Columbia County Building Department issues building permit to ISAAC Construction Inc. Permit number 23411

August 09, 2005 Temporary power service inspection by Randy Jones (Assistant Building Official) Passed inspection.

August 15, 2005 Rough plumbing inspection by Randy Jones (Assistant Building Official) Passed inspection

September 06, 2005 Foundation inspection (Monolithic Slab) for addition by Randy Jones (Assistant Building Official) Passed inspection.

September 06, 2005 Zoning land use setback inspection by Randy Jones (Assistant Building Official) Passed inspection.

December 13, 2005 Inspection of dwelling requested by owner Edward

White, whom was present with Personal from Columbia County Building

Department, Randy Jones Assistant Building Official, Harry Dicks Building

Inspector and Joe Haltiwanger Plans Examiner. Performed inspection and
photographed construction site.

December 15, 2005 a letter from the Columbia County Building Department was given to Mr. White and ISAAC Construction Inc. This letter included photographs and structural deficiency found on the date of the inspection.

This letter also required a structural evaluation be preformed by a professional architect or engineer before continuing work on the dwelling.

July 25, 2006 building permit number 23411expries, no request by ISAAC Construction Inc. was made for an extension of the building permit.

July 28, 2006 the Columbia County Building Department received a hand delivered letter from Edward White to John Kerce Columbia County Building Official. This letter informed the building department that a professional engineer had made an inspection of the dwelling. This letter also requested that additional inspections be preformed by the Columbia County Building Department to take action of permit violations.

August 21, 2006 Letter from Edward White to John Kerce Columbia County
Building Official was forwarded to Columbia County Attorney Marlin
Feagle.

August 24, 2006 a letter from Columbia County Attorney Marlin Feagle to
Columbia County plans examiner Joe Haltiwanger was received.

This letter informed Mr. White the process to renew the expired permit and the method to file a compliant with the Florida Department of Business and Professional Regulations due the contractor Isaac Bratkovich CBC059323

(ISAAC Construction Inc.) is licensed and regulate by the Florida

Department of Business and Professional Regulations.

August 29, 2006 the Columbia County Attorney Marlin Feagle and Columbia County Building Department personal Randy Jones Assistant Building Official, Harry Dicks Building Inspector and Joe Haltiwanger Plans Examiner met with Mr. Edward White at the Columbia County Building Department office. A letter from William Freeman P.E. (Freeman Design Group Inc.) was presented, which detailed a structural inspection preformed by Mr. Freeman. This letter presented methods to correct structural problems and was placed into Mr. White file.

Columbia County Attorney Marlin Feagle presented to Mr. White methods to resolve the financial aspect of his request to the Columbia County Building Department. Mr. Feagle explained that Columbia County Building Department did not license or regulate Mr. Robert Taylor or Mr. Isaac Bratkovich, but the building department would contact the Florida Department of Business and Professional Regulations and assist this department after a formal complaint was filed by Mr. White with the Florida Department of Business and Professional Regulations.

August 30, 2006 Harry Dicks Building Inspector with the Columbia County
Building Department spoke by phone to Mr. Jim Patton field investigator
with the Florida Department of Business and Professional Regulations. Mr.
Dicks discussed the request from Mr. White to the Columbia County
Building Department. Mr. Patton advised Mr. Dicks that he would contact
Mr. White and assist him in making any formal complaints to his
department.

August 30, 2006 Mr. Jim Patton field investigator with the Florida

Department of Business and Professional Regulations contacted Mr. Harry

Dicks Columbia County Building Inspector by phone and advised that after

contacting Mr. White by phone Mr. White at this date wish not to make any

formal complaint to the Florida Department of Business and Professional

Regulations on either Mr. Isaac Bratkovich or Mr. Robert Taylor.

Alpine Engineered Products, Inc.

1950 Marley Drive Haines City, FL 33844 Florida Engineering Certificate of Authorization Number: 567 Florida Certificate of Product Approval # FL1999
Page 1 of 1 Document ID:1SNC487-Z0125081043

Truss Fabricator: Anderson Truss Company
Job Identification: 5-214-ISAAC CONST/ED & DIANE WHITE - ROOF
Truss Count: 13
Model Code: Florida Building Code 2001
Truss Criteria: ANSI/TPI-1995
Engineering Software: Alpine Software, Version 7.04.

Structural Engineer of Record:

Address:

Minimum Design Loads: Roof - 40.0 PSF @ 1.25 Duration

Floor - N/A Wind - 110 MPH ASCE 7-98 -Closed

Notes:

Determination as to the suitability of these truss components for the structure is the responsibility of the building designer/engineer of record, as defined in ANSI/TPI 1-1995 Section 2.2

2. The drawing date shown on this index sheet must match the date shown on the individual truss component drawing.


3. As shown on attached drawings; the drawing number is preceded by: HCUSR487


Details: BRCLBSUB-A11015EC-GBLLETIN

#	Ref Description	Drawing#	Date
1	66515A	05144001	05/24/05
2	66516AS	05144002	05/24/05
3	66517AGE	05144003	05/24/05
4	66518B	05144004	05/24/05
5	66519BS	05144005	05/24/05
6	66520BGE	05144006	05/24/05
7	66521C	05144007	05/24/05
8	66522CGE	05144013	05/24/05
9	66523M	05144008	05/24/05
10	66524MGE	05144009	05/24/05
11	66525 ASGE	05144010	05/24/05
12	66526T	05144011	05/24/05
13	66527 TGE	05144012	05/24/05

-Truss Design Engineer-Arthur R. Fisher Florida License Number: 59687 1950 Marley Drive Haines City, FL 33844








WARNING: Furnish a copy of this DWG to the installation contractor. Special care must be taken during handling, shipping and installation of trusses. See "WARNING" note below. 110 mph wind, 12.91 ft mean hgt, ASCE 7-98, CLOSED bldg, Located anywhere in roof, CAT II, EXP B, wind TC DL-5.0 psf, wind BC DL-5.0 psf. (A) Continuous lateral bracing equally spaced on member. Deflection meets L/360 live and L/240 total load (Y Top chord 2x4 SP #2 Dense Bot chord 2x4 SP #2 Dense Webs 2x4 SP #3 :W6, W16 2x4 SP #2 Dense: (5-214-ISAAC CONST/ED & DIANE WHITE - ROOF


(**) Plate relocated as shown.



PLT TYP. Wave TPI

SPACING

201



DRW HCUSR487 05144004 201 REF R487-- 66518 Scale =.1875"/Ft. 05/24/05 1SNC487 17168 HC-ENG JB/AF 0-0-6 110 mph wind, 12.08 ft mean hgt, ASCE 7-98, CLOSED bldg, Located anywhere in roof, CAT II, EXP B, wind TC DL-5.0 psf, wind BC DL-5.0 psf. JREF -SEON-DATE 10.0 PSF 0.0 PSF 40.0 PSF 20.0 PSF 10.0 PSF 24.0" FL/-/3/-/-/R/-1.25 0-0-1 DUR. FAC SPACING T01.LD. STC DL BC LL 10 08 S 3 X 9≡ 1.5X4# <3-4-4× R=1397 U=249 W=4" W. SIONAL ENGL 5X8(**)≡ WAR R. FICO. 4 X 4≡ May 25 '05 3 X 5 ≡ 18-4-4 5 X 4≡ 3 X 4 ≡ **IMPORTANT** FERRISH A COPY OF THIS DESIGN TO THE INSTALLATION COMPACTOR.

PRODUCTS. THE SHALL NOT BE RESPONSIBLE FOR ANY DEVIATION FROM THIS DESIGN.

PRODUCTS. THE SHALL NOT BE RESPONSIBLE FOR ANY DEVIATION FROM THIS DESIGN.

PRODUCT OF CONTROL WITH THE PROPERTY OF A CHARLEST AND THE PARTY OF THE PROPERTY OF THE PR **MARNING** TRUSSES REGULDE EXTREME CARE IN FARRICATION, INADILIGA, SHIPPING, INSTALLING AND BRACING.
REFER TO RESELY—OR GUILDING COMPONENT SAKETY INFORMATION), PUBLISHED BY TOT (TRUSS PATE INSTITUTE, 583
POWDER OR BOSIL - OR GUILDING COMPONENT SAKETY INFORMATION), PUBLISHED BY TOT (TRUSS PATE INSTITUTE, 583
HONDSON, IN 53719) FOR SAFETY PRACITICE PRIOR TO PERFORMED INSES CONTENTION OF THE SAFETY PRACITICES PRIOR TO PERFORMED THE CHORD SHALL HAVE A PROPERLY ATTACHED REGION CHORD SHALL HAVE A PROPERLY ATTACHED. 36-8-8 Over 2 Supports Design Crit: TPI-1995(STD)/FBC 3 X 5≡ 3X7= 5 X 5≡ 3 X 4 ≡ 5 X 4≡ Deflection meets L/360 live and L/240 total load. 18-4-4 - 8) R=1397 U=249 W=4" 3 X 5 ≡ (5-214-ISAAC CONST/ED & DIANE WHITE - ROOF 5X8 (**) ≡ (**) Plate relocated as shown. 4 X 4 ≥ <3-4-4> Alpine Engineered Products, 1 Top chord 2x4 SP #2 Dense Bot chord 2x4 SP #2 Dense Webs 2x4 SP #3 PLT TYP. Wave TPI 1.5X4 W 3X4 W 3X9= ALPINE 0-0-1

Dense Dense


##5

Top chord 2x4 SP # Bot chord 2x4 SP # Webs 2x4 SP #

LUMBER LOADS

SPECIAL

From From From



MARNING PRUSSES REQUIRE EXTREME CARE IN FARRICATION, MARNING, SHIPPING, INTEXALLING AND BRACING, BEFERE TO BESSES, SHIPPING, INTEXALLING AND BRACING, BESSES, 10 SHIPPING, SING BESSES, 10 SHIPPING, SAITE MISTERINE, SSS P. MODERO, DE., SHITE 200, MADISON, HI SZYJS) AND WICK, GOOD TRUSS COUNCED OF AMERICA, GOOD ENTERPRISE IN, MADISON, HI SZYJS) TO SAFETY PRACITICES PRIOR TO PERFORMING THESE FUNCTIONS. UNHESS OTHERWISE INCICATED PRIOR CHARGES AND BOTTOM CHORD SHALL HAVE PROPERLY ATTACHED. Design Crit: TPI-1995(STD)/FBC Note: All Plates Are 1.5X4 Except As Shown Alpine Engineered Products, 1950 Marley Drive Hoime City Ft. 33844 PLT TYP. Wave TPI ALPINE

!HPORTANT TERRISH A COPY OF THIS DESIGN TO THE INSTALLATION CONTRACTOR. ANY TALLOR TO BRITCH THE PROPRETRY DEPONDED. THE SHALL NOT BE RESPONSIBLE FOR ANY DEFIALDING SEDIGIC. ANY TALLOR TO BRICKING THE PROPRISED TO BE STORE THE STALL THE STALL THE STALLENG AND THE TO BRICKE THE STALL SHALL THE STALL THE STALL SHALL SHALL

DRW HCUSR487 05144013

HC-ENG JB/AF

JREF - 1SNC487_Z01

24.0"

1.25

DUR. FAC. SPACING

SONAL ENGL

May 25 '05

17222

SEON-

40.0 PSF 0.0 PSF

TOT.LD.

BC LL BC DL

R487-- 66522

20.0 PSF 10.0 PSF 10.0 PSF

FL/-/3/-/-/R/-

Scale =.25"/Ft.

05/24/05

DATE REF

TC DI

DRW HCUSR487 05144007 201 REF R487 -- 66521 05/24/05 Scale =.25"/Ft. 17206 1SNC487 HC-ENG JB/AF 110 mph wind, 11.41 ft mean hgt, ASCE 7-98, CLOSED bldg, Located anywhere in roof, CAT II, EXP B, wind TC DL-5.0 psf, wind BC DL-5.0 psf. 0-0-6 JREF -SEON-DATE 20.0 PSF 10.0 PSF 0.0 PSF 40.0 PSF 10.0 PSF 24.0" FL/-/3/-/-/R/-1.25 0-0-1 DUR.FAC. SPACING TOT.LD. TC LL BC DL BC LL TC DL 1.5X4# SSIONAL ENGINEER 3 X 9≡ K-3-4-4-> May 25 "US TAUR R. Flore R=970 U=180 W=4" 5X8(**)≡ PETER TO BUSINES REQUIRE EXTREME CAME IN FABRICATION, INABLING, SHIPPING, INSTALLING AND BEACING. COPROMENT SAKETY INFORMATION), PUBLISHED BY TPI (TRUSS PLAKE INSTITUTE, SSS) CONTROL OF AUXILIA SAME TO BE., SUITE ZOO, MADISON, HI 53719, AND HIGKS, HONGING, HI 153719, TOR SAKETY PRACTICES PRIOR TO PERFORMENT HERSE CONTROL OF MEREAUSE INDICATED TOR SAKETY PRACTICES PRIOR TO PERFORMENT HERSE UNCITONS. UNLESS DIMERALS HADCHED CHORD SHALL HAVE A PROPERLY ATTACHED CHORD CALLING. **IMPORTANT** FURNISH A COPY OF THIS BESIGN TO THE INSTALLATION CONTRACTOR.

ALF THE ENGINEERED

PRODUCTS, INC.
SHALL HOT BE RESPONSIBLE FOR ANY DEVIATION FROM HIS DESIGN:
FINISH OF CONCOMMENT HIS PUT.

OB FABLE TAILED

OF FABLE TO BOILD

OF FABLE TO BOILD

TO BOILD

APPLY

CONNECTOR PLATES OF THIS ARE ANY OF 2018/166A. (M. 1872)S ASIA BASE AND BOILD

PLATES TO CACH FACE OF THIS ASIA.


ANY HIS PECTION OF PLATES FOLLOWED BY (1) SHALL BE PER ANNEX AS OF PLY-2008 SEC.)


A ASIA OF THIS BOILD AND A CACCHARGE OF PROFESSIONAL ENGINEER HIS DESIGN, FOR THE REARINGS 160A-Z.


BOALING TO SOLICE THE BASE AND A CONTRACTOR OF THIS DESIGN.


THE SULLABILITY AND USE OF PROFESSIONAL ENGINEER HIS DESIGNS[BILLITY SOLELY FOR THE RESPONSIBILITY OF THE

BRILLOING DESIGNEE PER ANSI/TPI I SEC. 2. -26-0-8 Over 2 Supports Design Crit: TPI-1995(STD)/FBC 4 X 4≡ Note: All Plates Are 3X4 Except As Shown. Deflection meets L/360 live and L/240 total load R=970 U=180 W=4" () 13-0-4 (5-214-ISAAC CONST/ED & DIANE WHITE - ROOF 2X8 (**) ≡ K-3-4-4-(**) Plate relocated as shown. Alpine Engineered Products, Inc. 1950 Marley Drive Haines City, FL 33844 Top chord 2x4 SP #2 Dense Bot chord 2x4 SP #2 Dense Webs 2x4 SP #3 1.5X4 W PLT TYP. Wave TPI 3X9≡ ALPINE 0-0-1









TO CONVERT FROM "L" TO "T" REINFORCING MEMBERS, MULTIPLY "T" FACTOR BY LENGTH (BASED ON GABLE VERTICAL SPECIES, GRADE AND SPACING) FOR (1) 2X4 "L" BRACE, GROUP A, OBTAINED FROM THE APPROPRIATE ALPINE GABLE DETAIL FOR ASCE OR MAXIMUM ALLOWABLE "T" REINFORCED GABLE VERTICAL LENGTH IS 14" FROM TOP TO BOTTOM CHORD.

"T" BRACE WEB LENGTH INCREASE W/

20 % 0 0 % 0 0 % 0 0 0 % 0 0 0 % 0 0 0 0	AND MRH	110 MPH	15 FT	110 MPH	30 FT	100 MPH	15 FT	100 MPH	30 FT	HdW 06	15 FT	90 MPH	30 FT	80 MPH	15 FT	80 MPH	30 FT	70 MPH	15 FT	70 MPH	30 FT
ASK 10 10 10 10 10 10 10 10 10 10 10 10 10	MBR. SIZE	2x4	2x6	2x4	2x6	2x4	2x6	2x4	2x6	2x4	2x6	2x4	2x6	2x4	2x6	2x4	2x6	2x4	2x6	2x4	2x6
ASCE 10 10 10 10 10 10 10 10 10 10 10 10 10	SBCCI	10 %	40 %	10 %	20 %	% 01	30 %	% 01	40 %	20 %	20 %	10 %	30 %	10 %	25 01	20 %	20 %	% 0	% 0		10 %
	ASCE	201	20 %	10 %									50 %	20 %	30 %				20 %	20 %	30 %

ASCE WIND SPEED = 100 MPH

MEAN ROOF HEIGHT = 30 FT GABLE VERTICAL = 24" O.C. SP #3 "T" REINFORCING MEMBER SIZE = 2X4

"T" BRACE INCREASE (FROM ABOVE) = 10% = 1.10 (I) 2X4 "L" BRACE LENGTH = 6" 7" MAXIMUM "T" REINFORCED GABLE VERTICAL LENGTH

 $1.10 \times 6' 7" = 7'$

DRWG GBLLETIN1103 REF LET-IN VERT DATE 01/16/04 -ENG DLJ/KAR MAX TOT. LD. 60 PSF

ANY DUR. FAC.


INPORTANT FURNISH CORY OF THIS DESIGN TO INSTALLATION CONTRACTOR: ALPHE ENGINEERED PRODUCTS, INC. SHALL NOT BE RESPONSIBLE FOR AWY DEVAINING SHEW HATS BESIGN ANY FAILURE TO BUILD THE FURSE. IN CONTRACTOR OF THE FACTOR OF THE SHEW AND THE SHEW AS THE SHEW AND THE SHEW SHEW THE SHEW AND THE SHEW SHEW THE SHEW

ALPINE ENGINEERED PRODUCTS, INC.

ALPINE

POMPANO BEACH, FLORIDA

24.0" MAX SPACING



CLB WEB BRACE SUBSTITUTION

THIS DETAIL IS TO BE USED WHEN CONTINUOUS LATERAL BRACING (CLB) IS SPECIFIED ON AN ALPINE TRUSS DESIGN BUT AN ALTERNATIVE WEB BRACING METHOD IS DESIRED.

NOTES:

THIS DETAIL IS ONLY APPLICABLE FOR CHANGING THE SPECIFIED CLB SHOWN ON SINGLE PLY SEALED DESIGNS TO T-BRACING OR SCAB BRACING.

FOR MINIMUM ALTERNATIVE BRACING, RE-RUN DESIGN WITH APPROPRIATE ALTERNATIVE BRACING SPECIFIED IN CHART BELOW MAY BE CONSERVATIVE.

EB	WEB MEMBER SIZE	SPECIFIED CLB BRACING	ALTERNATIVE BRACING T OR L-BRACE SCAB BRACE	TE BRACING SCAB BRACE
2X3	OR 2X4	1 ROW	2X4	1-2X4
	OR 2X4	2 ROWS	2X6	2-2X4
	2X6	1 ROW	2X4	1-2X6
	2X6	2 ROWS	2X6	2-2X4(*)
	2X8	1 ROW	2X6	1-2X8
	2X8	2 ROWS	2X6	2-2X6(*)


T-BRACE, L-BRACE AND SCAB BRACE TO BE SAME SPECIES AND GRADE OR BETTER THAN WEB MEMBER UNLESS SPECIFIED OTHERWISE ON ENGINEER'S SEALED DESIGN.

APPLY (1) SCAB TO EACH CENTER SCAB ON WIDE FACE OF WEB.

L-BRACE I-BRACE OR L-BRACE T-BRACE ATTACH WITH 16d NAILS AT 6" O.C. BRACE IS A MINIMUM 80% OF WEB APPLY TO EITHER SIDE OF WEB NARROW FACE MEMBER LENGTH T-BRACING OR L-BRACING:

SCAB BRACING:

NAILS AT 6" O.C. BRACE IS A MINIMUM APPLY SCAB(S) TO WIDE FACE OF WEB. NO MORE THAN (1) SCAB PER FACE. ATTACH WITH 10d OR .128"x3" GUN 80% OF WEB MEMBER LENGTH



TC LL TC DL BC DL

ALPINE

TPI ALTER APPLY FEEL A ALPINE ENGINEERED PRODUCTS, INC. POMPANO BEACH, FLORIDA


PSF DRWG BRCLBSUB1103 -ENG MLH/KAR PSF PSF DUR. FAC SPACING TOT. LD BC LL


THIS DRAWING REPLACES DRAWING 579,640

CLB SUBST

PSF REF

PSF DATE 11/26/03





DRW HCUSR487 05144011 R487-- 66526 Scale =.1875"/Ft 05/24/05 17297 JB/AF psf. 110 mph wind, 22.81 ft mean hgt, ASCE 7-98, CLOSED bldg, Located anywhere in roof, CAT II, EXP B, wind TC DL=5.0 psf, wind BC DL=5.0 HC-ENG SEON-DATE REF \$ 20-0-0 22-0-6 20.0 PSF 10.0 PSF 40.0 PSF 10.0 PSF 0.0 PSF FL/-/3/-/-/R/-1.25 R=582 U=183 W=5.25" DUR.FAC. TOT.LD \exists 7 10 0-0-1 35. 37.00 38 BC BC Shim all supports to solid bearing. ASSIONAL ENGINE 1.5X4 // L<3-4-4> TE OF 696910 R=696 U=180 W=5.25" **MARNING** TRUSSES REQUIRE EXTREME CARE IN FABRICATION, INABOLING, SHIPPING, INSTALLING AND BRACING, REFER ID OSS.1 1-30 BUDLIANG COMPONENT SAFETY INFORMATION, POBLISHED (NESS PLAIR INSTITUTE, 583 D'ONDOPELO DE., SUITE ZOO, MADISON, HI SATZIO) AND WICA, (MOOD TRUSS COUNCLL OF AMERICA, 6300 ENTERPRISE IN. HADISON, MI SATZIO) FOR SAFETY PRACILCES PRIOR TO PERFORMENT INESS CONCENTORS. UNLESS OTHERNISE INDICATED. TOP CHORD SHALL MAVE PROPERLY ATTACHED AND BUTTON CHORD SHALL MAVE A PROPERLY ATTACHED FIGURE CELLING. 18/16GA (N.N/S/K) ASTA ASSA GRADE 40/60 (N. K/N/S) GALY. STEEL. APPLY.
. UNICSS OTBERHSE LOCATED ON THIS DESIGN, POSITION PER DEALHARS 16GA-Z.
D BY (1) SHALL BE PER AMMEX A3 OF IPIL 2002 SEC.3. A SEAL ON THIS PROFESSIONAL WIGHERPING RESPONSIBILITY SOLLY FOR THE TRUSS COMPONENT ALPINE ENGINEERED ALL BE PER ANNEX AS OF 1P11-2002 SEC.3.
AL ENGINEERING RESPONSIBILITY SOLCEY SEPONSIBILITY OF THE DESIGN: ANY FAILURE TO BUILD THE IG. INSTALLING & BRACING OF TRUSSES. EC. BY AFREA) AND TP1. ALPINE Design Crit: TPI-1995(STD)/FBC 32-4-8 Over 4 Supports R-697 U-180 W-5.25" 4X5 (R) III 0 SUITABILITY AND USE OF BLE PROVISIONS Deflection meets L/360 live and L/240 total load. (5-214-ISAAC CONST/ED & DIANE WHITE - ROOF - T) Shown ANY INSPECTION OF PLATES FOLLOWER DRAWING INDICATES ACCEPTANCE OF DESIGNA SHOWN. THE SULTABLILIY PHILITAGE RECEDURE WELL AND A R=582 U=180 W=5.25" 16-2-4 Note: All Plates Are 3X4 Except As **IMPORTANT** FURRISH PRODUCTS, IMC. SHATRUSS IN CONFORMANC DESIGN CONFORMS WIT CONNECTOR PLATES AS #2 Dense #2 Dense #3 €3-4-4> Alpine Engineered Products, Inc. 1950 Marley Drive Haines City Ft. 33844 1.5X4 W 3 X 9 ≡ 252 Wave ALPINE Top chord 2x4 S Bot chord 2x4 S Webs 2x4 S PLT TYP

COLUMBIA COUNTY BUILDING DEPARTMENT

RESIDENTIAL MINIMUM PLAN REQUIREMENTS AND CHECKLIST FOR FLORIDA BUILDING CODE 2001 ONE (1) AND TWO (2) FAMILY DWELLINGS

ALL REQUIREMENTS ARE SUBJECT TO CHANGE EFFECTIVE MARCH 1, 2002


ALL BUILDING PLANS MUST INDICATE THE FOLLOWING ITEMS AND INDICATE COMPLIANCE WITH CHAPTER 1606 OF THE FLORIDA BUILDING CODE 2001 BY PROVIDING CALCULATIONS AND DETAILS THAT HAVE THE SEAL AND SIGNATURE OF A CERTIFIED ARCHITECT OR ENGINEER REGISTERED IN THE STATE OF FLORIDA, OR ALTERNATE METHODOLOGIES, APPROVED BY THE STATE OF FLORIDA BUILDING COMMISSION FOR ONE-AND-TWO FAMILY DWELLINGS. FOR DESIGN PURPOSES THE FOLLOWING BASIC WIND SPEED AS PER FIGURE 1606 SHALL BE USED.

WIND SPEED LINE SHALL BE DEFINED AS FOLLOWS: THE CENTERLINE OF INTERSTATE 75.

- 1. ALL BUILDINGS CONSTRUCTED EAST OF SAID LINE SHALL BE ----- 100 MPH
- 3. NO AREA IN COLUMBIA COUNTY IS IN A WIND BORNE DEBRIS REGION

APPLICANT - PLEASE CHECK ALL APPLICABLE BOXES BEFORE SUBMITTAL

Applicant	Plans Exam	MENTS: Two (2) complete sets of plans containing the following:
	D	All drawings must be clear, concise and drawn to scale ("Optional" details that are not used shall be marked void or crossed off). Square footage of different areas shall be shown on plans.
.E	D	Designers name and signature on document (FBC 104.2.1). If licensed architect or engineer, official seal shall be affixed.
	B	Site Plan including:
		a) Dimensions of lot
		b) Dimensions of building set backs
	1	 Location of all other buildings on lot, well and septic tank if applicable, and all utility easements.
	/ /	d) Provide a full legal description of property.
TI	P	Wind-load Engineering Summary, calculations and any details required
		a) Plans or specifications must state compliance with FBC Section 1606
		b) The following information must be shown as per section 1606.1,7 FBC
	100	a. Basic wind speed (MPH) b. Wind importance factor (I) and building category
		c. Wind exposure – if more than one wind exposure is used, the wind exposure and applicable wind direction shall be indicated
		d. The applicable internal pressure coefficient
		e. Components and Cladding. The design wind pressure in terms of psf (kN/m²), to be used for the design of exterior component and cladding materials not specifally designed by the registered design professional
DY .	B	Elevations including:
विविविविविविव	D/	a) All sides
		b) Roof pitch
	5	
<u>"</u>	D	c) Overhang dimensions and detail with attic ventilation
U	NE CONTRACTOR OF THE PARTY OF T	d) Location, size and height above roof of chimneys
	0	e) Location and size of skylights
10		f) Building height
48-	02	e) Number of stories



Floor Plan including:

- a) Rooms labeled and dimensioned
- b) Shear walls
- c) Windows and doors (including garage doors) showing size, mfg., approval listing and attachment specs. (FBC 1707) and safety glazing where needed (egress windows in bedrooms to be shown)
- d) Fireplaces (gas appliance) (vented or non-vented) or wood burning with
- e) Stairs with dimensions (width, tread and riser) and details of guardrails and handrails
- f) Must show and identify accessibility requirements (accesssable bathroom)
 Foundation Plan including:
- a) Location of all load-bearing wall with required footings indicated as standard Or monolithic and dimensions and reinforcing
- b) All posts and/or column footing including size and reinforcing
- c) Any special support required by soil analysis such as piling
- d) Location of any vertical steel

Roof System:

- a) Truss package including:
 - Truss layout and truss details signed and sealed by Fl. Pro. Eng.
 - Roof assembly (FBC 104.2.1 Roofing system, materials, manufacturer, fastening requirements and product evaluation with wind resistance rating)
- b) Conventional Framing Layout including:
 - 1. Rafter size, species and spacing
 - 2. Attachment to wall and uplift
 - 3. Ridge beam sized and valley framing and support details
 - Roof assembly (FBC 104.2.1 Roofing systems, materials, manufacturer, fastening requirements and product evaluation with wind resistance rating)

Wall Sections including:

- a) Masonry wall
 - 1. All materials making up wall
 - 2. Block size and mortar type with size and spacing of reinforcement
 - 3. Lintel, tie-beam sizes and reinforcement
 - Gable ends with rake beams showing reinforcement or gable truss and wall bracing details
 - All required connectors with uplift rating and required number and size of fasteners for continuous tie from roof to foundation
 - Roof assembly shown here or on roof system detail (FBC 104.2.1 Roofing system, materials, manufacturer, fastening requirements and product evaluation with resistance rating)
 - 7. Fire resistant construction (if required)
 - 8. Fireproofing requirements
 - 9. Shoe type of termite treatment (termiticide or alternative method)
 - 10. Slab on grade
 - Vapor retarder (6mil, Polyethylene with joints lapped 6 inches and sealed)
 - Must show control joints, synthetic fiber reinforcement or Welded fire fabric reinforcement and supports
 - 11. Indicate where pressure treated wood will be placed
 - 12. Provide insulation R value for the following:
 - a. Attic space
 - b. Exterior wall cavity
 - c. Crawl space (if applicable)

15561594		
e of the		
x		
~	H	b) Wood frame wall
W.		1. All materials making up wall
		2. Size and species of studs
		3. Sheathing size, type and nailing schedule
61		(4) Headers sized
		5.) Gable end showing balloon framing detail or gable truss and wall
		hinge bracing detail
		6. All required fasteners for continuous tie from roof to foundation
		(truss anchors, straps, anchor bolts and washers)
		7. Roof assembly shown here or on roof system detail (FBC104.2.1
		Roofing system, materials, manufacturer, fastening requirements
		and product evaluation with wind resistance rating)
	, and E. T. Tatalian .	8. Fire resistant construction (if applicable)
		9. Fireproofing requirements
		10. Show type of termite treatment (termiticide or alternative method)
		11. Slab on grade
		a. Vapor retarder (6Mil. Polyethylene with joints lapped 6
		inches and sealed
		b. Must show control joints, synthetic fiber reinforcement or
9		welded wire fabric reinforcement and supports
THE STATE OF		12. Indicate where pressure treated wood will be placed
		13. Provide insulation R value for the following:
40		a. Attic space
, 1800	/	b. Exterior wall cavity
		c. Crawl space (if applicable)
0	ď	c) Metal frame wall and roof (designed, signed and sealed by Florida Prof.
,		Engineer or Architect)
/		Floor Framing System:
6		a) Floor truss package including layout and details, signed and sealed by Florida
		Registered Professional Engineer
A 10 10 10 10 10 10 10 10 10 10 10 10 10		b) Floor joist size and spacing
0		c) Girder size and spacing
D		d) Attachment of joist to girder
6		e) Wind load requirements where applicable
		Plumbing Fixture layout
/	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Electrical layout including:
6/		a) Switches, outlets/receptacles, lighting and all required GFCI outlets identified
व व व व व व व व व व व व व व व व व व व	0	b) Ceiling fans
0	0	c) Smoke detectors
e/	0	d) Service panel and sub-panel size and location(s)
1	0	e) Meter location with type of service entrance (overhead or underground)
10		f) Appliances and HVAC equipment
1		HVAC information
B)	0	a) Manual J sizing equipment or equivalent computation
B)		b) Exhaust fans in bathroom
#		Energy Calculations (dimensions shall match plans)
n	n	Gas System Type (LP or Natural) Location and BTU demand of equipment
		Disclosure Statement for Owner Builders
		Notice Of Commencement
65		Private Potable Water
100		a) Size of pump motor
	16 get	b) Size of pressure tank
		c) Cycle stop valve if used
		No.
	The second	
	a contract of the contract of	



WOOD-EDGE STEEL DOORS

APPROVED DOOR STYLES: 3/4 GLASS:



















CERTIFIED TEST REPORTS:

NCTL 210-1897-7, 8, 9, 10, 11, 12; NCTL 210-1864-5, 6, 7, 8; NCTL 210-2178-1, 2, 3

Certifying Engineer and License Number: Barry D. Portney, P.E. / 16258.

Unit Tested in Accordance with Miami-Dade BCCO PA202.

Evaluation report NCTL-210-2794-1

Door panels constructed from 26-gauge 0.017" thick steel skins. Both stiles constructed from wood. Top end rails constructed of 0.041" steel. Bottom end rails constructed of 0.021" steel. Interior cavity of slab filled with rigid polyurethane foam core. Slab glazed with insulated glass mounted in a rigid plastic lip lite surround.

Frame constructed of wood with an extruded aluminum bumper threshold.

PRODUCT COMPLIANCE LABELING:

TESTED IN ACCORDANCE WITH MIAMI-DADE BCCO PAZO2

COMPANY NAME CITY, STATE


To the best of my knowledge and ability the above side-hinged exterior door unit conforms to the requirements of the 2001 Florida Building Code, Chapter 17 (Structural Tests and Inspections).

State of Florida, Professional Engineer Kurt Balthazor, P.E. - License Number 56533

Johnson EntrySystems


March 25, 2002 Jur conflowing program of product improvement makes specifications, design and product tends subject to change without nation.





WOOD-EDGE STEEL DOORS

APPROVED ARRANGEMENT:



Units of other sizes are covered by this report as long as the panels used do not exceed 3'0" x 6'8".

Double Door

Design Pressure +40.5/-40.5

cial threshold design is used.

Large Missile Impact Resistance

Hurricane protective system (shutters) is REQUIRED.

MINIMUM ASSEMBLY DETAIL:

Compliance requires that minimum assembly details have been followed - see MAD-WL-MA0012-02 and MAD-WL-MA0041-02.

MINIMUM INSTALLATION DETAIL:

Compliance requires that minimum installation details have been followed -- see MID-WL-MA0002-02.

APPROVED DOOR STYLES: 1/4 GLASS:











1/2 GLASS:


















*This glass kit may also be used in the following door styles: 5-panel; 5-panel with scroll; Eyebrow 5-panel; Eyebrow 5-panel with scroll.






OUTSWING UNITS WITH DOUBLE DOOR



March 29, 2002 Our continuing program of product improvement maters specifications design and product detail subject to distince without paties.



DOUBLE DOOR



Latching Hardware:


Compliance requires that GRADE 2 or better (ANSI/BHIMA A156.2) cylinderical and deadlock hardware be installed.

Notes:


- Anchor calculations have been carried out with the lowest (least) fastener rating from the different fasteners being considered for use. Fasteners
 analyzed for this unit include #8 and #10 wood screws or 3/16" Tapcons.
- The wood screw single shear design values come from Table 11.3A of ANSI/AF & PA NDS for southern pine lumber with a side member thickness of 1-1/4" and achievement of minimum embedment. The 3/16" Tapcon single shear design values come from the ITW and ELCO Dade Country approvals respectively, each with minimum 1-1/4" embedment.
- 3. Wood bucks by others, must be anchored properly to transfer loads to the structure.



GLASS INSERT IN DOOR OR SIDELITE PANEL



SECTION A-A Typical rigid plastic Lip Lite Surround



THIS DOCUMENT WAS PREPARED WITHOUT BENEFIT OF TITLE SEARCH.

FOR RECORDER

THIS INSTRUMENT WAS PREPARED BY: Krista L. Waldron, Esquire (PES) Fisher, Tousey, Leas & Ball, P.A. 818 North A1A, Suite 104 Ponte Vedra Beach, Florida 32082 Inst:2003008855 Date:04/29/2003 Time:09:29
OC Stamp-Deed: 0.70
_____DC,P.DeWitt Cason,Columbia County B:981 P:2183

SPECIAL WARRANTY DEED

THIS INDENTURE, made this 20 day of APRIL , 2003, between VIRGINIA H. BISHOP, as Trustee of the Virginia H. Bishop Living Trust, whose address is P. O. Box 1298, Lake City, Florida 32056, party of the first part, and EDWARD C. WHITE, JR. and DIANE B. WHITE, husband and wife, whose address is 80 Cliffcreek Trace, Atlanta, Georgia 30350, parties of the second part.

WITNESSETH:

That the said party of the first part, in consideration of love and affection, has granted, bargained, and convoyed to the said parties of the second part, their heirs, successors and assigns forever, her remaining one-half interest in the following described lands, situate, lying and being in Columbia County, Florida, to wit:

Commence at the Southwest Corner of the Southwest ¼ of Northwest ¼ of Section 2, Township 5 South, Range 16 East and run thence North 0 degrees 49 minutes West along the West line of said Section 2, 658.91 feet for Point of Beginning; thence continue North 0 degrees 49 minutes West along the West line of said Section 2, 500 feet; thence run South 65 degrees 59 minutes 30 seconds East, 1000.05 feet to the Northerly line of State Road No. 47; thence run South 40 degrees 53 minutes West along the West line of State Road No. 47 a distance of 474.23 feet; thence run North 65 degrees 59 minutes 30 seconds West, a distance of 652.5 feet more or less to the Point of Beginning, said land lying in the Southwest ¼ of the Northwest ¼ of Section 2, Township 5 South, Range 16 East, Columbia County, Florida, containing: 10 acres, more or less.

Real Estate Assessment No: 02-5S-16-03443-002

Subject to covenants, restrictions, easements, mortgages and all other encumbrances of record and taxes assessed subsequent to December 31, 2002; provided, however, this reference will not serve to reimpose any such covenants, restrictions or easements.


	Anna Paragraphic Committee and the Committee of the Commi
	hst:2003008855 Date:04/29/2003 Time:09:29
	nc Steen-Deed : 0.70
	DC,P. DeWitt Cason, Columbia County B:981 P:21
ing part 내려 뉴 () 그리고 있는데 하는데 하는데 아니라 아니라 아니라 아니라 그리고 아니라 그리고 있다면 아니라	art does hereby fully warrant the title to said land, and will ns of all persons whomsoever claiming by, through or under otherwise.
IN WITNESS WHEREOF, the and year first above written.	undersigned has hereunto set her hand and seal as of the day
0:110(-1:-0	
Signed and Sealed in Our Presence:	
1	10
Sign: Dais G. Johnson	1 d'1
	- Maine N. Dutop
Print Name: Doris A. Johns	VIRGINIA H. BISHOP, as Trustee of the
*** _ * * * * * * * * * * * * * * * * *	V rginia H. Bishop Living Trust
Sign: Dlene Litters	
Print Name: Shew Little	
41 .	그리는 레르힐 모양 시간에 많아 그들고 꾸고를 잃었다면 하는
STATE OF TLORIDA	
COUNTY OF CoLumbia	
The foregoing instrument was a VIRGINIA H. BISHOP, as Trustee of the who is personally known to me or (as identification.	cknowledged before me this 28 day of Lipki L, 2003, by the Virginia H. Bishop Living Trust, (notary must check one box): (State) driver's license No.
and the seathers of the seathers	
And the Market Commence	Elsine K. Jolan
	Name: Elaine K. TolaR
	NOTARY PUBLIC, State of FLOR: DA
	Commission Number:

VENT-FREE

This unit is A.G.A. certified as a heater with 99% heat efficiency No chimney or flue system required Wide selection of factory installed options offered


VF-4000

- 14,000 25,000 Btu/hr with manual control valve
- 19,500 25,000 Bru/hr with millivolt control valve
- · Fully assembled and ready to install
- · Attractive wood surrounds available
- 15" x 30" fixed or operable screen opening



VF-5000

- 25,000 Btu/hr millivolt variable heat output
- * 15" X 30" glass or screen viewing area
- · Clean burning, safe and easy to install
- Realistic charted oak logs with glowing embers




VF-6000


- · 32,000 Bru/hr millivolt variable heat output
- Beautiful 20" X 34" glass or screen viewing area
- · Will operate during a power failure
- · Designed for large rooms



F4000/5000/6000









SURROUNDS

The Charleston Poplar Surround is hand crafted using a combination of solid Poplar and Poplar veneer. Using the unique wood type of Poplar allows you the option to paint or stain this elegantly detailed surround. The surround is constructed using easy to assemble cam locks, and available in corner and wall units.





Distributed by:



Refractory tan brick panels





Square brass trim kit.



Brass Louver Kit (For YF-4 only)



(For VF-5 & VF6 only)



Arch klt. (For VF-5 & VF6 only)



Glass door kit. (For VF-5 & VF6 only)




Brass hood. (For VF-5 & VF6 only)




Wall switch or optional wireless remote available. (For VF-4MV, VF-5 & VF-6)




Wall thermostat. (For VF-4MV, VF-5 & VF-6) Front View



Left Side View



Top View



Vent-Free Product Dimensions

. 4 8 6	VP-4000/5000C	VF-6000C
Ara		42-1/8"
В	31-1/2"	36-5/8"
会で来	ASSESSMENT OF THE PARTY OF THE	184846 20"
D	30"	34"
		16 40"
P	5-1/2°	5-1/2"
	Land Cont.	Office 1/2" sales
H	3-3/4"	3-3/4"
		Walls 8-1/2"
J	5"	3"
SE AN	0.57	19-1/2"
L	27"	28-1/2"

Btu Chart

Model	Natural	Propane
VF-4000 munual	14,000 - 25,000	14,000 - 25,000
VY-4000/5000 millivolt	19,500 - 25,000	19,500 - 25,000
	25,000 - 32,000	25,000 - 32,000

Framing Dimension

Model	Width	Height	Depth
VF-4000/5000	37"	37-1/4"	15-1/2
VF-6000	41"	42-3/8"	19-1/2

NOTE: Diagrams and illustrations are not to scale. Product designs, materials, dimensions, specifications, colors and prices subject to change or discontinuation without notice. Built to ANSI 221.11.2 standard and approved by A.G.A. (report # 12970017).

Consult your distributor for local fireplace code information.



www.LennoxHearthProducts.com

P/N 904564 HEV F 9/00

Printed in U.S.A. @2001 Lennox Hearth Products • 1110 West Taft Ave., Orange, CA 92865-4150 Lennox Hearth Products Direct Vent heater rated gas appliances include a 20-year limited warrantyDisplaying 1-1 of 1

Org Code: PDM

System ID: 3585

General American

Montgomery:

James Campbell Contact

00016581349

Product Manufacturer 177

01/01/2099 Expire

Approved Status

Phone

She Link: www.gadco.com

Spirit District Spirit Spirit

ORIDA BUILDING COD

User Registration

User Authorization

Organization Aucteditation

inn Search Organization

Select the organization type, status, or name to find an organization

Buildings Wanufact.

Approva Status

(ALL)

Organization General American Deor - Product Meanufacturer Name

4.0

Organization Product Manufacturer Type:

Search

Cancel

Result List for Organizations

Displayang 1-1 of 1

Nature


O.


http://www.floridebuilding.org/Common/c_org_regi_SRCH_esp


6/21/2004


TARA


משתנה נדחונדתי











MIAMI-DADE COUNTY, FLORIDA METRO-DADE FLAGLER BUILDING

BUILDING CODE COMPLIANCE OFFICE METRO-DADE FLAGLER BUILDING 140 WEST FLAGLER STREET, SUITE 1603 -MIAMI, FLORIDA 33130-1363 (305) 375-2901 FAX (305) 375-2908

CONTRACTOR LICENSING SECTION (305) 375-2527 FAX (305) 375-2525

CONTRACTOR ENFORCEMENT DIVISION (305) 375-2966 FAX (305) 375-2968

PRODUCT CONTROL DIVISION (305) 375-2902 FAN (305) 372-6339

PRODUCT CONTROL NOTICE OF ACCEPTANCE

Premdor Entry Systems 911 E. Jeserson, P.O. Box 76 Pittsburgh, KS 66762

Your application for Notice of Acceptance (NOA) of:

Entergy 6-8 S-W/E Inswing Opaque Double w/sidelites Residential Insulated Steel Door under Chapter 8 of the Code of Miami-Dade County governing the use of Alternate Materials and Types of Construction, and completely described herein, has been recommended for acceptance by the Miami-Dade County Building Code Compliance Office (BCCO) under the conditions specified herein.

This NOA shall not be valid after the expiration date stated below. BCCO reserves the right to secure this product or material at any time from a jobsite or manufacturer's plant for quality control testing. If this product or material fails to perform in the approved manner, BCCO may revoke, modify, or suspend the use of such product or material immediately. BCCO reserves the right to revoke this approval, if it is determined by BCCO that this product or material fails to meet the requirements of the South Florida Building Code.

The expense of such testing will be incurred by the manufacturer.

ACCEPTANCE NO.: 01-0314.24 EXPIRES: 04/02/2006

Rauf Kodriguez Chief Product Control Division

THIS IS THE COVERSHEET, SEE ADDITIONAL PAGES FOR SPECIFIC AND GENERAL CONDITIONS BUILDING CODE & PRODUCT REVIEW COMMITTEE

This application for Product Approval has been reviewed by the BCCO and approved by the Building Code and Product Review Committee to be used in Miami-Dade County, Florida under the conditions set forth above.

Francisco J. Quintana, R.A.

Francisco / acintesa


Director

Miami-Dade County

Building Code Compliance Office

APPROVED: 06/05/2001

Internet mail addresses made



PRODUCT CONTROL NOTICE OF ACCEPTANCE

Premdor Entry Systems 911 E. Jeferson, P.O. Box 76 Pittsburgh ,KS 66762

BUILDING CODE COMPLIANCE OFFICE

METRO-DADE FLAGLER BUILDING 140 WEST FLAGLER STREET, SUITE 1603 MIAMI, FLORIDA 33130-1563 (305) 375-2901 FAX (305) 375-2908

> CONTRACTOR LICENSING SECTION (305) 375-2527 FAX (305) 375-2558

CONTRACTOR ENFORCEMENT DIVISION (305) 375-2966 FAN (305) 375-2908

> PRODUCT CONTROL DIVISION (305) 375-2902 FAX (305) 372-6339

Your application for Notice of Acceptance (NOA) of:

Entergy 6-8 S-W/E Inswing Opaque Single w/sidelites Residential Insulated Steel Door under Chapter 8 of the Code of Miami-Dade County governing the use of Alternate Materials and Types of Construction, and completely described herein, has been recommended for acceptance by the Miami-Dade County Building Code Compliance Office (BCCO) under the conditions specified herein.

This NOA shall not be valid after the expiration date stated below. BCCO reserves the right to secure this product or material at any time from a jobsite or manufacturer's plant for quality control testing. If this product or material fails to perform in the approved manner, BCCO may revoke, modify, or suspend the use of such product or material immediately. BCCO reserves the right to revoke this approval, if it is determined by BCCO that this product or material fails to meet the requirements of the South Florida Building Code.

The expense of such testing will be incurred by the manufacturer.

ACCEPTANCE NO.: 01-0314.18 EXPIRES: 04/02/2006

Raul Kodriguez

Chief Product Control Division

21/16/20

THIS IS THE COVERSHEET, SEE ADDITIONAL PAGES FOR SPECIFIC AND GENERAL CONDITIONS BUILDING CODE & PRODUCT REVIEW COMMITTEE

This application for Product Approval has been reviewed by the BCCO and approved by the Building Code and Product Review Committee to be used in Miami-Dade County, Florida under the conditions set forth above.

Francisco J. Quintana, R.A.

Manares / auntesa

Director

Miami-Dade County

Building Code Compliance Office

APPROVED: 06/05/2001



AAMA/NWWDA 101/LS.2-97 TEST REPORT SUMMARY

Rendered to:

MI HOME PRODUCTS, INC.

SERIES/MODEL: 650
TYPE: Aluminum Picture Window

Title of Test	Results
Rating	F-R45 60 x 80
Overall Design Pressure	+45.0 psf -47.2 psf
Air Infiltration	0.04 cfm/ft ²
Water Resistance	8.25 psf
Structural Test Pressure	+67.5 psf -70.8 psf
Forced Entry Resistance	Grade 10

Reference should be made to Report No. 01-41135.01 dated 03/26/02 for complete test specimen description and data.

For ARCHITECTURAL TESTING, INC.

Mark A. Hess, Technician

MAH:nlb

allen M. Remai



AAMA/NWWDA 101/LS.2-97 TEST REPORT

Rendered to.

MI HOME PRODUCTS, INC. 650 West Market Street P.O. Box 370 Gratz, Pennsylvania 17030-0370

Report No: 01-41135.01

Test Date:

03/07/02 03/26/02

Report Date:

Expiration Date:

03/07/06

Project Summary: Architectural Testing, Inc. (ATI) was contracted by MI Home Products, Inc. to perform tests on Series/Model 650, aluminum picture window at their facility located in Elizabethville, Pennsylvania. The samples tested successfully met the performance requirements for a F-R45 60 x 80 rating.

Test Specification: The test specimen was evaluated in accordance with AAMA/NWWDA 101/LS.2-97, Voluntary Specifications for Aluminum, Vinyl (PVC) and Wood Windows and Glass Doors.

Test Specimen Description

Series/Model: 650

Type: Aluminum Picture Window

Overall Size: 5' 0" wide by 6' 8" high

Daylight Opening Size: 4' 9-1/4" wide by 6' 5-1/4" high

Finish All aluminum was white.

Glazing Details: The test specimen utilized 7/8" thick, scaled insulating glass constructed from two sheets of 3/16" thick, clear annealed glass and a metal reinforced butyl space system. The glass was interior glazed against double-sided adhesive foam tane and the system. with aluminum snap-in glazing beads.

> 130 Demy Court York, PA 17402-9405 phone: 717.764.7700 fax; 717,764.4129 www.archtest.com





Frame Construction: The frame was constructed of extruded aluminum with coped, butted, and sealed corners fastened with two #8 x 1" screws through the head and sill into each jamb screw boss.

Reinforcement: No reinforcement was utilized.

Installation: The test specimen was installed into a 2 x 8 #2 Spruce-Pine-Fir wood test buck. #8 x 2-1/2" installation screws were utilized 18" on center around the interior perimeter. Polyurethane was utilized to seal the exterior.

Test Results:

The results are tabulated as follows:

<u>Paragraph</u>	Title of Test - Test Method	Results	Allowed
	Air Infiltration (ASTM E 283-91)		
	@ 1.57 psf (25 mph)	0.04 cfm/ft ²	0.3 cfm/ft² max.

Note #1: The tested specimen meets the performance levels specified in AAMA/NWWDA 101/I.S. 2-97 for air infiltration.

	Water Resistance (ASTM E:	547-00)	
	WTP = 2.86 psf	No leakage	No leakage
2.1.4.1	Uniform Load Deflection (A: (Measurements reported were (Loads were held for 33 second	taken on the jamb)	
	@ 25.9 psf (positive) @ 34.7 psf (negative)	0.01" 0.01"	0.41" max. 0.41" max.
2.1.4,2	Uniform Load Structural (AS (Measurements reported were (Loads were held for 10 second	taken on the jamb)	
	@ 38.9 psf (positive) @ 52.1 psf (negative)	0.0" 0.01"	0.29" max. 0.29" max.





Title of Test - Test Method

Test Results: (Continued)

Paragraph

Paragraph	Title of Test - Test Method	Results	Allowed
	Forced Entry Resistance (ASTM F	588-97)	
	Type: D		
	Grade: 10		
	Hand and Tool Manipulation Test	No entry	No entry
Optional Per	formance		
4.3	Water Resistance (ASTM E 547-0	0)	
	WTP = 8.25 psf	No leakage	No leakage
	Uniform Load Deflection (ASTM	E 330-97)	
	(Measurements reported were take (Loads were held for 33 seconds)	n on the jamb)	
	@ 45.0 psf (positive)	0.02"	A 411
	@ 47.2 psf (negative)	0.02"	0.41" max.
		0.02	0.41" max.
	Uniform Load Structural (ASTM F	330-97)	
	(Measurements reported were taken	n on the jamb)	
	(Loads were held for 10 seconds)		
	@ 67.5 psf (positive)	0.01"	0.29" max
	@ 70.8 psf (negative)	0.02"	0.29" max.
			- nameda.

Detailed drawings, representative samples of the test specimen, and a copy of this report will be retained by ATI for a period of four years. The above results were secured by using the designated test methods and they indicate compliance with the performance requirements of the above referenced specification. This report does not constitute certification of this product, which may only be granted by the certification program administrator.

For ARCHITECTURAL TESTING, INC.

Mark A. Hess Technician

MAH:nb 01-41135.01 Allen N. Reeves, P.E.

Director - Engineering Services (1)

1 APAIL 2002



AAMA/NWWDA 101/LS.2-97 TEST REPORT SUMMARY

Rendered to:

MI HOME PRODUCTS, INC.

SERIES/MODEL: 650 Fin
TYPE: Aluminum Single Hung Window

Title of Test	Results
Rating	H-R40 52 x 72
Overall Design Pressure	+45.0 psf -47.2 psf
Operating Force	11 lb max.
Air Infiltration	0.13 cfm/ft ²
Water Resistance	6.00 psf
Structural Test Pressure	+67.5 psf -70.8 psf
Deglazing	Passed
Forced Entry Resistance	Grade 10

Reference should be made to Report No. 01-41134.01 dated 03/26/02 for complete test specimen (?)

For ARCHITECTURAL TESTING, INC.

Mark A. Hess, Technician

MAH:ntb

alle A. Reeming



AAMA/NWWDA 101/I.S.2-97 TEST REPORT

Rendered to

MI HOME PRODUCTS, INC. 650 West Market Street P.O. Box 370 Gratz, Pennsylvania 17030-0370

> Report No: 01-41134.01 Test Date: 03/07/02 Report Date: 03/26/02 Expiration Date: 03/07/06

Project Summary: Architectural Testing, Inc. (ATI) was contracted by MI Home Products, Inc. to perform tests on Series/Model 650 Fin, aluminum single hung window at their facility located in Elizabethville, Pennsylvania. The samples tested successfully met the performance requirements for a H-R40 52 x 72 rating.

Test Specification: The test specimen was evaluated in accordance with AAMA/NWWDA. 101/LS.2-97, Voluntary Specifications for Aluminum, Vinyl (PVC) and Wood Windows and Glass Doors.

Test Specimen Description:

Series/Model: 650 Fin

Type: Aluminum Single Hung Window

Overall Size: 4' 4-1/4" wide by 6' 0-3/8" high

Active Sash Size: 4' 1-3/4" wide by 3' 0-5/8" high

Daylight Opening Size: 3' 11-3/8" wide by 2' 9-1/2" high

Screen Size: 4' 0-1/4" wide by 2' 11-1/8" high

Finish: All aluminum was white.

Glazing Details: The active and fixed lites utilized 5/8" thick, sealed insulating glass constructed from two sheets of 1/8" thick, clear annealed glass and a metal reinforced butyl spacer system. The active sash was channel glazed utilizing a flexible vinyl wrap ground gasket. The fixed lite was interior glazed against double-sided adhesive foare tape and secured with PVC snap-in glazing beads.

130 Derry Court York, PA 17402-9405 phone: 717.764.7700 fax: 717.764.4129 www.archtest.com

aller M. Rem

STATE OF

2





Weatherstripping:

Description	Quantity	Location
0.230" high by 0.270" backed polypile with center fin	1 Row	Fixed meeting rail
0.250" high by 0.187" backed polypile with center fin	2 Rows	Active sash stiles
1/2" x 1/2" dust plug	4 Pieces	Active sash, top and bottom of stiles
1/4" foam-filled vinyl bulb seal	1 Row	Active sash, bottom rail

Frame Construction: The frame was constructed of extruded aluminum with coped, butted, and sealed corners fastened with two #8 x 1" screws through the head and sill into each jamb screw boss. End caps were utilized on the ends of the fixed meeting rail and secured with two 1-1/4" screws per cap. Meeting rail was secured to the frame utilizing two 1-1/4" screws.

Sash Construction: The sash was constructed of extruded aluminum with coped, butted, and sealed corners fastened with two #8 x 1-1/2" screws through the rails into each jamb screw boss.

Screen Construction: The screen was constructed from roll-formed aluminum with keyed corners. The fiberglass mesh was secured with a flexible spline.

Hardware:

Description	Quantity	Location
Metal cam lock with keeper		Midspan, active meeting rail with keeper adjacent on fixed meeting rail
Plastic tilt latch	2	Active sash, meeting rail ends
Metal tilt pin	2	Active sash, bottom rail ends
Balance assembly	2	One in each jamb
Screen plunger	2	4" from rail ends on top rail NO. 1975
		TATE .
		alle M. Read Son Distriction of the State of



Drainage: Sloped sill

Reinforcement: No reinforcement was utilized.

Installation: The test specimen was installed into a 2 x 8 #2 Spruce-Pine-Fir wood test buck with #8 x 1-5/8" drywall screws every 8" on center around the nail fin. Polyurethane was used as a scalant under the nail fin and around the exterior perimeter.

Test Results:

The results are tabulated as follows:

Paragraph	Title of Test - Test Method	Results	Allowed
2.2.1.6.1	Operating Force	11 lbs	30 lbs max
	Air Infiltration (ASTM E 283-91)		
Mass div. m	@ 1.57 psf (25 mph)	0.13 cfm/ft ²	0.3 cfm/ft² max

Note #1: The tested specimen meets the performance levels specified in AAMA/NWWDA 101/I.S. 2-97 for air infiltration.

	water Resistance (ASTM E 54 (with and without screen) WTP = 2.86 psf	47-00) No leakage	No leakage
2.1.4.1	Uniform Load Deflection (AST (Measurements reported were to (Loads were held for 33 second @ 25.9 psf (positive)	aken on the meeting rails)	
	@ 34.7 psf (negative)	0.42"*	0.26" max.

*Exceeds L/175 for deflection, but passes all other test requirements.

Uniform Load Structural (ASTM E 330-97)
(Measurements reported were taken on the meeting rail)
(Loads were held for 10 seconds)

@ 38.9 psf (positive)

@ 52.1 psf (negative)

0.02"

0.18" max.

0.18" max.

APRIL 2002





Paragraph	Title of Test - Test Method	Results	Allowed	
2.2.1.6.2	Deglazing Test (ASTM E 987) In operating direction at 70 lbs			
	Meeting rail Bottom rail	0.12"/25% 0.12"/25%	0.50°/100% 0.50°/100%	
	In remaining direction at 50 lbs			
	Loft stile Right stile	0.06"/12% 0.06"/12%	0.50"/100% 0.50"/100%	
	Forced Entry Resistance (ASTM F 588-97)			
	Type: A Grade: 10			
	Lock Manipulation Test	No entry	No entry	
	Tests A1 through A5 Test A7	No entry No entry	No entry No entry	
	Lock Manipulation Test	No entry	No entry	
Optional Per	formance			
4.3	Water Resistance (ASTM E 547-00) (with and without screen)			
	WTP = 6.00 psf	No leakage	No leakage	
	Uniform Load Deflection (ASTM I (Measurements reported were taken (Loads were held for 33 seconds)	330-97) on the meeting rail)		
	@ 45.0 psf (positive) @ 47.2 psf (negative)	0.47"* 0.46"*	0.26" max.	

*Exceeds L/175 for deflection, but passes all other test requirements.

Uniform Load Structural (ASTM E 330-97) (Measurements reported were taken on the meeting rail) (Loads were held for 10 seconds) @ 67.5 psf (positive) @ 70.8 psf (negative)

CIL M. Remarks OF CONTRACT OF CONTRACT OF THE PROPERTY OF THE

0.26" max.



01-41134.01 Page 5 of 5

Detailed drawings, representative samples of the test specimen, and a copy of this report will be retained by ATI for a period of four years. The above results were secured by using the designated test methods and they indicate compliance with the performance requirements of the above referenced specification. This report does not constitute certification of this product, which may only be granted by the certification program administrator.

For ARCHITECTURAL TESTING, INC:

1.11 Technician

MAH:nlb 01-41134.01 Allen N. Reeves, P.E.

Director - Engineering Services

I APRIL 2002





AAMA/NWWDA 101/I.S.2-97 TEST REPORT

Rendered to:

MI HOME PRODUCTS, INC.

SERIES/MODEL: 650
TYPE: Aluminum Triple Single Hung Window

Title of Test	Summary of Results	
AAMA Rating	H-R35 112 x 72	
Uniform Load Deflection Test Pressure	+35.3 psf -47.2 psf	
Operating Force	25 lb max.	
Air Infiltration	0.16 cfm/ft ²	
Water Resistance Test Pressure	5.25 psf	
Uniform Load Structural Test Pressure	+53.0 psf -52.5 psf	
Deglazing	Passed	
Forced Entry Resistance	Grade 10	

Reference should be made to ATI Report No. 01-41641.01 for complete description and data.

Iller M. Rames

Zooz OR



AAMA/NWWDA 101/LS.2-97 TEST REPORT

Rendered to

MI HOME PRODUCTS, INC.
P.O. Box 370
650 West Market Street
Gratz. Pennsylvania 17030-0370

Report No: 01-41641.01

Test Date: 05/13/02

And: 05/16/02

Report Date: 06/05/02

Expiration Date: 05/16/06

Project Summary: Architectural Testing, Inc. (ATI) was contracted by MI Home Products, Inc. to witness testing on a Series/Model 650, aluminum triple single hung window at their facility located in Elizabethville, Pennsylvania. The sample tested successfully met the performance requirements for a H-R35 112 x 72 rating.

Test Specification: The test specimen was evaluated in accordance with AAMA/NWWDA 101/I.S.2-97, Voluntary Specifications for Aluminum, Vinyl (PVC) and Wood Windows and Glass Doors.

Test Specimen Description:

Series/Model: 650

Type: Aluminum Triple Single Hung Window

Overall Size: 9' 3-1/2" wide by 5' 11-11/16" high

Active Sash Size (3): 3' 0-1/4" wide by 2' 10-3/4" high

Fixed Daylight Opening Size (3): 2' 8-1/4" wide by 2' 9-1/8" high

Screen Size (3): 2' 9-1/8" wide by 2' 11" high

Finish: All aluminum was painted white.

130 Derry Court York, PA 17402-9405 phone: 717.764.7700 fax: 717.764.4129 www.archtest.com





Glazing Details: The active and fixed lites utilized 5/8" thick, sealed insulating glass constructed from two sheets of 1/8" thick, clear annealed glass and a metal reinforced butyl spacer system. The active sash was channel glazed utilizing a flexible vinyl wrap-around gasket. The fixed lite was interior glazed against double-sided adhesive foam tape and secured with PVC snap-in glazing beads.

Weatherstripping:

<u>Description</u>	Quantity	Location	
0.230" high by 0.270" backed polypile with center fin	Row	Fixed meeting rail	
0.250" high by 0.187" backed polypile with center fin	2 Rows	Active sash stiles	
1/2" by 1/2" dust plug	4 Pieces	Active sash, top and bottom of stiles	
1/4" foam filled vinyl bulb seal	1 Row	Active sash, bottom rail	

Frame Construction: The frame was constructed of extruded aluminum with coped, butted, and sealed corners fastened with two #8 x 1" screws through the head and sill into each jamb screw boss. End caps were utilized on the ends of the fixed meeting rail and secured with two 1-1/4" screws per cap. The meeting rail was secured to the frame utilizing two 1-1/4" screws. The multions were secured utilizing four #8 x 1-1/4" screws through the head and sill into the multion screw boss.

Sash Construction: The sash was constructed of extruded aluminum with coped, butted, and sealed corners fastened with two #8 x 1-1/2" screws through the rails into each stiles' screw boss.

Screen Construction: The screen was constructed from roll-formed aluminum with keyed corners. The fiberglass mesh was secured with a flexible spline.

STATE OF STA



Hardware:

Description	Ouantity	Location
Metal cam lock with keeper	1	Midspan of each active meeting rail with adjacent keepers
Plastic tilt latch	2	Each active sash meeting rail ends
Metal tilt pin	2	Each active sash bottom rail ends
Balance assembly	2	Each active sash contained one in each jamb
Screen plunger	2	Each screen contained two 4" from rail ends on top rail

Drainage: Sloped sill

Reinforcement: No reinforcement was utilized.

Installation: The test specimen was installed into a 2 x 8 #2 Spruce-Pine-Fir wood buck with #8 x 1-5/8" drywall screws every 8" on center around the nail fin. Polyurethane was used as a sealant under the nail fin and around the exterior perimeter.

Test Results:

The results are tabulated as follows.

Paragraph	Title of Test - Test Method	Results	Allowed
2.2.1.6.1	Operating Force	25 lbs	30 lbs max.
	Air Infiltration (ASTM E 283-91)		
	@ 1.57 psf (25 mph)	0.16 cfm/ft ²	0.3 cfm/ft ² max

Note #1: The tested specimen meets the performance levels specified in AAMA/NWWDA 101/I.S. 2-97 for air infiltration.

> Water Resistance (ASTM E 547-00) (with and without screen) WTP = 2.86 psf

No leakage

No leakage #2 1235 7 JONE 2002



Test Results: (Continued)

			grand the second of the second	
Paragraph	Title of Test - Test Method	Results	Allowed	
2.1.4.1	Uniform Load Deflection (AST)	M E 330-97)		
	(Measurements reported were tal	[1] [1] [1] [1] [1] [1] [1] [1] [1] [1]		
	(Loads were held for 52 seconds			
	@ 15.0 psf (positive)	0.15"	0.41" max.	
	@ 15.0 psf (negative)	0.29"	0.41" max.	
2.1.4.2	Uniform Load Structural (ASTN	1 E 330-97)		
	(Measurements reported were ta			
	(Loads were held for 10 seconds)		
	@ 22.5 psf (positive)	0.01"	0.29" max.	
	@ 22.5 psf (negative)	0.01"	0.29" max.	
2.26.2	Deglazing Test (ASTM E 987-8	8)		
	In operating direction at 70 lbs			
	Right sash, meeting rail	0.12"/25%	0.50"/100%	
	Right sash, bottom rail	0.12"/25%	0.50"/100%	
	Middle sash, meeting rail	0.12"/25%	0.50"/100%	
	Middle sash, bottom rail	0.12"/25%	0.50"/100%	
	Left sash, meeting rail	0.12"/25%	0.50"/100%	
	Left sash, bottom rail	0.12"/25%	0.50"/100%	
	In remaining direction at 50 lbs			
	Right sash, right stile	0.000,000		
	Right sash, left stile	0.06"/12%	0.50"/100%	
	Middle sash, right stile	0.06"/12%	0.50"/100%	
	Middle sash, left stile	0.06"/12%	0.50"/100%	
	Left sash, right stile	0.06"/12%	0.50"/100%	
	Left sash, left stile	0.06"/12%	0.50"/100%	
		0.06"/12%	0.50"/100%	
2 .8	Forced Entry Resistance (ASTM F 588-97)			
	Type: A	V 5 K 5		
	Grade: 10			
	Lock Manipulation Test			
	Took istemburation Lest	No entry	No entry	
	Test A1 through A5	37-		
	Test A7	No entry	No entry N. P.	
		No entry	No shoe	
	Lock Manipulation Test	No ent-	S. C. Killing	
		No entry	150 anny 113. 15254 .	
			2 -	
		all on	2 ED 1 17170	
		TUNE 2	Pendio STATE OF	
		LONE 2	2002 1000 2000	
			The State of the S	
			A Section	
			. sabiteety, 42,	



Test Results: (Continued)

Paragraph	Title of Test - Test Method	Results	Allowed
Optional Per	<u>formance</u>		
4.3	Water Resistance (ASTM E 54 (with and without screen) WTP = 5.25 psf	7-00) No leakage	No leakage
	Uniform Load Deflection (ASTM E 330-97) (Measurements reported were taken on the mullion) (Loads were held for 52 seconds) @ 35.3 psf (positive) 0.46"* 0.41" ma @ 47.2 psf (negative) 0.67"* 0.41" ma		
*Exceeds L/1	75 for deflection, but meets all other	er test romirom out	

Uniform Load Structural (ASTM E 330-97)

(Measurements reported were taken on the mullion)

(Loads were held for 10 seconds)

@ 53.0 psf (positive) 0.03" 0.29" max @ 52.5 psf (negative) 0.02" 0.29" max

Detailed drawings, representative samples of the test specimen, and a copy of this report will be retained by ATI for a period of four years. The above results were secured by using the designated test methods and they indicate compliance with the performance requirements of the above referenced specification. This report does not constitute certification of this product, which may only be granted by the certification program administrator.

For ARCHITECTURAL TESTING, INC.

Morh A. Cham Technician

MAH:nlb 01-41641.01

Illen M. Rem Allen N. Reeves, P.E.

Director - Engineering Services

7 JUNE 2002

Premdor Entry Systems

ACCEPTANCE No.: 01-0314.18

APPROVED

JUN 0 5 2001

EXPIRES

April 02, 2006

STANDARD CONDITIONS NOTICE OF ACCEPTANCE:

Renewal of this Acceptance (approval) shall be considered after a renewal application has been filed 1. and the original submitted documentation, including test supporting data, engineering documents, are no older than eight (8) years.

Any and all approved products shall be permanently labeled with the manufacturer's name, city, 2. state, and the following statement: "Miami-Dade County Product Control Approved", or as specifically stated in the specific conditions of this Acceptance.

Renewals of Acceptance will not be considered if: 3.

There has been a change in the South Florida Building Code affecting the evaluation of this product and the product is not in compliance with the code changes.

The product is no longer the same product (identical) as the one originally approved. b.

If the Acceptance holder has not complied with all the requirements of this acceptance, including the correct installation of the product.

- The engineer who originally prepared, signed and scaled the required documentation initially d. submitted, is no longer practicing the engineering profession.
- Any revision or change in the materials, use, and/or manufacture of the product or process shall 4. automatically be cause for termination of this Acceptance, unless prior written approval has been requested (through the filing of a revision application with appropriate fee) and granted by this office.
- Any of the following shall also be grounds for removal of this Acceptance: 5.

Unsatisfactory performance of this product or process.

- Misuse of this Acceptance as an endorsement of any product, for sales, advertising or any b. other purposes.
- The Notice of Acceptance number preceded by the words Miami-Dade County, Florida, and followed by the expiration date may be displayed in advertising literature. If any portion of the Notice of Acceptance is displayed, then it shall be done in its entirety.
- A copy of this Acceptance as well as approved drawings and other documents, where it applies. 7. shall be provided to the user by the manufacturer or its distributors and shall be available for inspection at the job site at all time. The engineer needs not reseal the copies.
- Failure to comply with any section of this Acceptance shall be cause for termination and removal of Acceptance.
- This Notice of Acceptance consists of pages 1, 2 and this last page 3. 9.

END OF THIS ACCEPTANCE

Manuel Perez, P.E., Product Control Examiner Product Control Division

Premdor Entry Systems

ACCEPTANCE No.: 01-0314.18

APPROVED

JUN 0 5 2001

EXPIRES

April 02, 2006

NOTICE OF ACCEPTANCE: SPECIFIC CONDITIONS

1. SCOPE

1.1 This renews the Notice of Acceptance No. 00-0321.20 which was issued on April 28, 2000. It approves a residential insulated door, as described in Section 2 of this Notice of Acceptance, designed to comply with the South Florida Building Code (SFBC), 1994 Edition for Miami-Dade County, for the locations where the pressure requirements, as determined by SFBC Chapter 23, do not exceed the Design Pressure Rating values indicated in the approved drawings.

2. PRODUCT DESCRIPTION

2.1 The Series Entergy 6-8 S-W/E Inswing Opaque Single Residential Insulated Steel Door with Sidelites- Impact Resistant Door Slab Only and its components shall be constructed in strict compliance with the following documents: Drawing No 31-1020-EW-I, Sheets I through 6 of 6, titled "Premdor (Entergy Brand) Wood Edge Single Door in Wood Frames with a Bumper Threshold (Inswing)," prepared by manufacturer, dated 7/29/97 with revision C dated 01/15/01, bearing the Miami-Dade County Product Control approval stamp with the Notice of Acceptance number and approval date by the Miami-Dade County Product Control Division. These documents shall hereinafter be referred to as the approved drawings.

3. LIMITATIONS

- 3.1 This approval applies to single unit applications of single door only, as shown in approved drawings.
- 3.2 Unit shall be installed only at locations protected by a canopy or overhang such that the angle between the edge of canopy or overhang to sill is less than 45 degrees. Unless unit is installed in non-habitable areas where the unit and the area are designed to accept water infiltration.

4. INSTALLATION

4.1 The residential insulated steel door and its components shall be installed in strict compliance with the approved drawings.

4.2 Hurricane protection system (shutters):

- 4.2.1 Door: the installation of this unit will not require a hurricane protection system.
- 4.2.2 Sidelite: the installation of this unit will require a hurricane protection system.

5. LABELING

5.1 Each unit shall bear a permanent label with the manufacturer's name or logo, city, state and following statement: "Miami-Dade County Product Control Approved".

6. BUILDING PERMIT REQUIREMENTS

6.1 Application for building permit shall be accompanied by copies of the following:

6.1.1 This Notice of Acceptance

6.1.2 Duplicate copies of the approved drawings, as identified in Section 2 of this Notice of Acceptance, clearly marked to show the components selected for the proposed installation.

6.1.3 Any other documents required by the Building Official or the South Florida Building Code (SFBC) in order to properly evaluate the installation of this system.

Manuel Perez, P.E. Product Control Examiner

Product Control Division



FEB - 4 FED

January 31, 2002

TO: OUR FLORIDA CUSTOMERS:

Effective February 1, 2002, the following TAMKO shingles, as manufactured at TAMKO's Tuscaloosa, Alabama, facility, comply with ASTM D-3161, Type I modified to 110 mph. Testing was conducted using four nails per shingle. These shingles also comply with Florida Building Code TAS 100 for wind driven rain.

- Glass-Seal AR
- Elite Glass-Seal AR
- ASTM Heritage 30 AR (formerly ASTM Heritage 25 AR)
- Heritage 40 AR (formerly Heritage 30 AR)
- Heritage 50 AR (formerly Heritage 40 AR)


All testing was performed by Florida State certified independent labs.

Please direct all questions to TAMKO's Technical Services Department at 1-800-641-4691.

TAMKO Roofing Products, Inc.



Application Instructions For Heritage® 25 Series Shingles



In the first 10 courses, there are 4 cuts and no waste.

When you reach the other side of the roof, whatever has to be trimmed off can be used in the field of roofing.

For additional application information consult the application instructions printed on the product package.

NOTE: These application instructions apply only to Heritage 25 and Heritage 25 AR shingles.



Application Instructions for

· Glass-Seal AR

• Glass-Seal ----- • Elite Glass-Seal® · Elite Glass-Seal® AR

Three-tab asphalt shingles

THESE ARE THE MANUFACTURER'S APPLICATION INSTRUCTIONS FOR THE ROOFING CONDITIONS DESCRIBED. TAMKO ROOF-ING PRODUCTS, INC. ASSUMES NO RESPONSIBILITY FOR LEAKS OR OTHER ROOFING DEFECTS RESULTING FROM FAILURE TO FOLLOW THE MANUFACTURER'S INSTRUCTIONS.

THIS PRODUCT IS COVERED BY A LIMITED WARRANTY, THE TERMS OF WHICH ARE PRINTED ON THE WRAPPER. IN COLD WEATHER (BELOW 40°F), CARE MUST BE TAKEN TO AVOID DAMAGE TO THE EDGES AND CORNERS OF THE SHINGLES.

IMPORTANT: It is not necessary to remove the plastic strip from the back of the shingles.

I. ROOP DECK

These shingles are for application to roof decks capable of receiving and retaining fasteners, and to inclines of not less than 2 in. per foot. For roofs having pitches 2 in. per foot to less than 4 in. per foot, refer to special instructions titled "Low Slope Application". Shingles must be applied properly. TAMKO assumes no responsibility for leaks or defects resulting from improper application, or failure to properly prepare the surface to be roofed over.

NEW ROOF DECK CONSTRUCTION: Roof deck must be smooth, dry and free from warped surfaces. It is recommended that metal drip edges be installed at eaves and rakes.

PLYWOOD: All plywood shall be exterior grade as defined by the American Plywood Association. Plywood shall be a minimum of 3/8 in. thickness and applied in accordance with the recommendations of the American Plywood Association.

SHEATHING BOARDS: Boards shall be well-seasoned tongue-andgroove boards and not over 6 in. nominal width. Boards shall be a 1 in. nominal minimum thickness. Boards shall be properly spaced and nailed.

ROTELICKEY.S

Inadequate ventilation of attic spaces can cause accumulation of moisture in winter months and a build up of heat in the summer. These conditions can lead to:

- 1. Vapor Condensation
- 2. Buckling of shingles due to deck movement
- 3. Rotting of wood members.
- 4. Premature failure of roof.

To insure adequate ventilation and circulation of air, place louvers of sufficient size high in the gable ends and/or install continuous ridge and

FHA minimum property standards require one square foot of net free ventilation area to each 150 square feet of space to be vented, or one square foot per 300 square feet if a vapor barrier is installed on the warm side of the ceiling or if at least one half of the ventilation is provided near the ridge. If the ventilation openings are screened, the total area should be doubled.

IT IS PARTICULARLY IMPORTANT TO PROVIDE ADEQUATE VEN-TILATION.

Dringtery . E


NAILS: TAMKO recommends the use of nails as the preferred method

WIND CAUTION: Extreme wind velocities can damage these shingles after application when proper sealing of the shingles does not occur. This can especially be a problem if the shingles are applied in cooler months or in areas on the roof that do not receive direct sunlight. These conditions may impede the sealing of the adhesive strips on the shingles. The inability to seal down may be compounded by prolonged cold weather conditions and/or blowing dust. In these situations, hand sealing of the shingles is recommended. Shingles must also be fastened according to the fastening instructions described below.


Correct placement of the fasteners is critical to the performance of the shingle. If the fasteners are not placed as shown in the diagram and described below, TAMKO will not be responsible for any shingles blown off or displaced. TAMKO will not be responsible for damage to shingles caused by winds or gusts exceeding gale force. Gale force shall be the standard as defined by the U.S. Weather Bureau.

FASTENING PATTERNS: Fasteners must be placed above or below the factory applied sealant in an area between 5-1/2" and 6-3/4" from the butt edge of the shingle. Fasteners should be located horizontally according to the diagram below. Do not nail into the sealant. TAMKO recommends nailing below the sealant whenever possible for greater wind resistance.

1) Standard Fastening Pattern. (For use on decks with slopes 2 in. per foot to 21 in. per foot.) One fastener 1 in, back from each end and one 12 in. back from each end of the shingle for a total of 4 fasteners. (See standard fastening pattern illustrated below).



2) Mansard or High Wind Fastening Pattern. (For use on decks with slopes greater than 21 in. per foot.) One fastener 1 in. back from each end and one fastener 10-1/2 in. back from each end and one fastener 13-1/2 in, back from each end for a total of 6 fastener per shingle. (See Mansard fastening pattern illustrated below.)



NAILS: TAMKO recommends the use of nails as the preferred method of application. Standard type roofing nails should be used. Nail shanks should be made of minimum 12-gauge wire, and a minimum head diameter of 3/8 in. Nails should be long enough to genetrate 3/4 in.

(Continued)

Visit Our Web Site at www.tamko.com Central District Northeast District Southeast District Southwest District Western District

220 West 4th St., Joplin, MO 64801 4500 Tamko Dr., Frederick, MD 21701 2300 35th St., Tuscaloosa, AL 35401 7910 S. Central Exp., Dallas, TX 75216 5300 East 43rd Ave., Denver, CO 80216

800-641-4591 800-368-2055 800-228-2656 800-443-1834 800-530-8868



(CONTINUED from Pg. 2)

• Glass-Seal • Glass-Seal AR

• Elite Glass-Seal® • Elite Glass-Seal® AR

THREE-TAB ASPHALT SHINGLES

with quick setting asphalt adhesive cement immediately upon installation. Spots of cement must be equivalent in size to a \$.25 piece and applied to shingles with a 5 in. exposure, use 6 fasteners per shingle. See Section 3 for the Mansard Fastening Pattern.

S. BZ-ROOFING

Nail down or remove curied or broken shingles from the existing roof. Replace all missing shingles with new ones to provide a smooth base. Shingles that are buckled usually indicate warped decking or protruding nails. Hammer down all protruding nails or remove them and refasten in a new location. Remove all drip edge metal and replace with new.


If re-roofing over an existing roof where new flashing is required to protect against ice dams (freeze/thaw cycle of water and/or the backup of water in frozen or dogged gutters), remove the old roofing to a point at least 24 in. beyond the interior wall line and apply TAMKO's Moisture Guard Plus® waterproofing underlayment. Contact TAMKO's Technical Services Department for more information.

The nesting procedure described below is the preferred method for rerooting over square tab strip shingles with a 5 in. exposure.

Starter Course: Begin by using TAMKO Shingle Starter or by cutting shingles into 5 x 36 inch strips. This is done by removing the 5 in. tabs from the bottom and approximately 2 in. from the top of the shingles so that the remaining portion is the same width as the exposure of the old shingles. Apply the starter piece so that the self-sealing adhesive lies along the eaves and is even with the existing roof. The starter shing should be wide enough to overhang the eaves and carry water into the gutter. Remove 3 in. from the length of the first starter shingle to ensure that the joints from the old roof do not align with the new.

First Course: Cut off approximately 2 in, from the bottom edge of the shingles so that the shingles fit beneath the existing third course and align with the edge of the starter strip. Start the first course with a full 36 in, long shingle and fasten according to the instructions printed in Section 3.

Second and Succeeding Courses: According to the off-set application method you choose to use, remove the appropriate length from the



rake end of the first shingle in each succeeding course. Place the top edge of the new shingle against the butt edge of the old shingles in the courses above. The full width shingle used on the second course will reduce the exposure of the first course to 3 in. The remaining courses will automatically have a 5 in. exposure.

9. FALLEY APPLICATION

Over the shingle underlayment, center a 36 in. wide sheet of TAMKO Nail-Fast® or a minimum 50 lb: roll roofing in the valley. Nail the felt only where necessary to hold it in place and then only nail the outside edges.

IMPORTANT: PRIOR TO INSTALLATION WARM SHINGLES TO PRE-VENT DAMAGE WHICH CAN OCCUR WHILE BENDING SHINGLES TO FORM VALLEY.

 Apply the first course of shingles along the eaves of one of the intersecting roof planes and across the vailey.

Note: For proper flow of water over the trimmed shingle, always start applying the shingles on the roof plane that has the lower slope or less height.

- Extend the end shingle at least 12 in. onto the adjoining roof. Apply succeeding courses in the same manner, extending them across the valley and onto the adjoining roof.
- · Do not trim if the shingle length exceeds 12 in. Lengths should vary.
- · Press the shingles tightly into the valley.
- · Use normal shingle fastening methods.

Note: No fastener should be within 6 in. of the valley centerline, and two fasteners should be placed at the end of each shingle crossing the valley.

 To the adjoining roof plane, apply one row of shingles extending it over previously applied shingles and trim a minimum of 2 in. back from the centerline of the valley.

Note: For a neater installation, snap a chalkline over the shingles for quidance.

Clip the upper comer of each shingle at a 45-degree angle and embed the end of the shingle in a 3 in. wide strip of asphalt plastic cament. This will prevent water from penetrating between the courses by directing it into

ST wide TAMOD Valley Cartainline

The Valley.


The Co containing

The Co c



Excessive use of adhesive will cause bilstering to this product.

TAMKO assumes no responsibility for blistering.



Visit Our Web Site at www.tamko.com

Central District Northeast District Southeast District Southwest District Western District

220 West 4th St., Joplin, MO 64801 4500 Tamko Dr., Frederick, MD 21701 2300 35th St., Tuscaloosa, AL 35401 7910 S. Central Exp., Dallas, TX 75216 5300 East 43rd Ave., Denver, CO 80216 800-541-4591 800-368-2055 800-228-2656 800-443-1834 800-530-8868

07/01

3



(CONTINUED from Pg. 3)

- · Glass-Seal · Glass-Seal AR
- Elite Glass-Seal® • Elite Glass-Seal® AR

Three-tab asphalt shingles

FOR ALTERNATE VALLEY APPLICATION METHODS, PLEASE CONTACT TAMKO'S TECHNICAL SERVICES DEPARTMENT.

io. Hip and aidge fastening detail

Apply the shingles with a 5 in, exposure beginning at the bottom of the hip or from the end of the ridge opposite the direction of the prevailing winds. Secure each shingle with one fastener 5-1/2 in, back from the exposed end and 1 in, up from the edge. Do not nail directly into the sealant.

TAMKO recommends the use of TAMKO Hip & Ridge shingle products. Where matching colors are available, it is acceptable to use TAMKO's Glass-Seal or Elite Glass-Seal shingles cut down to 12 in, pieces,


NOTE: AR type shingle products should be used as Hip & Ridge on Glass-Seal AR and Elite Glass-Seal AR shingles.

Fasteners should be 1/4 in. longer than the one used for shingles.

IMPORTANT: PRIOR TO INSTALLATION, CARE NEEDS TO BE TAXEN TO PREVENT DAMAGE WHICH CAN OCCUR WHITE BENDING SHINGLES IN COOL WEATHER.

THESE ARE THE MANUFACTURER'S APPLICATION INSTRUCTIONS FOR THE ROOFING CONDITIONS DESCRIBED. TAMKO ROOFING PRODUCTS, INC. ASSUMES NO RESPONSIBILITY FOR LEAKS OR OTHER ROOFING DEFECTS RESULTING FROM FAIL-URE TO FOLLOW THE MANUFACTURER'S INSTRUCTIONS.

Direction of prevailing wind



THIS PRODUCT IS COVERED BY A LIMITED WARRANTY. THE TERMS OF WHICH ARE PRINTED ON THE WRAPPER.

IMPORTANT - READ CAREFULLY BEFORE OPENING BUNDLE

In this paragraph "You" and Your" refer to the installer of the shingles and the owner of the building on which these shingles will be installed. This is a legally binding agreement between You and TAMKO Roofing Products, Inc. ("TAMKO"). By opening this bundle You agree: (a) to install the shingles strictly in accordance with the instructions printed on this wrapper; or (b) that shingles which are not installed strictly in accordance with the instructions printed on this wrapper are sold "AS IS" and are not covered by the limited warranty that is also printed on this wrapper, or any other warranty, including, but not limited to (except where prohibited by law) implied warranties of MERCHANTABILITY and FITNESS FOR USE.

800-530-8868

07:01

Project Review and Design Remediation Recommendations

for the

Remodeling and Addition to Existing Residence for Mr. Ed and Diane Bishop White of Lake City, Florida

prepared for:

Mr. Jefferson Braswell of the law firm Scruggs and Carmichael, PA of Gainesville, Florida.

Prepared by:

Martin Gold, AIA
AR 93691
m_gold design and Consulting
2710 NW 27th Place
Gainesville, Florida

20 March 2007

Executive Summary

The execution of the residential addition design, as envisioned by Mr. and Mrs. White has been severely compromised through the architectural development and the execution of the phases of construction that have occurred up to 13 December, 2005. Errors in the drawings and unconventional building practices (that do not meet the minimum standard set by the Florida Building Code) have produced a partial structure that cannot be effectively completed as illustrated in the architectural drawings.

The fundamental massing, balance and proportion of an architectural composition compatible with the existing residence cannot be physically achieved with the construction that is presently in-place. This conclusion is based on the fact that the existing residence, of noted architectural integrity, has a roof pitch of 2 in 12 (2 foot rise in 12 feet of horizontal run), yet the design of the addition is based on a 3 in 12 roof pitch. The roof pitch is a critical global architectural parameter that establishes the building proportion, aesthetic symmetry, potential for room height and detailing required for the integration of second floor and loft space. The base bearing elevation of the roof was incorrectly identified on the drawings with the existing roof shown approximately 1' - 0" higher than it actually is. Furthermore, the relationship between the building and the ground is not correctly represented in the drawings — a critical error given the multiple ground levels around the building. Unfortunately, errors of incorrectly representing the existing roof pitch; incorrectly establishing the building ground relationship, using multiple incorrect dimensions; and incorrectly establishing the existing building height are present throughout the drawings. These errors do not seem to have been detected until late in the construction phase.

Many unconventional structural framing practices seem to have been developed by the contractor including the cutting and modification of trusses and engineered wood structural members in a manner inconsistent with the architectural and structural drawings and the Florida Building Code. The initial compromised structural integrity of the phase of construction completed to date has been exacerbated by exposure to weather rendering it unusable. Please also refer to the detailed structural assessment provided by TLC Engineering for Architecture (dated August 28, 2006) and the Freeman Design Group, Inc, (dated July, 28, 2006). Furthermore, these deficiencies were also documented in a facsimile follow-up letter and stop work order based on site inspections conducted December 13, 2005 by Columbia County Building Department officials.

We recommend a complete redesign of the addition to be architecturally compatible with the existing home. In order to use conventional structural systems and that would meet or exceed the standard of the Florida Building Code, the existing addition should be demolished. The incorrect 3 in 12 roof pitch and excessive building height results in massing and structural incongruities in the present construction that poses such a complex puzzle of questions regarding the usability of the slab as a 'correct footprint'; a suitable foundation for structural bearing; and the probable relocation of inslab elements such as plumbing and electrical systems renders the slab likely unusable. Detailed structural analysis would be required to verify the integrity of the slab which would add expense and may prove it to be useless. Therefore, we suggest a complete demolition of the current phase of construction as the most efficacious solution to achieve an architecturally compatible and complete residential addition.

Introduction

M_gold design and consulting has been engaged to evaluate the architectural design drawings of the *Remodeling and Addition to Existing Residence for Mr. Ed and Diane Bishop White* dated 9 May, 2005 with revisions on 21, July 2005; 23 July, 2005; 13 September, 2005; and 13 November 2005 as provided by Associated Florida Architects, Inc. The drawing set was signed and sealed by Mr. Robert S. Taylor, Sr., Architect, AR-0007526. We inspected the remaining existing structure and unfinished construction of the proposed design and met with Mr. White on February 6, 2007. Our analysis, recommendations and this report is based on the review of architectural drawings noted above, site visits, meetings with Mr. White and reviews of structural engineering reports and notes from the Columbia County Building Department. Detailed evaluations of the architectural drawings are included under the heading Drawing Review.

Architectural Integrity

The existing residence of Mr. and Mrs. White is architecturally notable as a Prairie style home. The prairie style, developed by Frank Lloyd Wright in the first decades of the 20th Century, is characterized by a low-pitched roof, overhanging eaves, horizontal lines, central hearth (fireplace) corner windows, open floor plan and clerestory windows. These characteristics are important as the roof pitch is one of the fundamental defining features of the prairie style. Furthermore, the existing home represented a very high quality design interpretation that can be clearly characterized as prairie style architecture. Mr. and Mrs. White were quite sensitive to the architectural character of their home and engaged Associated Florida Architects, Inc. to translate their expansion ideas and spatial needs into an addition that would compliment the existing prairie style home.

Drawing Review

This section includes our review of the individual drawing sheets that were provided by Associated Florida Architects, Inc. This review is not an extensive review and does not propose to detail all of the inconsistencies between the individual drawings, drawings and the existing structure nor conflicts between the drawings and the construction phase completed as of 13 December, 2005. Our comments are intended to reveal important inconsistencies that would cause serious difficulties in completing the project as shown in the drawings.

Field measurements were conducted to verify that the existing roof pitch has a slope of 2 feet of rise in 12 feet of run (2 in 12). The drawings prepared by Associated Florida Architects, Inc. represents the existing roof as having a 3 in 12 roof pitch. Field measurements were also used to verify the height of bearing at the lower eave walls to establish a reference for projecting the roof slope. We found the height of the existing wall at the lowest roof bearing to be approximately eight feet (8' - ½" actual) from the top of slab to the roof bearing point. The architectural drawings provided by Associated Florida Architects, Inc., incorrectly, show this existing height of bearing to be nine feet (9') — an error of 1'-0".

Sheet Description/Comments (in italics)

Cover Cover, Index, Site Plan @ 1"=30"

(09 May 2005)

· no site plan actually shown on the cover sheet.

A - 1.01 Existing Floor Plan @ 1/8" = 1'-0" Demolition Plan @ 1/8" = 1'-0"

(09 May 2005)

no accordion door and transom shown at bedroom entry.

A - 2.01 Floor Plan @ 1/8" = 1'-0" Second Floor Plan 1/8" = 1'-0"

(Rev 13 Nov. 2005)

- The stairs to the second level show 15 risers on the First Floor Plan and 16 risers on the Second Floor Plan. The landing location is not consistent between the plans resulting in ambiguity as to the circulation to and from the second level.
- Gate/entry fence columns not centered on courtyard doors nor are they aligned with the centers of the structural columns of the high ceiling family room. This imbalance will appear as odd.

- Roof overhang is not centered on Family Room facade. There
 is a 2'-0" overhang at the Garage side and a 1'-6" overhang at
 the existing residence side they are both shown as 1'-6" on
 the elevation drawings (A 4.01, revised 21, July, 2005).
- no door shown at bedroom entry in existing residence.

A - 4.01 Elevations @ 1/4" = 1 foot (field directive number one)

(Rev, 13 Sep. 2005)

- The elevation drawings show the existing walls at the lowest roof bearing to be approximately 9' tall. Field measurements revealed this dimension to be 8' - ½". This error can cause substantial problems in construction especially with a twostory, low roof slope design.
- The elevation drawings incorrectly show the building ground relationship of the existing structure.
- The elevation drawings incorrectly show the existing eave (overhang) to be 3'-0" when in fact it is actually 5' - 0".
- Multiple dimensions on the "Right Side Elevation" as shown on the drawings do not match field measurements with differences of 1'-4" in a dimension of less than 7' - 0". This is far beyond normal tolerances for architectural design at a the drawing scale of 1/8" = 1 foot used in the elevation drawings.
- no chimney or fire place venting system is shown for the existing fire place(s). The chimney element is usually a notable design feature of prairie style architecture.
- The spiral stair connecting the deck at the second level to the ground should be shown on the elevation as it makes a significant visual impact on the design.
- Brick veneer is shown graphically two different sizes of brick.

A - 6.01 Building Section @ 1/4" = 1' - 0"

(9 May 2005)

- The building section is not keyed to the plan as is standard practice. Without the reference to the plan it is somewhat ambiguous as to where the section is taken.
- The circulation connection between the Entry Foyer (area inside of the entry doors) and the Family Room is not shown

on this drawing. There should be an opening of some kind to show how these spaces will be connected.

- The high roof structure is not shown. The structural system and depth of the structure should be shown for this element as is shown for other framing systems.
- 16 stair risers are shown on the Building Section which is inconsistent with the First Floor Plan. Furthermore, all risers are not shown with the same height — The Florida Building Code requires all stair risers to be the same height.
- The Partial Stair Section detail calls for 7-3/4" risers, which with 16 risers would come to 10' - 4" above the first floor — the second floor is shown at 10' - 0". With 15 stair risers, as is shown on some drawings, the height of the stair would be 9" -8-1/4". The stairs do not connect with the second floor level as shown in any of the drawings.

A - 7.01 Typical Wall Sections @ 3/4" = 1' - 0"

(09 May 2005)

- We count at least six different wall/roof or wall/deck bearing conditions. As only one "typical" detail is provided, there is great ambiguity as to how the roof and walls will be joined the variety of configurations that exist in the design.
- The "Optional Typical Detail @ Existing Roof" does not have dimensions noted. When the detail is scaled as per the 3/4" = 1' 0" scale, the wall height is shown at nine feet (9' 0"). Field measurements indicate the existing wall is approximately eight feet tall (8' ½" actual).
- M 1.01 Mechanical Plan First Floor @ 1/8" = 1' 0" (09 May 2005)

 Mechanical Plan Second Floor @ 1/8" = 1' 0"
 - No drop ceiling or duct soffit shown for supply and return air outlets in the Pub space.
 - The supply duct leading to the playroom looks like it will be exposed on the elevation of the building if it is run up to typical supply air height. This plan also shows a window at the top of the stairs that is not in the final version of the plan and elevation drawings.
 - A curved landing is also shown here that does not appear in other drawings.

- E 1.01 Electrical Plan First Floor @ 1/8" = 1' 0" (09 May 2005) Electrical Plan - Second Floor @ 1/8" = 1' - 0"
 - The existing panel box is shown to be located on a wall that is shown as removed on the floor plan (A - 2.01, all revision dates) and on the building section (A - 6.01, 9 May, 2005).
 - A light is shown at a balcony on the second floor. This balcony is not shown in the most recent First Floor Plan or Second Floor Plan.
- S 1.01 Details, Foundation Plan @ 1/8" = 1' 0" (09 May 2005)
 - No comments
- S 2.01 Roof Framing Plan: New Addition (13 Sep. 2005) @ 1/8" = 1' - 0", Notes, Details
 - Bearing details for framing over the existing structurally modified wall are not shown. This is a complicated structural connection that should be detailed and reviewed by a licensed structural engineer.
 - The new second level deck is in conflict with the existing roof edge based on the drawings — they are shown to overlap.
 - 18 stair risers shown on the First Floor Framing Plan (15 and 16 risers shown on other drawings as noted above).
 - A Balcony is shown at the Second Level that is not shown in the most recent Second Floor Plan (13 Sep. 2005).

The drawings do not meet, in our professional opinion, the minimum standard of care expected for architectural design. There are substantial conflicts between and within the drawings of various dates including the most recent revision. There are, in our professional judgement, significant omissions of important details and drawings such as building sections or wall sections that show the integration of details with major building components.

Structural Integrity

There are serious concerns with the structural integrity of the construction phase that is in place at the time of this report. Deficiencies and inconsistencies regarding the structural veracity of the Construction Documents drawings and the existing partial structure are well documented by the structural evaluation conducted by TLC Engineering for Architects dated August 28, 2006. The review and recommendations by the Freeman Design Group Engineers and Planners points out many difficulties that seemed to arise from trying to correct design conflicts during construction. Furthermore, the building officials from Columbia County in their follow-up letter from a December 13, 2005 site inspection clearly notes the deficiency of the first floor walls ability to support the second floor. These are very serious deficiencies that could lead to structural failure.

Course of Action

A complete redesign of the addition based on the original sketches that Mr. White developed is required to achieve the renovated home originally commissioned. The correct eave wall height and roof pitch of the existing prairie style home must be used in the earliest phases of design to achieve an integrated and aesthetically balanced union between the new and existing structures. The design should not only be studied in orthographic drawings (2D) but also in 3D computer models and/or physical scale models. This is required to work out the complexities of multiple levels interpenetrating a low-slope (2 in 12) roof system.

Demolish, in it's entirety, the partially complete addition that is in place.

A budget cost estimate must be developed based on new construction costs in the locality and projected out to the estimated time of actual construction. This construction cost estimate should be based on the square foot area with specific adjustments for the quality of materials that are clearly indicated in the design proposal by Associated Architects. Furthermore, adjustments will be required for integrating the structural connection between the new addition and the existing residence — this may need to go beyond the original design as structural analysis does not seem to have been integrated into the construction drawings. A qualified cost consultant should be engaged to develop a project budget based on a best estimate given the quality and scope (area and massing) of the design suggested in drawings by Associated Florida Architects, Inc. The cost estimate must include any specific materials, appliances and finishes called out in the construction documents including the Architectural Specifications for the project.

A demolition cost estimate will also need to be developed.

Architects fees and engineering fees will need to be estimated. These fees can be estimated as a percentage of the cost of construction. Architectural services for design phases, construction documents phases and site supervision phase for a home of this scale and architectural significance would be approximately 10% of the actual cost of construction. Engineering fees could range from 1% to 3% of the cost of construction—an engineering firm should be consulted to hone this estimate.

Conclusions


- The drawings provided by Associated Florida Architects, Inc. do not meet the minimum professional standard and are rife with significant errors and omissions.
- The Associated Florida Architects, Inc. drawings incorrectly establish
 the roof pitch of the existing structure subsequently compromising the
 design of the addition as drawn, it will not match the existing when
 constructed.
- The Associated Florida Architects, Inc. drawings incorrectly establish
 the height of the low eave bearing point with an error of approximately
 one foot the addition, if constructed to the drawings, will not align
 architecturally with the existing structure when constructed.
- The Associated Florida Architects, Inc. drawings incorrectly establish the various ground/foundation heights of the existing structure.
- Modifications to the design were made in the field to correct design errors that contributed to additional conflicts and the noted lack of structural integrity.
- The exposed frame structure has been compromised by the weather, moisture and molds and is unusable.
- The structural integrity of the slab does not meet, as per the TLC engineering report, the bearing capacity required for the roof and wall loads.
- The partially complete addition should be entirely demolished and removed.
- A complete redesign of the addition is required to integrate the original plan provided by Mr. and Mrs White with the prairie style existing

- home. This will require new and complete architectural and engineering services.
- 10. A project construction budget must be established based on the built floor area and adjustments for structural requirements and the quality of finishes (as already defined) to establish the professional fees.
- A complete redesign with integrated structural analysis could take 6 to 12 months.

End of Report

Martin A. Gold, Al. Principal Architect

AR 93691



signed and sealed by Robert S. Taylor Sr., AR 0007526.

AFA, Inc. is Associated Florida Architects, Inc., the incorrect elevation drawing shown in red above is taken from Sheet A -4.01 updated 13 Sept. 2005 and



August 28, 2006

Ed and Diane White P.O. Box 2111 Lake City, FL 32024

Re:

Ed and Diane White Residence Structural Condition Survey Report

TLC Project No. 106628

Dear Mr. & Mrs. White:

In accordance with your request, on July 27, 2006 a Registered Engineer from this office of TLC Engineering for Architecture, Inc. (TLC) conducted limited visual observations of your residence located approximately 7 miles southwest of Lake City, Florida on State Route 47.

The purpose of this inspection was to observe existing structural conditions and gather information that would enable TLC to render an opinion concerning the condition of the construction work of the building addition to your residence. In addition to evaluating the condition of the work in-place, TLC was asked to review the construction documents prepared by Robert S. Taylor, Sr., Associated Florida Architects, Gainesville, Florida and Tamara G. Baker, P.E., Baker Engineering & Consulting, P.L., Jacksonville, Florida and render an opinion regarding the content of the construction documents. TLC's field visit and this report are not intended to cover hidden defects, hazardous materials, mechanical, electrical or architectural features.

GENERAL INFORMATION

Ed and Diane White are the owners of the residence constructed in 1966 by the father of Diane White. It was the desire of the White's to construct a large, 2-story, 3000 square foot building addition to the existing structure and hired Associated Florida Architects (AFA) to prepare the construction documents. The Whites gave AFA floor plan design sketches and building elevations as a general basis of their concept for the design. AFA prepared construction documents and submitted them to the Columbia County Building Authority for construction permit. A building permit was issued July 25, 2005. Isaac Construction Company, Lake City, Florida was hired by the Whites to construct the building addition. On December 13, 2005, Columbia County Building Authority issued a Stop Work Order and directed the structure be evaluated by a Florida Professional Engineer for compliance with Florida Building Code 2001. To date, no further construction work has been performed by Isaac Construction.

TLC was given copies of many of the construction documents prepared by AFA and Baker Engineering and Consulting, L.P., Jacksonville, Florida. The AFA permit drawings consisted of the following sheets dated May 9, 2005:

Cover	Index of drawings and Wind Load Design Parameters	
A1.01	Existing Floor Plan, Demolition Plan	
A2.01	First & Second Floor Plans	
A4.01	Exterior Building Elevations	
A6.01	Building Sections	
A7.01	Typical Wall Sections	
M1.01	Mechanical Plan First Floor, Mechanical Plan Second Floor	
E1.01	Electrical Plan First Floor, Electrical Plan Second Floor	
S1.01	Foundation Plan and Details	
S2.01	Roof Framing Plan: New Addition, Notes, Details	

Revised drawings dated July 21, 2005, identified as Addendum Number One:

A2.01	First & Second Floor Plans, Finish Schedules, Partial Stair Section, Wall Legend
A4.01	Exterior Building Elevations (4 Each)
S2.01	First & Second Floor Roof Framing Plans

Structural drawings prepared by Baker Engineering & Consulting Signed/Sealed May 23, 2005 for inclusion in Addendum Number One.

S-1	General Structural Notes
S-2	Framing Details

OBSERVATIONS

The following is a list of comments concerning the content of the construction documents:

- Construction drawings and details do not specify an adequate building lateral bracing system to resist Florida Building Code 2001, with 2003 Revisions Building Code (FBC) minimum specified Main Wind Force Pressures. The construction documents do not meet, in our professional opinion, the minimum standard of care for the building structural systems.
- Construction drawings and details do not specify adequate building foundations at building columns to resist FBC minimum specified Main Wind Force uplift pressures and gravity loads. The construction documents do not meet, in our professional opinion, the minimum standard of care for the building structural systems.
- Construction drawings and details do not, in our professional opinion, provide adequate fastening and anchoring of new wall sections and roof members to existing structure.



4. Construction drawings and details do not correctly portray the roof pitch of the existing building structure. The design of the building addition was based on faulty information and resulted in building elevations not consistent with as built conditions. The building elevations depicted in the construction drawings and the expectations of the Owners could not be achieved as represented by the drawings. The architect did not verify the as built conditions and developed a design not constructible as shown on the drawings. In our professional opinion, the construction drawings do not meet the minimum standard of care for professionally prepared construction documents.

The following is a list of observations made during the site investigation July 27, 2006:

- The high roof area is constructed without any evidence of a lateral bracing system to resist FBC main wind forces.
- Anchoring of the new wall on the west end of the existing building structure is structurally inadequate. No continuous load path to foundation for wind lateral and uplift loads is provided.
- Columns supporting the high roof structure, second floor loft area and the rear second floor deck structure are not as specified on the construction drawings. No column foundations were observed for these columns.
- 8. Extension of the side walls supporting the high roof structure is unconventional and does not provide continuous load path for wind uplift forces.
- Construction of cantilevered engineered wood beams supporting high roof structure is unconventionally framed. The framing does not provide continuous load path to the foundation for lateral and uplift wind forces.
- 10. Construction of the east wall supporting high roof structure was founded on the existing roof structure not competent to support the loads. Fastening of the new wall to the existing structure is structurally inadequate and provides no continuous load path to foundation for wind lateral and uplift forces.
- 11. Modification of high roof structure pre-engineered wood trusses is unconventional and structurally inadequate. The truss modifications appear to be absent of engineering input from the truss engineer.
- 12. The foundation slab on grade was observed to have minimum random cracks. No settlement of the foundation slab was observed. Verification of the foundation size and depth was not made.
- 13. Mono-pitched roof framing at the second floor loft area is unconventional framing and structurally inadequate. The beam splice/connection is on the verge of structural failure.



- 14. Construction of second floor deck framing is improperly framed to direct rain water away from the building interior.
- 15. Interior wood columns supporting the high roof structure are not the members specified on the construction documents and are inadequate to support the roof loads. The columns as constructed bear on the second floor sheathing and are not continuous members to the foundation level. The framing system is unconventional and not compliant with building code standards.
- 16. High roof trusses are not anchored by metal straps as specified in contract documents and are not in compliant with building code standards.
- 17. The exposed to weather wood framing materials are severely deteriorated and warped. The majority of the exposed framing must be replaced because of deterioration and sub-standard framing assemblies.

CONCLUSIONS

Based on our observations, we have the following comments:

- The construction documents do not, in our professional opinion, meet the standard of care for
 professionally prepared documents. The documents are incomplete, incorrect depiction of as
 built conditions and structurally inadequate to specify the contraction of the work in accordance
 with building code standards and accepted engineering standards.
- 2. The contractor proceeded with construction of the work prior to verification of as built conditions and specifically the roof slope. In our professional opinion, the work proceeded long after the roof slope discrepancy was discovered and framing alterations were initiated by the contractor to compensate for the roof slope discrepancy. Much of the framing alterations were made, in our professional opinion, in the absence of structural engineering consultations as evidenced by the large extent of unconventional framing observed. At the time of the Stop Work Order by Colombia County Building Authority, the as built configuration of the building addition did not resemble the building elevations shown in the construction documents.
- Construction of the work did not comply with the specified 6"x6" square wood structural columns
 and isolated concrete foundations shown on the construction documents for the high roof and
 rear deck structure. The columns constructed are not adequate to support the loads of the
 structure. The concrete foundations were not constructed.
- 4. Deterioration of the exposed to weather wood framing is severe and in our professional opinion, should be removed. The extent of the deterioration of the under roof structure framing is, in our professional opinion, minor to severe. However, the extent of unconventional framing and



absences of consistent load path through the structure to the foundation indicates the entire framing be removed from the site and reconstructed to building code standards.

5. Further investigation of the foundation slab on grade is recommended to verify if the foundation system as built is in accordance with building code standards. The existing slab was observed to be generally free of random cracking and a portion of the slab could be used if investigation proves the construction is acceptable. Although several isolated column foundations were not constructed, the foundations could be added to the existing slab on grade if deemed cost effective.

Our opinions are based upon engineering judgment to an extent normal for a field review of this type. We reserve the right to revise or amend our opinions if additional information becomes available in the future. Our review was walk-through in nature and we did not use any special tools or instruments were used for our observations. No material testing, intrusive investigations or structural analysis were made for preparation of this report.

This report is prepared for the sole benefit of Ed and Diane White. Unauthorized use of the information contained in this report without our permission shall result in no liability or legal exposure to TLC.

We appreciate this opportunity to be of service to you. If we can be of further assistance, please call me.

Very truly yours,

TLC ENGINEERING FOR ARCHITECTURE, INC.

David B. Griffith, PE

Principal/Senior Project Engineer

Roger L. Jeffery, P.E.

Principal/Structural Division Director

L:\2006-Jobs\106628 White Residence\Report letter.doc



From: The Columbia County Building Department
Plans Review
135 NE Hernando Av:
P. O Box 1529
Lake City Florida, 32056-1529

Dear Mr. Ed White

On December 13, 2005 per your request Mr. Randy Jones Assistant Building Official, Mr. Harry Dicks Building Inspector and I as the Plans Examiner accompanied you with a structural inspection of your resident at 7018 SW SR 47. The inspection pertains to Building permit number 23411 issued July 25, 2005 to ISAAC. This build permit was to construct an addition on to an existing single family dwelling. You requested that we inspect the structural framing which has been completed thus far for building code compliance. The Columbia County Building Department has several concerns which are:

1. Mr. Robert Taylor Architect, of Associated Florida Architects, Inc. 802 NW 23rd
Avenue Gainesville Florida, State of Florida Registration Number AR-0007526
filed a letter with the Columbia County Building Department on July 22, 2005
which stated that Associated Florida Architects, Inc. were the architects of record
for the construction of a addition on to your single family dwelling. Mr. Robert
Taylor in this letter also stated that certain structural issues which I as the plan
examiner had would be addressed once the construction of this addition was
started. Mr. Robert Taylor stated that within forty-five (45) days of commencing
with construction a written structural report addressing the needed issues would
be filed with the Columbia County Building Department. No reports have been

filed with the Columbia County Building Department by Mr. Taylor or Associated Florida Architects.

- 2. An example of one of the issues which was not addressed was the use of an exterior load bearing foundations and shear walls which was used to construct a second story load bearing wall without the contractor and the architect confirming that the foundation and the structural walls could safely support the additional structural load-bearing weight which has been applied to the foundation and walls for of a second story and a roof truss system.
- 3. The addition onto the structure of 3,044 square feet incorporated a first and second floor, using wood frame structural walls. Within the first floor several exterior and interior load bearing walls have been created to provide support for the second floor, flooring and roof truss system. Several first floor walls lack sufficient structural strength to properly support the second floor.
- The roof trusses have been modified by the contractor, the truss designer will be required to assess the trusses system to certify that the trusses system meet the original truss system design.

In order to continue work on this structure, a structural evaluation by a professional architect or engineer is needed to comply with the Florida Building Codes 2001. If you should have any additional question please contact me.

Thank you,

Joe Haltiwanger Plan Examiner

Columbia County Building Department



161 N.W. Madison St., Suite 102 Lake City, Florida 32055

> Tel: 386-758-4209 Fax: 386-758-4290

7/28/2006

Ed White P. O. Box 1376 Lake City, FL. 32056

Re: Structural Inspection

Dear Mr. White,

I have completed the structural inspection and have reviewed the original plans and the following evidence is evident:

The plans call for an exterior bearing wall height of 9'0". The exterior bearing walls were constructed at an 8'0" height. The ceiling height of the master bedroom is shown as a 9'0" ceiling height but was constructed as a 10'0" ceiling height. During construction the roof of the first floor interfered with the floor level of the second floor since the wall was constructed 1'0" too short and the floor level 1'0" too high. This caused a problem with floor joist layout as indicated on the plans. Since the floor joists interfered with the incorrectly placed roof system, the floor joists were altered so that they were no longer bearing on the walls as indicated on the plans. The plans did indicate structural load bearing walls to support the upper floor joist system, however, by shifting the bearing locations to new non-structural walls there was no provision for a structural foundation or structural headers. This could cause failure in the slab and wall components.

The two-story portion of the house was not constructed to the proper wall height as indicated on the plans. The original design called for a set of four (4) beams to run continuous from front to rear of the structure. The exterior walls were constructed in this manor to perform as a post and beam system. The beams are intended to span a certain distance and then bear on a post which has a structural footing directly underneath. The exterior walls on the two story portion were altered to bring the height up according to the original design. When this was done, the structural beam was removed in order to build a new knee wall above the original wall that was built too low.

This created two main problems. When the beam was removed, the post-beam structure became a continuous load-bearing wall. There is no interior structural footing to carry the load along the entire length of wall. When the knee wall was constructed to extend the

wall height per design, a hinge point was created in the wall. This could likely fail when wind pressure is applied to the wall.

A new wall was constructed on top of the original house. At this point, there is no evidence that the exterior wall is resting on anything structural. The weight of the wall and the roof trusses are only bearing on the existing roof decking and is showing signs of excessive deflection. The load-bearing wall needs to have a continuous load path from the foundation, up to the roof.

In order to solve the issues discussed above the structure would need to be dismantled. A redesign of the project should be accomplished taking into account the correct pitch of the existing roof. It should contain detail for the joining of the new and the old structure and foundation requirements to support changes in the correct plans. Because the structure could not be completed the trusses have now been exposed to the weather for nearly a year and have shown signs of twisting and buckling.

If you have any questions, you may contact me at (386) 758-4209.

Sincerely,

William Freeman, P.E.

Willest Freem

From:

The Columbia County Building Department

Plans Review

135 NE Hernando Av.

P. O Box 1529

Lake City Florida, 32056-1529

Dear Mr. Ed White

On December 13, 2005 per your request Mr. Randy Jones Assistant Building Official, Mr. Harry Dicks Building Inspector and I as the Plans Examiner accompanied you with a structural inspection of your resident at 7018 SW Kemp Court. The inspection pertains to Building permit number 23411 issued July 25, 2005 to ISAAC. A Build Permit to construction an addition on to an existing single family dwelling.

You requested that we inspect the structural framing which has been completed thus far for building code compliance. The Columbia County Building Department has several questions and concerns which are describer below.

1. Mr. Robert Taylor Architect, of Associated Florida Architects, Inc. 802 NW 23rd Avenue Gainesville Florida, State of Florida Registration Number AR-0007526 filed a letter (attached) with the Columbia County Building Department on July 22, 2005 which stated that Associated Florida Architects, Inc. were the architects of record for the construction of a addition on to your single family dwelling. Mr. Robert Taylor in this letter also stated that certain structural issues which I as the plan examiner had would be address once the construction of this addition was started. Also with this correspondence Mr. Robert Taylor confirmed that within forty-five (45) day/of commencing with construction a written report would be filed with the Columbia County Building Department to comply with the Florida Building Code 2001 Chapter thirty four (34) sections 3401.8.2.3.1, 3401.8.2.3.2

- and 3401.8.2.3.3 which are attached. As of this date these code requirements have not be fulfilled by Mr. Taylor
- 2. The north existing wall prior to construction was a shear wall for the single family dwelling, additional structural load-bearing weight has been applied to the foundation and wall by the contractor without confirming that the foundation and the structural wall could accommodate these structural loads for of a second story and a roof truss system. The building department questions the foundation integrity to have sufficient load bearing capacity to support the additional weight which has been applied to this foundation and wall. An engineering report will be required to be submitted to building department to state that the existing foundation and wall as modified complies with the Florida building code, as this code relates to foundation and wind-load design requirements for a structural wall of the height to which the wall has been constructed and all components of the wall will receive the required anchoring and strapping devices to comply with the wind-load design requirements.
- 3. The addition onto the structure of 3,044 square feet incorporated a first and second floor, with wood frame structural walls. Within the first floor several exterior and interior load bearing wall were created to provide support for the second floor, flooring system and roof trusses. Several of these first floor walls lack sufficient structural strength to properly support the second floor. An engineering review of these load bearing walls will be required to bring these walls into compliance with the Florida building code requirements for load bearing walls.

- 4. Several of the second story roof trusses have been modified by the builder, the engineered truss designer will be required to assess the trusses as modified to certify that these trusses still meet the original truss design.
- In order to continue work on this structure, a structural evaluation by a
 professional architect or engineer will be required to be preformed to meet the
 requirement of chapter 34 of the Florida Building Code sections 3401.8.2.3.1,
 3401.8.2.3.2 and 3401.8.2.3.3.

If you should have any question please contact me.

Thank you,

Joe Haltiwanger

Plan Examiner

Columbia County Building Department



associated florida architects, inc.

florida registration AA-C001907 802 nw 23rd avenue • gainesville, florida 32609-3534 352 375-3005 • 352 378-2523 • 352 375-5397 fax

July 22, 2005

Columbia County Building Department 135 NE Hernando Ave.

Lake City, FL 32055

Re: Ed & Diane Bishop-white Residence

To Whom It May Concern:

We are the architects for the referenced project. We have a full service contract with the owners including contract administration.

Due to the fact that this is an addition we will be able to do the discovery work on the existing residence when construction commences.

We will write a report with findings and recommendations within forty-five (45) days of start of construction. As per 3401.8.2.3.1, 3401.8.2.3.2 and 3401.8.2.3.3 of 2001 Florida Building Code.

Robert S. Taylor, Sr. Architect

Florida Registration AR-0007526

3401.8.1.2 The requirements of this section shall not supersede specific requirements of the code for construction in Fire Zones.

3401.8.2 Additions

3401.8.2.1 Any addition or alterations increasing the floor area of the building, shall meet the requirements of this section. For purposes of this section, whether an addition falls within the stated percentages shall be calculated based on the cumulative increase of the building during the course of one calendar year.

3401.8.2.2 All except Group R3 occupancies shall comply with the following:

3401.8.2.2.1 When additions, or alterations increasing floor area, are made to an existing building, and the addition and existing building are separated by a fire rated wall, as defined in Section 704, the addition shall conform to all the requirements of the code applicable to a building of the area of the addition.

3401.8.2.2.2 Where the existing building and the addition are not separated by a fire rated wall and the area of the addition is 25 percent or more of the area of the existing building, the existing building and the addition shall be made to comply with all requirements of the code for a building of area equal to the combined area for the addition and existing building.

3401.8.2.2.3 Where the existing building and the addition are not separated by a fire rated wall or where the addition is vertically superimposed on an existing building, and the area of the addition is less than 25 percent of the area of the existing building, the following requirements shall apply:

 The addition shall conform to all requirements of the code applicable to a building having the combined area and height of the existing

building and the addition.

The existing building shall conform to all requirements of the means of egress for a building of the combined area and height of the addition and the existing building.

 An approved detection, alarm and communications system, detecting products of combustion, shall be required for all public areas and means of egress within the existing building.

3401.8.2.3 Group R3 Occupancies shall comply with the following:

3401.8.2.3.1 When additions, or alterations increasing floor area, are made to an existing building and the addition constitutes 25 percent or more of the area of the existing building, the addition shall be made to comply with all the requirements of the code and the existing building shall comply with the following:

Impact resistance devices having a valid NOA shall be installed at openings to provide protection against storms.
 Corners of buildings of masonry construction

- 2. Corners of buildings of masonry construction shall be checked for tie downs. If tie downs are not found in corners, testing shall be performed to locate tie downs in all walls. Proper installation of tie downs shall be done at 20 foot intervals and at each corner except that interior tie downs may be provided in each side not less than 2 feet on each side of each corner.
 - 2.1 Tie down refers to the anchorage from the foundation to the tie beam and shall provide the equivalent strength of a vertical #5 reinforcing bar properly attached to the foundation and tie beam encased in concrete or mortar and lapped a minimum of 30 inches or otherwise spliced in a manner which will develop the full strength of the bar.

2.2 Alternate methods of providing anchorage of equivalent strength to that described in 2.1 may be used where design calculations which admit rational analysis are submitted by a Registered Engineer or Architect proficient in structural design.

- 3. Roof anchorage shall be checked at all walls where the addition connects to the existing building. If major deficiencies are found and the anchorage is not in compliance with the minimum requirements of the code, the roof anchorage shall be checked for all the existing roof. Minimum anchorage shall be provided to each member bearing on the exterior walls.
- 4. Permanent roof bracing shall be provided at all gable ends.
- G.F.C.I. outlets shall be installed where required by the code.
- Smoke detectors shall be installed where required by the code.

3401.8.2.3.2 The design professional shall conduct a site visit to ascertain the necessary work to be performed to comply with the requirements of this Section.

3401.8.2.3.3 The design professional shall provide an inspection report and indicate on the drawings all remedial actions to be performed on the building submittal as a part of the permit plans.

3401.8.3 Repairs and alterations

3401.8.3.1 Repairs and alterations not increasing the area of the building, made within any 12 month period, shall meet the requirements of this section.