



Cal-Tech Testing, Inc.

• Engineering P.O. Box 1625 • Lake City, FL 32057
• Geotechnical Tel. (386) 755-3633 • Fax (386) 752-5456
• Environmental 2907 Spring Glen Rd. Jacksonville, FL 32207
• Structural Steel Tel. (904) 381-8901 • Fax (904) 381-8902
LABORATORIES

REINFORCING STEEL INSPECTION

REPORT NO.: 2648001RSI07072026AB

DATE: 7/7/2026
PROJECT #: 26-480-01
PROJECT: FPL Columbia Storm Processing Facility P2
LOCATION: 1855 NW County Road 25A Lake City, FL
CAL-TECH P.M.: Chad Day

CLIENT: Florida Power & Light Company
CONTRACTOR: Pinnacle / Williams-Brown Inc.
INSPECTOR: Andrew Broughton
JURISDICTION: Columbia County/ Permit Number: 000055813
WEATHER: Clear TEMP: 94

Visual inspection was performed of reinforcing steel placement for footing construction located along Grid Lines B and C between Grid Lines 1.5 and 5. Inspection included observation of reinforcing steel size, quantity, spacing, configuration, support, and general placement in accordance with the approved project construction documents and applicable project details.

Reinforcing steel placement within the inspected areas was observed to be properly positioned, tied, and supported to maintain required placement. Based on conditions accessible and observed at the time of inspection, the reinforcing steel placement was found to be in accordance with the approved project documents and was acceptable.

Reviewed by: 

To the best of my knowledge, the above WAS performed in accordance with the approved plans. Specification and regulatory requirements.

Superintendent/Representative:

Technician:

X _____

X Andrew Broughton ICC#9947481



Pictures of Examination

Page 2 of 2



Picture 1: Reinforcing steel placement for footing construction within the inspected area along Grid Lines B and C between Grid Lines 1.5 and 5.



Picture 2: Field verification of reinforcing steel placement and elevation within the inspected footing area.



Picture 3: Field verification of #6 transverse bottom reinforcing steel spacing at approximately 10 inches on center within the inspected footing area.



Picture 4: Reinforcing steel placement, including continuous wall footing reinforcement and intersecting footing reinforcement within the inspected area.