Tree fell in left rear corner of house, damaging .
Some Trusses and fell on Panel Box, we repeired some trusses damaged by storm and replaced some with termite damage. We removed all sheetrack for wiring purpose and will prelice sheetrack after rough inspection. We repaired will prelice sheetrack after rough inspection. We repaired a few wells due to termites.

29

Framing
Painting
Drywall
Electrical
Wood Plooring

Warner J. Hori