



# Columbia County

## BUILDING DEPARTMENT

### Inspection Affidavit



Permit Number: 31672

I MaryCarol Johnson, licensed as a(n) Contractor\* /Engineer/Architect,  
(please print name and circle Lic Type) FS 468 Building Inspector\*

License #: CCC1330073 On or about 02-24-14,  
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal  
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 147 NW Zede Dr, Lake City FL 32055  
(Job Site Address)

Based upon that examination I have determined the installation was done according to the  
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Carol Johnson

Signature

STATE OF FLORIDA  
COUNTY OF

Sworn to and subscribed before me this 25 day of February, 2014

By L. A., Notary Public, State of Florida

(Print, type or stamp)



Personally known ☒ or

Produced Identification ☐ Type of identification produced. \_\_\_\_\_

\* Include photographs of each plane of the roof with the permit number  
clearly shown marked on the deck for each inspection. Place a tape  
measure next to the nailing pattern to show distance between nails.

\* Photographs must clearly show all work and have the permit number  
indicated on the roof.

\* Affidavit and Photographs must be provided when final inspection is  
requested.

\* Metal overlay & purlin installations shall have photographs of purlins  
or underlayment, whichever applies.