

ш

Z \Box

4 SOUTH,

CENTERLINE

AS PER A PLAT OF RECORD
AS PER A DEED OF RECORD
AS PER CALCULATIONS

PERMANENT CONTROL POINT PERMANENT REFERENCE MARKER AS PER FIELD MEASUREMENTS WOODEN FENCE CHAIN LINK FENCE WIRE FENCE ELECTRIC LINES

SECTION LINE



FIDELITY

CHADD A. BRINKLEY FIRST FEDERAL BANK ABSTRACT TRUST TITLE, LLC NATIDNAL TITLE INSURANCE

COMPANY

FIELD SURVEY DATE

12/09/2019

CERTIFIED TO

FIELD

BOOK

SEE

PAGE(S)

FILE

NOTE) UNLESS IT BEARS THE DRIGINAL SIGNATURE AND THE DRIGINAL RAISED SEAL OF A FLORIDA LICENSED SURVEYOR AND MAPPER THIS DRAWING, SKETCH, PLAT OR MAP IS FOR INFORMATIONAL PURPOSES ONLY AND IS NOT VALOR.

CERTIFICATION # 5757

I HEREBY CERTIFY THAT THIS SURVEY WAS MADE UNDER MY RESPONSIBLE CHARGE AND MEETS THE KINIMAM TECHNICAL STANDARDS AS SET FORTH BY THE FLORIDA BOARD OF PROFESSIONAL SURVEYORS AND MAPPERS IN CHAPTER 5.J-17, FLORIDA ADMINISTRATIVE CODE, PURSUANT TO SECTION 472027, FLORIDA STATUTES.

SURVEYOR'S CERTIFICATION

M MAPPING, SURVEYING

2086 SW MAIN BLVD, SUITE, 112, LAKE CITY, FLORIDA 32025 (386)752-7163 FAX (386)752-5573 WWW.brittsurvey.com WORK ORDER # L-**26230** LAND SURVEYORS AND MAPPERS, L.B. # 8016

CAROL CHADWICK P.E.

Giuil Gnyineex
1208 S.W. Fairfax Glen
Lake City, FL 32025
307.680.1772
ccpewyo@gmail.com
www.carolchadwickpe.com

December 14, 2019

Trent Giebeig
Trent Giebeig Construction, Inc.
trentgiebeigconstruction@gmail.com

re: ELEVATION LETTER INSPECTION - 26 | SW DEANNA TERRACE, LAKE CITY, FL

As requested, I inspected grading around the home at the above referenced site. A swale was graded between the street and the home to prevent direct precipitation runoff around the home to the southeast side of the lot. A swale was grading adjacent to the south property line to direct runoff east of the existing home to the south. The swale on the south side of the lot was sodded to prevent erosion. Please see the attached survey completed on December 9, 2019 by Britt Surveying & Mapping, LLC. The natural topography of the lot slopes to the southeast side of the home and continues southeast.

I certify that the grading will protect the new home and the existing home to the south from water damage from direct precipitation, as defined in Article 8 of the Land Development Regulations.

Should you have any questions, please don't hesitate to contact me.

Respectfully,



Carol Chadwick, P.E.

attachment: survey completed on December 9, 2019 by Bntt Surveying & Mapping, LLC

CC Job #FL19080

Final grading looking southeast





Final grading looking at the northeast corner of the new home





