Columbia County Building Permit Application

For Office Use Only Application # 0701-90 Date	Bankland 1-74-0704 (7 Barrell #	75455
	Plans Examiner	i i
Application Approved by - Zoning Official Dat Flood Zone Development Permit Zoni		· - ' - ' - ' - ' - ' - ' - ' - ' - ' -
	JAMAGE - NO Chable	
NOC WEH Deed or PA Site Plan S	itate Road Info Parent Parcel # De Fox 352-35	
Name Authorized Person Signing Permit Nathan	Ward Phone 352-35	
Address 224 NW 8th Ave, GAINESUL	les FL 37601	
Owners Name BRAD + JAN GURNEY	Phone 386-96	
	e. L.C. 32055 386-36	5-1/9/
Contractors Name ResTORATION Special	Phone <u>352-37</u>	6-0721
Address 224 N.W. 8 AVE GAINES	Will, FL, 3260)	:
Fee Simple Owner Name & Address NA		· · · · · · · · · · · · · · · · · · ·
Bonding Co. Name & Address N/A		بست کشمندی فرود این به دارا این به دارا
Architect/Engineer Name & Address N(4		
Mortgage Lenders Name & AddressNA		
Circle the correct power company - FL Power & Light - Ci	lay Elec. – Suwannee Valley Elec. ~ P	rogressive Energy
Property ID Number 23-35-16-02270-011		
Subdivision Name Johns Place @ Woodbo		
Driving Directions 979-2644		And his of the other common payments.
Type of Construction <u>REPAIR home</u>		
Type of Construction	ulvert Permit or Culvert Waiver or Hav	e an Existing Drive
Type of Construction <u>REPAIR DEMP</u> Total Acreage <u>219</u> Lot Size Do you need a - <u>C</u> Actual Distance of Structure from Property Lines - Front	ulvert Permit or <u>Culvert Walver</u> or <u>Hav</u>	e an Existing Drive _ Rear
Type of ConstructionROPAIR	ulvert Permit or <u>Culvert Walver</u> or <u>Hav</u> Side Side Roof Heated Floor Area Roof	e an Existing Drive Rear Pitch
Type of Construction	ulvert Permit or Culvert Waiver or Hav Side Side Roof Heated Floor Area Roof i installations as indicated. I certify that and that all work be performed to meet	e an Existing Drive Rear Plich no work or the standards of
Type of Construction	ulvert Permit or Culvert Waiver or Have Side Side Roof Roof Installations as Indicated. I certify that and that all work be performed to meet iformation is accurate and all work will be ion and zoning.	e an Existing Drive Rear Pitch no work or the standards of
Type of Construction	ulvert Permit or Culvert Walver or Have Side Side Roof Heated Floor Area Roof I Installations as Indicated. I certify that and that all work be performed to meet formation is accurate and all work will be ion and zoning. CE OF COMMENCMENT MAY RESULT II INTEND TO QUARTER INANCING, CONS	e an Existing Drive Rear Pitch no work or the standards of the done in N YOU PAYING
Type of Construction	Livert Permit or Culvert Waiver or Have Side Side Roof Roof Roof Roof Roof Roof Roof Roo	e an Existing Drive Rear Pitch no work or the standards of the standards of the work of the standards of
Type of Construction	Livert Permit or Culvert Waiver or Have Side Side Roof Roof Roof Roof Roof Roof Roof Roo	e an Existing Drive Rear Pitch no work or the standards of the Standard
Type of Construction	Livert Permit or Culvert Waiver or Have Side Side Roof Roof Roof Roof Roof Roof Roof Roo	e an Existing Drive Rear Pitch no work or the standards of the standard
Type of Construction	Livert Permit or Culvert Waiver or Have Side Side Roof Roof Roof Roof Roof Roof Roof Roo	Rear Plich no work of the standards of t
Type of Construction	Livert Permit or Culvert Waiver or Have Side Side Roof Roof Roof Roof Roof Roof Roof Roo	Rear

@ CAM112M01 S CamaUSA Appraisal System 1/24/2007 14:43 Legal Description Maintenance Year T Property Sel 2007 R 23-3S-16-02270-011 268 SCENIC LAKE DR NW LAKE CITY HX GURNEY JAN & BRAD	66937 323085 8080 398102	lumbia County Land 001 * AG 000 Bldg 001 Xfea 002 TOTAL B*
1 LOT 1 JOHNS PLACE AT WOODBOROUGH. 979-2644		, 2 4
3		'
5		' 8
7		10
9		່ 12
11		' 1 <i>4</i>
13		16
15		1 Ω
17,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		່່ 20
19		່່ 22
21		' ' 24
23		26
25		28
27		
Mnt 8/19/2 F1=Task F3=Exit F4=Prompt F10=GoTo PgUp/PgDn F24=More	003 0222	

44 N.W. 9th Street Ocala, Fl 34475 (352) 732-2322 224 N.W. 8th Avenue Gainesville, Fl 32601 (352) 376-

0721

36 W. Gulf to Lake Hwy Lecanto, Fl 34461 (352) 746-4878

Toll-free (888) 214-2322 CGC042165 CCC056803 Federal Tax ID #: 593626928 01/08/2007

Estimate:

GURNEY_BRAD

Claim Number:

59-X524-601

Insured:

GURNEY, BRAD

Policy Number:

80-PN-7825-5

Property:

268 NW SCENIC LAKE DR

Type of Loss:

Wind

LAKE CITY, FL 32055-8579

\$2,000.00

Home:

(386) 961-8569

Deductible:

FLGA2F6D1

Business:

(386) 365-7191

Price List:

Restoration/Service/Remodel F = Factored In, D = Do Not Apply

Date of Loss:

12/25/2006

Date Inspected:

12/26/2006

Summary for Wind

Line Item Total Material Sales Tax	@	6.250% x	2,789.32	8,149.77 174.33
Replacement Cost Value Less Depreciation			_	8,324.10 (0.00)
Actual Cash Value (ACV) Overhead	@	10.0% x	8,324.10	8,324.10 832.41
Profit	@	10.0% x	8,324.10	832.41
Actual Cash Value (Includ Less Deductible Less agreed value of salva		•		9,988.92 (2,000.00) (0.00)
Net Actual Cash Value Pa	yment			\$7,988.92

JUDY RENN

ALL AMOUNTS PAYABLE ARE SUBJECT TO THE TERMS, CONDITIONS AND LIMITS OF YOUR POLICY.

THIS IS A PRELIMINARY ESTIMATE ONLY. THE EXTENT OF ROOFING REPAIRS HAS NOT BEEN DECIDED AT THIS TIME AND THE FENCING AND IRRIGATION SYSTEM REPAIRS ARE OPEN, AWAITING EVALUATION AND BIDS FROM SUB-CONTRACTORS.

WE ARE SHOWING TO MAKE REPAIRS OF DAMAGE TO THE HOME CAUSED BY A TORNADO. THE AFFECTED

44 N.W. 9th Street Ocala, Fl 34475 (352) 732-2322 224 N.W. 8th Avenue Gainesville, Fl 32601 (352) 376-0721

36 W. Gulf to Lake Hwy Lecanto, Fl 34461 (352) 746-4878

Toll-free (888) 214-2322 CGC042165 CCC056803 Federal Tax ID #: 593626928 01/08/2007

AREAS INCLUDE THE NW BEDROOM, MASTER BEDROOM, AND GREAT ROOM INSIDE. ON THE EXTERIOR, SOFFITS, FASCIA, GUTTERS, SIDING, FENCING, AND THE ROOF WAS DAMAGED. IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT ME AT (352) 359-6246.

MIKE MITCHELL

Replace Roof; 4 pcs OSB (damaged) 48 Sqs. of shings 25 Rolls of 3DIb Felt NAILS.


CONTRACTOR AND MATERIALS SUPPLIER WARRANTIES UNDER STATE FARM PREMIER SERVICE® Under the State Farm Premier Service® program (SFPSP), the State Farm insured is provided by the Contractor and Materials Supplier identified below, with the following warranties on repairs for covered damage to a dwelling insured under State Farm's insurance policy: The Contractor identified on this estimate warrants for a period of five (5) years from the date of the insured's authorization to pay, that all workmanship of the Contractor and the subcontractors working of the Contractor and the subcontractor and the subcontractor and the subcontractor and the subcontractor and the subco	
Under the State Farm Premier Service® program (SFPSP), the State Farm insured is provided by the Contractor and Materials Supplier identified below, with the following warranties on repairs for covered damage to a dwelling insured under State Farm's insurance policy: The Contractor identified on this estimate warrants for a period of five (5) years from the date of the	
Under the State Farm Premier Service® program (SFPSP), the State Farm insured is provided by the Contractor and Materials Supplier identified below, with the following warranties on repairs for covered damage to a dwelling insured under State Farm's insurance policy: The Contractor identified on this estimate warrants for a period of five (5) years from the date of the	
Contractor and Materials Supplier identified below, with the following warranties on repairs for covered damage to a dwelling insured under State Farm's insurance policy: The Contractor identified on this estimate warrants for a period of five (5) years from the date of the	
Contractor and Materials Supplier identified below, with the following warranties on repairs for covered damage to a dwelling insured under State Farm's insurance policy: The Contractor identified on this estimate warrants for a period of five (5) years from the date of the	
damage to a dwelling insured under State Farm's insurance policy: The Contractor identified on this estimate warrants for a period of five (5) years from the date of the	
The Contractor identified on this estimate warrants for a period of five (5) years from the date of the	:d
•	
insured's authorization to pay, that all workmanship of the Contractor and the subcontractors working	
	on
the above repairs (1) will be performed in accordance with this estimate and any construction agreeme	nt
with the insured, and (2) will be of good quality and free from any fault or defect. This warranty exclusion	des
damage caused by normal wear and tear, improper maintenance, and/or abuse. Any Materials Supplie	r
participating in SFPSP warrants that all materials and equipment furnished by it in the above repairs at	·e
covered by the manufacturers' warranties. The Contractor also warrants for a period of one year from	the
date of the insured's authorization to pay, that all materials and equipment furnished by it or the	
subcontractors in the above repairs will be new, of good quality, and free of defects. This warranty is	
limited to visible defects for materials and equipment furnished in the above repairs to the Contractor	эy
any Materials Supplier participating in SFPSP. Please contact your Contractor or State Farm for the n	ame
of the participating Materials Supplier and the item it furnished in the above repairs.	
Insured Name:	
insured Name.	
Repair Property Address:	
Contractor Signature:	

Phone Number:

01/08/2007

GURNEY_BRAD


Main Level



Room: NW	BEDROOM
----------	---------

Ceiling Height: 9'

-				
	470.99	SF Walls	170.33	SF Ceiling
	641.32	SF Walls & Ceiling	170.33	SF Floor
	18.93	SY Flooring	52.33	LF Floor Perimeter
	52.33	LF Ceil. Perimeter		



Subroom 1: CLOSET

75.00 LF

4.00 SF

674.99 SF

Ceiling Height: 9'

204.00 SF Walls	27.42 SF Ceiling
231.42 SF Walls & Ceiling	27.42 SF Floor
3.05 SY Flooring	22.67 LF Floor Perimeter
22.67 LF Ceil. Perimeter	

61.50

1.40

418.49

967.74

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Mask or cover per square foot	197.74 SF	0.29	57.34		57.34
THIS IS TO PROTECT THE FLOOI DRYWALL REPAIRS MADE.	NG WHILE THE	WINDOW IS BEING	REMOVED AND	REPLACED AND	
R&R Aluminum window, single hung 13-19 sf (2 pane w/thermal)	1.00 EA	301.93	301.93		301.93
Add for grid (double or triple glazed windows)	1.00 SF	1.69	1.69		1.69
Drywall patch, ready for paint	1.00 EA	52.89	52.89		52.89
THIS IS TO PATCH THE DRYWAI THIS LINE ITEM STATES THAT I' ITEM IS FOR MATCHING THE TE	T DOES NOT COV	WINDOW THAT IS I ER THE TIME NEED	BEING REPLACE DED TO MATCH T	D. THE DESCRIPT EXTURE. THE N	TION OF EXT LINE
Drywall Installer / Finisher - per hour	1.00 HR	72.50 D	72.50		72.50
THIS IS TO MATCH THE TEXTUR	E OF THE WALLS	SURROUNDING TH	HE WINDOW.		

0.82

0.35

0.62

GURN	ΕV	BRA	ח
UUUU	CI	DKA	۱IJ

Mask and prep for paint

Paint the walls - two coats

coat

Seal/prime the surface area - one

Room Totals: NW BEDROOM

61.50

1.40


418.49

967.74

0.00

GURNEY, BRAD

01/08/2007




Room: MSTRBDRM

Ceiling Height: Tray

436.18 SF Walls 744.63 SF Walls & Ceiling 28.91 SY Flooring 48.46 LF Ceil. Perimeter

260.16 SF Floor 48.46 LF Floor Perimeter

308.45 SF Ceiling



Subroom 1: OFFSET

Ceiling Height: 9'

94.50 SF Walls 107.73 SF Walls & Ceiling 1.47 SY Flooring 10.50 LF Ceil. Perimeter

13.23 SF Ceiling

13.23 SF Floor


10.50 LF Floor Perimeter

Missing Wall:

4'8" X 9'0"

Opens into MSTRBDRM

Goes to Floor/Ceiling



Subroom 2: BAY

Ceiling Height: 9'

122.24 SF Walls 143.59 SF Walls & Ceiling 2.37 SY Flooring 13.58 LF Ceil. Perimeter

21.35 SF Ceiling 21.35 SF Floor

13.58 LF Floor Perimeter

Missing Wall: 1	l -	11'0" X 9'0"	Opens into	MSTRBDRM	Goes to Floor/Cei	ling
DESCRIPTION		QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Reglaze double-pane thermal window unit, 10 - 16 sf		1.00 EA	183.30	183.30		183.30
Add for grid (double or triple glazed windows)		1.00 SF	1.69	1.69		1.69
R&R Window screen, 10 - 16 st	f	1.00 EA	23.25	23.25		23.25
Room Totals: MSTRBDRM				208.24	0.00	208.24

THE COLUMN ASSESSMENT OF THE COLUMN ASSESSMENT	Roo	m: GREAT ROOM			Ceiling	Height: Tray
	60 125	527.50	SF Walls		424.67 SF Ceiling	
		952.17	SF Walls & Ceiling	5	364.04 SF Floor	
1. P. C.		40.45	SY Flooring		56.67 LF Floor Per	rimeter
+		68.67	LF Ceil. Perimeter			
Missing Wall:	1 -	4'4" X 9'0"	Opens into	KITCHEN	Goes to Floor/Ce	iling
Missing Wall:	1 -	3'0" X 7'10"	Opens into		Goes to Floor	J
Missing Wall:	1 -	6'0" X 7'10"	Opens into	FOYER	Goes to Floor	
Missing Wall:	1 -	3'0" X 6'8"	Opens into	WEST HALL	Goes to Floor	
Missing Wall:	1 -	4'0" X 9'0"	Opens into	BRKFAST	Goes to Floor/Ce	iling
DESCRIPTION	a.	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Content Manipulation charge hour	- per	4.00 HR	23.69 D	94.76		94.76
THIS IS FOR TWO MEN FOR REPAIRS, AND THEN AGA	OR TV	VO HOURS EACH TO OR PAINTING.	O MOVE AND RE	PLACE THE CON	TENTS FOR DRYW	ALL
Detach & Reset Crown mold oversized - 4 1/4" MDF - w/o	letail	30.33 LF	2.31	70.06		70.06
THIS CROWN WILL HAVE	E TO E	BE REMOVED TO A	LLOW FOR THE (CEILING DRYWA	LL REPAIRS.	
R&R Blown-in insulation - 1 depth - R26		64.00 SF	1.26	80.64		80.64
THIS INSULATION IS BEL	I WO.	HE WORST ROOF L	EAK AND WILL	NEED TO BE REP	PLACED.	
Mask or cover per square for	ot	533.04 SF	0.29	154.58		154.5
THIS IS TO COVER AND I DRYWALL DUST IN THE	PROTE OTHE	ECT THE FLOORS, C TR AREAS OF THE H	CONTENTS, AND COME.	OPENINGS TO OT	THER ROOMS TO N	MINIMIZE
R&R 5/8" drywall - hung, tag heavy texture, ready for pain		64.00 SF	2.55	163.20		163.20
Texture drywall - heavy hand texture	i	64.00 SF	0.66	42.24		42.2
THIS IS FOR EXTRA SQU. "FEATHER-IN" THE REPA	ARE F JRS T	OOTAGE AROUND O BLEND WITH TH	THE REPLACEM E EXISTING TEX	ENT AREA WHEI FURE.	RE WE WILL HAVE	TO
Mask and prep for paint		68.67 LF	0.82	56.31		56.3
WE WILL NOT BE ABLE TO CENTRAL PART OF THE TREQUIRED 48 HOURS, THE WOULD NOT BE ACCESS	HOUS IE CH	E AND IF LEFT IN P ILDREN'S BEDROOI	LACE WHILE TH MS AND BATHRO	IE DRYWALL TE OOM ON THE WE	XTURE CURES FOR	R THE
Seal/prime the surface area - coat		133.00 SF	0.35	46.55		46.5
THIS IS TO SEAL THE CE WATER SPOTS HAVE SHO			R AREA AND TO	SPOT SEAL SEVE	RAL SMALL AREA	S WHERE
Paint crown molding, oversize two coats		60.67 LF	0.98	59.46		59.4
THIS IS FOR THE TWO PITTWO ADJOINING PIECES				FOR CEILING R	EPAIRS AND THE	OTHER
Paint the ceiling - two coats		424.67 SF	0.62	263.30		263.3

01/08/2007

CONTINUED - GREAT ROOM

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Room Totals: GREAT ROOM			1,031.10	0.00	1,031.10

7,2	= 1 = 1	
3.4.2		
7	2, -1 -1 2 3 42	


Room: KITCHEN

296.51 SF Walls
455.95 SF Walls & Ceiling
159.43 SF Ceiling
159.43 SF Floor
17.71 SY Flooring
32.94 LF Floor Perimeter
32.94 LF Ceil. Perimeter

Missing Wall: 1 -12'6" X 9'0" Opens into BRKFAST Goes to Floor/Ceiling Missing Wall: 4'4" X 9'0" 1 -Opens into GREAT ROOM Goes to Floor/Ceiling **DESCRIPTION QUANTITY UNIT COST RCV** DEPREC. ACV Mask and prep for paint 27.01 32.94 LF 0.82 27.01 Seal/prime the surface area - one 4.00 SF 0.35 1.40 1.40 THIS IS TO SPOT SEAL SEVERAL SMALL AREAS WHERE WATER SPOTS HAVE SHOWN UP.

Paint the ceiling - two coats 159.43 SF 0.62 98.85 98.85

Room Totals: KITCHEN 127.26 0.00 127.26



Missing Wall: 1 - Missing Wall: 1 -		12'6" X 9'0" 4'0" X 9'0"	Opens into KITCHEN Opens into GREAT ROOM		Goes to Floor/Ceiling Goes to Floor/Ceiling	
DESCRIPTION		QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Content Manipulation charge hour	e - per	2.00 HR	23.69 D	47.38		47.38

GURNEY_BRAD

Page: 7

01/08/2007

CONTINUED - BRKFAST

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
THIS IS FOR TWO MEN FOR ONE	HOUR EACH TO	MOVE AND REPLA	CE THE CONTE	NTS FOR PAINTING	i.
Mask and prep for paint	32.33 LF	0.82	26.51		26.51
Seal/prime the surface area - one coat	4.00 SF	0.35	1.40		1.40
THIS IS TO SPOT SEAL SEVERAL	L SMALL AREAS	WHERE WATER SPO	OTS HAVE SHO	WN UP.	
Paint the ceiling - two coats	148.67 SF	0.62	92.18		92.18
Room Totals: BRKFAST			167.47	0.00	167.47

Exterior

Area	Items:	Exterior
------	--------	----------

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
Mason - Brick / Stone - per hour	16.00 HR	38.76 D	620.16		620.16
THIS IS LABOR ONLY FOR A MAS SURROUNDING THE BROKEN WI REMOVED AND THEN WOVEN BA AND IT IS POSSIBLE THAT SOME NOTIFY THE ADJUSTOR AND MA	NDOW IN THE N ACK INTO THE S BRICKS WILL B	W BEDROOM. THE URROUNDING BRC E BROKEN EVEN US	SE BRICKS WILL KWORK. THIS IS SING THE UTMOS	HAVE TO BE CA VERY LABOR 🗈	NTENSIVE
R&R Soffit - metal	75.00 SF	2.93	219.75		219.75
IT WILL TAKE AT LEAST SIX 12' 6 DAMAGED AREAS AROUND THE		FFIT MATERIAL TO	MAKE REPAIRS	TO THE VARIOU	S
R&R Fascia - metal, 6"	84.00 LF	2.82	236.88		236.88
IT WILL TAKE AT LEAST SEVEN AROUND THE HOME.	12' PIECES OF FA	ASCIA TO MAKE RE	PAIRS TO THE VA	ARIOUS DAMAG	ED AREAS
Detach & Reset Fascia - metal, 6"	72.00 LF	1.52	109.44		109.44
THIS IS TO DETACH AND RESET S REPLACEMENT.	SOME OF THE FA	ASCIA AS NEEDED 1	TO ALLOW ACCE	SS FOR SOFFIT	
(Install) Fascia - metal, 6"	48.00 LF	1.51	72.48		72.48
THIS IS TO RE-ATTACH FOUR 12' WILL NOT REQUIRE REPLACEME		ASCIA THAT ARE B	LOWN LOOSE AT	VARIOUS AREA	AS, BUT
Detach & Reset Gutter / downspout - aluminum - 6"	12.00 LF	2.02	24.24		24.24
THIS WILL HAVE TO BE DETACH REPAIRS ON THE SOUTH SIDE OF		TO ALLOW FOR CL	EARANCE FOR FA	ASCIA AND SOF	FIT
R&R Gutter / downspout - aluminum - 6"	44.00 LF	6.40	281.60		281.60
THIS IS TO REPLACE DAMAGED WEST ENDS OF THE HOME.	GUTTER, DOWN	SPOUTS, AND DOW	'NSPOUT EXTENS	SIONS ON THE E	AST AND

01/08/2007

GURNEY, BRAD

CONTINUED - Exterior

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
R&R Siding - hardboard - lap pattern - 6" or 8"	12.00 SF	3.65	43.80		43.80
THIS IS TO REPLACE THE DAMA HOME.	GED SIDING ON	THE GABLE ON TH	IE WEST END OF	THE SOUTH SID	E OF THE
Seal/prime the surface area - one coat	12.00 SF	0.35	4.20		4.20
THIS IS TO SEAL/PRIME THE NEV	W SIDING ON TH	E GABLE.			
Paint the surface area - two coats	57.75 SF	0.62	35.81		35.81
THIS IS TO PAINT THE GABLE W	HERE REPAIRS	WERE MADE.			
Paint trim - 1 coat	43.33 LF	0.61	26.43		26.43
THIS IS TO PAINT (TWO COATS)	THE 4" TRIM BO	ARDS ON THE GAI	BLE WHERE REPA	IRS WERE MAD	Œ
Painter - per hour	1.00 HR	51.18 D	51.18		51.18
THIS IS FOR A PAINTER TO GO A	ROUND THE HO	ME AND TOUCH-U	IP THE SOFFIT AN	ID FASCIA.	
R&R Vinyl (PVC) fence, 3'- 4' high - installed	0.00 LF				OPEN-BID
THE EXTENT OF THE NEEDED FITTHE INVISIBLE FENCING.	ENCING REPAIR	S IS STILL OPEN. 7	THERE WILL ALSO	O BE REPAIRS N	EEDED TO
PLUMBING - Irrigation system repairs	1.00 EA				OPEN-BID
Area Items Total: Exterior		74	1,725.97	0.00	1,725.97


take tree page and the tree	Room: PORCH, F.O. 520.36 SF Walls			Ceiling Height: 10			
2.00				3	333.33 SF Ceiling		
*		853.69	SF Walls & Ceiling	3	33.33 SF Floor		
•		37.04	SY Flooring		43.33 LF Floor Per	imeter	
			LF Ceil. Perimeter				
Missing Wall:	1 -	33'4" X 10'0"	Opens into E		Goes to Floor/Cei	ling	
Missing Wall:	1 -	10'2" X 10'0"	Opens into E		Goes to Floor/Cei	ling	
DESCRIPTION		QUANTITY	UNIT COST	RCV	DEPREC.	ACV	
R&R Soffit - vinyl		25.00 SF	3.14	78.50		78.50	
THIS IS TO REPLACE TW	/O 9' PI	ECES.					
Detach & Reset Soffit - vin	v1	117.00 SF	1.36	159.12		159.12	

Page: 9

01/08/2007

CONTINUED - PORCH, F.O.

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
THIS IS TO DETACH AND RESET THAT WERE DAMAGED CAN BE	A PORTION OF TERPLACED.	THE SOFFIT SO THA	T TWO 12' 6" SE	CTIONS OF J-CHA	NNEL
Finish Carpenter - per hour	1.00 HR	57.26 D	57.26		57.26
THIS IS FOR A CARPENTER TO I	MAKE MINOR TO	UCH-UP REPAIRS TO	THE COLUMN	IS.	
Paint the surface area - two coats	243.54 SF	0.62	150.99		150.99
THIS IS TO PAINT THE COLUMN TOUCH-UP REPAIRS.	IS AND THE WOO	DWORK ADJOINING	THE COLUMN	IS FOLLOWING MI	NOR
Room Totals: PORCH, F.O.			445.87	0.00	445.87



Room: BBQ PORCH	Ceiling Height: 8' 10"
	······································
272 17 CE W-U-	100 04 OF C 11'

372.17 SF Walls 189.84 SF Ceiling 562.01 SF Walls & Ceiling 189.84 SF Floor 21.09 SY Flooring 56.83 LF Floor Perimeter 36.33 LF Ceil. Perimeter

Missing Wall:	1 -	3'4" X 6'4"	Opens into E	Goes to Ceiling
Missing Wall:	1 -	17'2" X 6'4"	Opens into E	Goes to Ceiling

DESCRIPTION	QUANTITY	UNIT COST	RCV	DEPREC.	ACV
R&R Patio/pool Enclosure - Half Screen	131.94 SF	9.17	1,209.89		1,209.89
R&R Patio Cover - Attached - Aluminum - Heavy Load	76.50 SF	15.01	1,148.27		1,148.27
Room Totals: BBQ PORCH			2,358.16	0.00	2,358.16

Room Totals: BBQ PORCH	2,358.16	0.00	2,358.16
Room Totals: DDQ TORCII	2,358.10	0.00	2,358.10


Area	Total	ls: E	xterior
------	-------	-------	---------

892.56 SF Walls	523.17 SF Ceiling	1,415.72 SF Walls and Ceiling
523.17 SF Floor	58.13 SY Flooring	100.17 LF Floor Perimeter
		79.67 LF Ceil. Perimeter

Area Items Total: Exterior 4,530.00 4,530.00 0.00

01/08/2007

Room: Roof



DESCRIPTION

QUANTITY

UNIT COST

RCV

DEPREC.

ACV

*************<u>NOTE</u>**********

THE EXTENT OF ROOFING REPAIRS IS STILL UNDECIDED AT THIS TIME. THIS ESTIMATE WILL BE CORRECTED WHEN WE ARE NOTIFIED BY STATE FARM OF THE AMOUNT OF ROOF REPLACEMENT BEING AUTHORIZED.


Room Totals: Roof

0.00

0.00

0.00

Room: General



DESCRIPTION

Single axle dump truck - per load -

QUANTITY

UNIT COST

RCV

DEPREC.

ACV

including dump fees

2.00 EA

151.84 D

303.68

303.68

WE WILL NOT BE ABLE TO SET A DUMPSTER AT THIS SITE SINCE THE LAWN IS VERY SOFT AND THERE IS AN UNDERGROUND IRRIGATION SYSTEM. THIS LINE ITEM IS FOR A DUAL AXLE, PULL-BEHIND, DUMP TRAILER WITH THE SAME VOLUME CAPACITY AS A DUMP TRUCK.

Taxes, insurance, permits & fees (Bid item)

1.00 EA

OPEN


Room Totals: General

303.68

0.00

303.68

Room: photos



URNEY, BRA	D	RESTOR	RATION SPECIALIS	STS		01/08/200
DESCRIPTIO		UANTITY	UNIT COST	RCV	DEPREC.	01/08/200 ACV
************ THIS IS A VE	*****NOTE*******************************	*** THE PHOTO	S AVAILABLE, BUT UP	LOADING MO	RE THAN THIS	CAUSES
Room Totals:	photos			0.00	0.00	0.00
Area Totals: N	Main Level					
8,7	755.91 SF Walls	3,	493.32 SF Ceiling	12,2	249.23 SF Walls a	nd Ceiling
3,4	419.35 SF Floor		379.93 SY Flooring	Ġ	925.19 LF Floor P	erimeter
				-	972.97 LF Ceil. Po	
	419.35 Floor Area 035.83 Exterior Wall Area		606.45 Total Area 272.54 Exterior Perimeter of Walls	_	873.81 Interior Wa	all Area
Area Items To	otal: Main Level			7,335.49	0.00	7,335.49
Line Item Sub	ototals: GURNEY_BRAD)		7,335.49	0.00	7,335.49
Adjustments 1	for Base Service Charges					Adjustmen
Carpenter - Fin	nish, Trim/Cabinet					114.5
Carpenter - M	echanic					107.0
Drywall Instal	ler/Finisher					290.0
Insulation Inst	aller					100.5
Painter						102.3
Siding Installe	er					99.8
Total Adjustm	ents for Base Service Charg	ges:				814.2
Line Item Tot	tals: GURNEY_BRAD			8,149.77	0.00	8,149.7
Grand Tota	al Arage					
	SF Walls	3 403 32	SF Ceiling	12 240 23	SF Walls and Ce	iling
	SF Floor	•	SY Flooring	-	LF Floor Perime	_
	SF Long Wall		SF Short Wall		LF Ceil. Perimet	
3,419.35	Floor Area	3,606.45	Total Area	8,873.81	Interior Wall Ar	ea
2,035.83	Exterior Wall Area	272.54	Exterior Perimeter of Walls			
	Surface Area		Number of Squares	0.00	Total Perimeter	Length
0.00	Total Ridge Length	0.00	Total Hip Length			
URNEY_BR	AD					Page: 12

Trade Summary

O&P Items			Total Dollars	%
AWNINGS & PATIO COVER	S		2,358.16	23.61%
CONTENT MANIPULATION			142.14	1.42%
GENERAL DEMOLITION			515.60	5.16%
DRYWALL			330.83	3.31%
FINISH CARPENTRY / TRIM	IWORK		127.32	1.27%
INSULATION			80,64	0.81%
MASONRY			620.16	6.21%
PAINTING			1,422.97	14.25%
SIDING			43.80	0.44%
SOFFIT, FASCIA, & GUTTER		1,182.01	11.83%	
WINDOWS - ALUMINUM		303.62	3.04%	
WINDOW REGLAZING & REPAIR		208.24	2.08%	
Subtotal			7,335.49	73.44%
Base Service Charges			814.28	8.15%
Material Sales Tax	@	6.250%	174.33	1.75%
Overhead	@	10.00%	832.41	8.33%
Profit	@	10.00%	832.41	8.33%
O&P Items Subtotal			9,988.92	100.00%
Less Deductible			(2000.00)	
Grand Total			7,988.92	

Structural Damage Claim Policy

When you have a covered structural damage claim to your real property, you should know:

- We want you to receive quality repair work to restore the damages to your property.
- We will provide you with a detailed estimate of the scope of damage and costs of repairs. Should the contractor you select have questions concerning our estimate, they should contact your claim representative directly.
- You may have the repairs made by a contractor of your choice.
- If you select a contractor whose estimate is the same as or lower than our estimate, based on the same scope of damages, we will pay based upon their estimate. If your contractor's estimate is higher than ours, you should contact your claim representative prior to beginning the repairs.
- State Farm cannot authorize any contractor to proceed with work on your property. Repairs should proceed only with your authorization.
- State Farm does not guarantee the quality of workmanship of any contractor or guarantee that the work will be accomplished within any specific time frame.
- It is understood that the contractor is hired by you, our insured, and that they work for you not State Farm.

Main Level

GURNEY, BRAD

01/08/2007

GURNEY, BRAD