



requested.

or underlayment, whichever applies.

Columbia County BUILDING DEPARTMENT Inspection Affidavit

Engle.

Permit Number: 31917
I NO RECO , licensed as a(n) Contractor* /Engineer/Architect, (please print name indexcel is Type) FS 468 Building Inspector*
License #: $\frac{CCC1330117}{\text{did personally inspect the}}$ On or about $\frac{6414}{\text{(Dute & time)}}$
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection work at 248 SF- Faun DR L.C. H
Based upon that examination I have determined the installation was done according to the
Hurficanc Mitigation Retrofit Manual (Based on 553.844 F.S.) On Cell Signature 6-
STATE OF FLORIDA COUNTY OF Sworm to and subscribed before me this 5 day of 201
By MA JULISE DI DO Motary Public, State of Florida The State of Florida The State of Florida
Personally known or Produced Identification The action and a standard part of the produced and the produced
* Include photographs of each plane of the roof white permits michan holary asso clearly shown marked on the deck for each inspection places are next to the nailing pattern to show distance between nails.
* Photographs must clearly show all work and have the permit number indicated on the roof

* Affidavit and Photographs must be provided when final inspection is

* Metal overlay & purlin installations shall have photographs of purlins