# Property Inspection Report Builders Trust Construction Co./Ameristar Home Inspections 11620 Hartman Road

Jacksonville, Florida 32225 CCC-057031 CBC 056148 HI 4663 904 568 0929

# POOF CERTIFICATION

ROOF CERTIFICATION	
05/16/23	
Montavious Bryant	
LOCATION:	
4761 SW US C Lake City, Flor	ounty Road 242 ida
I have inspected the roof at the ab	ove referenced location and have found the following
General Roof Conditions	
Drainage	Good drainage
Physical Damage Attic Condition	none Good
Structural Deformation	none
Age of roof	2018
Sloped Roof	
<b>Location:</b> Item	<b>Garage Section of house</b> Remarks
Roof Material	25 year 3 tab shingles
Condition of Surface	Good
Deformed edges	None
Sloped Roof Continued	
Item	Remarks
Shingles Buckled	none

Curled none Missing tabs none

Granular Loss normal

Other The low sloped roof is covered with

Modified Bitumen roof system. In

good sound condition.

#### **Roof Features**

Items Remarks

Fascia Good condition
Soffit Good condition
in good condition

in good condition

Skylights none Vents existing

## **Ceiling Conditions**

ItemsRemarksCracksnoneWater Stainingnone

Water Leaks none

#### **Exterior Wall Surface**

Staining none Deformation Finish none

#### **Interior Wall Surfaces**

ItemsRemarksCracksnoneWater StainingNo

No structural or wood damage.

Water leaks none
Deformed Finish none
Window Leaks none

## Recap:

I inspected the roof and the following conditions was noticed.

The roof was installed in 2018. This was determined by reviewing the dates all of the other roofs in the neighborhood was completed. By looking at the roofs that are similar condition as this roof, I determined that this roof was completed in or near 2018. This will place the roof being replaced the same time the roofing companies were replacing the neighborhoods roofs. This is not an uncommon practice. The roof is in good sound condition with over 17+ years left.

# Photos of roof:





Angel Rosado 11620 Hartman Road, Jacksonville, Florida 32225 904 568 0929