



**Columbia County**  
**BUILDING DEPARTMENT**  
**Inspection Affidavit**

49

**Permit Number:** \_\_\_\_\_

I Faustin Gallegos, licensed as a(n) Contractor\* /Engineer/Architect,  
(please print name and circle Lic. Type) FS 468 Building Inspector\*

License #: CCC 1327482 On or about \_\_\_\_\_,  
did personally inspect the \_\_\_\_\_ (Date & time)

☐ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal  
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 150 NW Green Ln.

(Job Site Address)

Based upon that examination I have determined the installation was done according to the  
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Faustin Gallegos  
Signature

STATE OF FLORIDA  
COUNTY OF \_\_\_\_\_

Sworn to and subscribed before me this 10 day of July, 2013

By Rusty Gallegos, Notary Public, State of Florida

Lise Huchingson  
(Print, type or stamp name)



Personally known X or

Produced Identification \_\_\_\_\_ Type of identification produced. \_\_\_\_\_

**\* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.**

**\* Photographs must clearly show all work and have the permit number indicated on the roof.**

**\* Affidavit and Photographs must be provided when final inspection is requested.**

**\* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.**