



STATE OF FLORIDA  
DEPARTMENT OF HEALTH  
ONSITE SEWAGE TREATMENT AND DISPOSAL SYSTEM  
EXISTING SYSTEM AND SYSTEM REPAIR EVALUATION

PERMIT # \_\_\_\_\_

APPLICANT: Reed Mc Daniel Construction

(Patel)  
home owner

CONTRACTOR / AGENT: \_\_\_\_\_

LOT: \_\_\_\_\_ BLOCK: \_\_\_\_\_ SUBDIV: \_\_\_\_\_ ID#: \_\_\_\_\_

TO BE COMPLETED BY FLORIDA REGISTERED ENGINEER, DEPARTMENT EMPLOYEE, SEPTIC TANK CONTRACTOR OR OTHER CERTIFIED PERSON. SIGN AND SEAL ALL SUBMITTED DOCUMENTS. COMPLETE ALL APPLICABLE ITEMS. COMPLETE TANK CERTIFICATION BELOW OR NOTE IN REMARKS WHY THE TANKS CANNOT BE CERTIFIED.

EXISTING TANK INFORMATION

75x61x46

[ 900 ]	GALLONS SEPTIC TANK/GPD ATU	LEGEND: _____	MATERIAL: <u>Concrete</u>	BAFFLED: <u>(Y)</u> N]
[ ]	GALLONS SEPTIC TANK/GPD ATU	LEGEND: _____	MATERIAL: _____	BAFFLED: [Y / N]
[ ]	GALLONS GREASE INTERCEPTOR	LEGEND: _____	MATERIAL: _____	
[ ]	GALLONS DOSING TANK	LEGEND: _____	MATERIAL: _____	# PUMPS: [ ]

I CERTIFY THAT THE LISTED TANKS WERE PUMPED ON 7/29/22 BY \_\_\_\_\_, HAVE THE VOLUMES SPECIFIED AS DETERMINED BY [ DIMENSIONS / FILLING / LEGEND ], ARE FREE OF OBSERVABLE DEFECTS OR LEAKS, AND HAVE A [ SOLIDS DEFLECTION DEVICE / OUTLET FILTER DEVICE ] 1 INSTALLED.

Adam Lundy Lundy's Septic Inc 7/29/22  
SIGNATURE OF LICENSED CONTRACTOR BUSINESS NAME DATE

EXISTING DRAINFIELD INFORMATION Tank appears to be in good condition / However the Drain field appears to be going bad.

[ ]	SQUARE FEET PRIMARY DRAINFIELD SYSTEM	NO. OF TRENCHES [ ]	DIMENSIONS: _____	X
[ ]	SQUARE FEET _____ SYSTEM	NO. OF TRENCHES [ ]	DIMENSIONS: _____	X

TYPE OF SYSTEM: [ ] STANDARD [ ] FILLED [ ] MOUND [ ] \_\_\_\_\_  
CONFIGURATION: [ ] TRENCH [ ] BED [ ] \_\_\_\_\_  
DESIGN: [ ] HEADER [ ] D-BOX [ ] GRAVITY SYSTEM [ ] DOSED SYSTEM  
ELEVATION OF BOTTOM OF DRAINFIELD IN RELATION TO EXISTING GRADE \_\_\_\_\_ INCHES [ ABOVE / BELOW ]

SYSTEM FAILURE AND REPAIR INFORMATION

[ ]	SYSTEM INSTALLATION DATE	TYPE OF WASTE [ ] DOMESTIC [ ] COMMERCIAL
[ ]	GPD ESTIMATED SEWAGE FLOW BASED ON	[ ] METERED WATER [ ] TABLE 1, 64E-6, FAC

SITE [ ] DRAINAGE STRUCTURES [ ] POOL [ ] PATIO / DECK [ ] PARKING  
CONDITIONS: [ ] SLOPING PROPERTY [ ] \_\_\_\_\_

NATURE OF [ ] HYDRAULIC OVERLOAD [ ] SOILS [ ] MAINTENANCE [ ] SYSTEM DAMAGE  
FAILURE: [ ] DRAINAGE / RUN OFF [ ] ROOTS [ ] WATER TABLE [ ] \_\_\_\_\_

FAILURE [ ] SEWAGE ON GROUND [ ] TANK [ ] D BOX/HEADER [ ] DRAINFIELD  
SYMPTOM: [ ] PLUMBING BACKUP [ ] \_\_\_\_\_

REMARKS/ADDITIONAL CRITERIA 726 NW Clubview Cir. Lake City,

SUBMITTED BY: \_\_\_\_\_ TITLE/LICENSE \_\_\_\_\_ DATE: \_\_\_\_\_

DH 4015, 08/09 (Obsoletes previous editions which may not be used)  
Incorporated 64E-6.001, FAC