



**COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit**

Permit Number: 000041368

I Tyler Turner, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) FS 468 Building Inspector*

License #: CCC1330410 On or about 3/7/2021, did
personally inspect the (Date & time)

- ☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions
☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection

work at 521 SW Mossy Oak Way, Lake City FL 32024
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]


Signature

STATE OF FLORIDA
COUNTY OF

Sworn to and subscribed before me this 18 day of March, 2012.

By [Signature], Notary Public, State of Florida

(Print, type or stamp name)



Personally known / or

Produced Identification Type of identification produced.

*** Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.**

*** Photographs must clearly show all work and have the permit number indicated on the roof.**

*** Affidavit and Photographs must be provided when final inspection is requested.**

*** Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.**