





Columbia County BUILDING DEPARTMENT

Inspection Affidavit

RE: Permit Number: 3/592

I Dow Rock ,licensed as a(n) Contractor* /Engineer/Architect, (please print name and circle Lic. Type) FS 468 Building Inspector*
License #; CCC\330\17 On or about \(\frac{11}{21} \) \(\frac{13}{13} \) , I did personally inspect the (Date & time)
roof deck attachment secondary water barrier roof to wall connection work at 132 Sw Green Ares Willy locke (Ity 12 30004 (Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.) Signature
STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this day of Notary Public, State of Florida By
Personally known or Produced Identification Type of identification produced Identification Include photographs of each plane of the root with the Identification Iden
measure next to the nailing pattern to show distance between nails.

- * Photographs must clearly show all work and have the permit number indicated on the roof.
- $\ensuremath{^*}\xspace$ Affidavit and Photographs must be provided when final inspection is requested.