



Columbia County
BUILDING DEPARTMENT
Inspection Affidavit

Permit Number: 31011

I Michael Munterel, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) **FS 468 Building Inspector***

License #: CBC 1258399 On or about 5/13/13 9:00 AM,
did personally inspect the CCC 1329627 ✓
(Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal
manufacturer's instructions

☒ Roof deck attachment ☒ Secondary water barrier ☐ Roof to wall connection

work at 163 PLANT STREET
(Job Site Address)

Based upon that examination I have determined the installation was done according to the
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Signature

STATE OF FLORIDA
COUNTY OF


Sworn to and subscribed before me this May day of 2013

By Sharon S. Fuentes, Notary Public, State of Florida

Sharon S. Fuentes
(Print, type or stamp name)

Personally known ☒ or

Produced Identification ☐ Type of identification produced. _____



*** Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.**

*** Photographs must clearly show all work and have the permit number indicated on the roof.**

*** Affidavit and Photographs must be provided when final inspection is requested.**

*** Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.**

016
7.6
5-15-13