



49

Columbia County

BUILDING DEPARTMENT

Inspection Affidavit



Permit Number: 31293

I William Duffield, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) FS 468 Building Inspector*

License #: CC1325785 On or about 8/2/13 8:00 am,
did personally inspect the (Date & time)

☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal
manufacturer's instructions

☒ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 183 SW Oakbe Terrace Lake City, FL
(Job Site Address)

Based upon that examination I have determined the installation was done according to the
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]
Signature

STATE OF FLORIDA

COUNTY OF Alachua


Sworn to and subscribed before me this 6 day of August, 2013

By William P. Duffield, Notary Public, State of Florida

Deborah D. Yasko
(Print, type or stamp name)

Personally known ☒ or

Produced Identification _____ Type of identification produced. _____



*** Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.**

*** Photographs must clearly show all work and have the permit number indicated on the roof.**

*** Affidavit and Photographs must be provided when final inspection is requested.**

*** Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.**