

## **COLUMBIA COUNTY** BUILDING DEPARTMENT Roof Inspection Affidavit

Permit Number: 000052763 Stephen Brant Hulst ,licensed as a(n) Contractor\* /Engineer/Architect, FS 468 Building Inspector\*

License #; CCC1331691 On or about May 1, 2005, 8AM, did personally inspect the One of about May 1, 2005, 8AM.	
Metal attachment per manufacturer's instructions Mailing of purlin per metal mariufacturer's instructions	
Roof deck attachment Secondary water barrier Roof to wall connection	
work at 355 sw Callacian Drive, Lake City, F1 32	0
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)	
Stephen Brant Hellst	
Contractor's Signature	

STATE OF FLORIDA

Swern to and subscribed before, me this 5 day of MAV

(Rrint, type or stamp name)

Notary Public, State of Florida

BARBARA ASHLEY CARVER Commission # HH 568929

Personally known Produced Identification

Type of identification produced.

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.

RE: Viet V Nguyen