

## Columbia County BUILDING DEPARTMENT

## **Inspection Affidavit**

Permit Number: 3/758
I folget   Feasy   ,licensed as a(n Contractor   /Engineer/Architect, (please print name and circle Lic Type)   FS 468 Building Inspector*
License #; Reo32600 On or about 3/11/14, did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions Mailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 545 s.w. Enerald 3T, Lake city (Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)
Signature  OK  nc.  4-7-14
STATE OF FLORIDA COUNTY OF
Sworn to and subscribed before me this 1 day of April
By Notary Public, State of Florida
Personally known or Produced Identification Type of identification produced.
· / po v. identification produced.

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.