



Columbia County
BUILDING DEPARTMENT
Inspection Affidavit



Permit Number: 31766

I Mary Carol Johnson, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic Type) **FS 468 Building Inspector***

License #: CCC1330073 On or about 04-01-14,
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 191 SE Cheyenne Ct., Lake City
(Job Site Address)

Based upon that examination I have determined the installation was done according to the
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Mary Carol Johnson
Signature

OK
16
4-3-14

STATE OF FLORIDA
COUNTY OF

Sworn to and subscribed before me this 3rd day of APRIL, 2014

By Laurie Hodson, Notary Public, State of Florida

(Print, type or stamp)



Personally known ☒ or

Produced Identification ☐ Type of identification produced. _____

*** Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.**

*** Photographs must clearly show all work and have the permit number indicated on the roof.**

*** Affidavit and Photographs must be provided when final inspection is requested.**

*** Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.**