RJ,ROOFING

R

PAGE 01/01

PAGE 01/01

06/03/2013 22:29

06/03/2013 20:08 2523796341

3527267031

RESTORATION SPEC

PAGE 02/02



Columbia County BUILDING DEPARTMENT

Inspection Affidavit RE: Permit Number: 30947
I <u>Courn Ray Werntckle</u> , licensed as a(n) Contractor* /Engineer/Architect, (please print name and circle Lie Type) FS 468 Building Inspector* 1C. License #; <u>COC 1337364</u> On or about <u>4/37/13</u> , I did personally inspect the
work at 160 N 5 0 10 Jack Com Ville LP Lake Cotte
Based upon that examination I have determined the installation was done according to the Hunicane Mitigation Retrofit Manual (Based on 553.844 F.S.) Signature
STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this, I day of May
* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
* Photographs must clearly show all work and have the permit number indicated on the roof.
* Affidavit and Photographs must be provided when final inspection is requested.

MY COMMISSION # EGOGS13 EXPIRES July 07, 2014 Florida Notecy Service, com