



Columbia County Fire Rescue

INCIDENT

Incident Number	Incident Date	NEWS Number	Incident Type
24-006409	12/23/2024	0006172	(111) - Building fire
CALL	Station	Shift	District
29091	45	A Shift	D45

Initial Dispatch Code

STRUCTURE FIRE LVL 3

Alarm	Working Fire?	COVID-19 was a factor	Critical Incident Team
01	Yes	No, COVID-19 was not a factor	

Community Resource Involvement

High-Risk Materials Released

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(51) - Ventilate

Action Taken 3

(12) - Salvage & overhaul

AID

Call Outcome/Received

(N) - None

LOCATION

Location Type

(1) - Street address

Address

323 Southeast RACECAR Court, HIGH SPRINGS, Florida, 32643

Local Street, USRN, or Directions

Latitude

0.00000000

Longitude

0.00000000

Census Tract

Detector Alarmed Dispatch

Property Use

(419) - 1 or 2 family dwelling

Mixed Use

TIMES

PSAP Received

08:22:46, 12/23/2024

Dispatch Notified Time

08:22:46, 12/23/2024

Alarm Time

08:22:46, 12/23/2024

TIMES

Arrival Time

08:40:30, 12/23/2024

Water on First Try

At Patient Time

App Setup Time

Controlled Time

Last Unit Cleared Time

12:36:51, 12/23/2024

Total On Scene Time

3 hrs 56 mins 21 sec

Total Incident Time

4 hrs 14 mins 5 sec**COUNTS**

Counts Include Airt Received?

No

Suppression:

Apparatus

7

Personnel

11

EMS:

Apparatus

0

Personnel

0

Other:

Apparatus

2

Personnel

2**\$ Loss**

Property:

Estimated Property Losses

\$100000

Content:

Estimated Content Losses

\$50000

Estimated Property Value

\$100000

Estimated Content Value

\$50000**PERSON/OWNER**

Person:

Name

Mcintyre, Mathew

Business Name

Phone

Address

323 Southeast RACECAR Court, HIGH SPRINGS, Florida, 32643**AUTHORIZATION**

Report Writer:

Name

MCCAULEY, CAMERON

Employee Number

1209

Assignment

Authorization Date

12/23/2024

Officer in Charge:

Name

MCCAULEY, CAMERON

Employee Number

1209

Assignment

Authorization Date

12/23/2024

Quality Control:

Name

Authorization Date

INCIDENT NARRATIVE

All listed units were dispatched to a double wide structure fire with flames showing out of the attic. Engine 45, and tanker 45 arrived on scene first and found a double wide of a home, not fully involved at this time, however, the entirety of the roof was on fire. Fire was showing out of both ends of the eve and had already burnt the wall out of both sides. Engine 45 crew began pulling a hand line setting up for supply and beginning initial fire attack. Battalion 48 arrived on scene taking over command and performing a 360 and also securing the power main to the home. At this time advising dispatch to contact the power company as well. As more Crews arrived on scene they assisted with firefighting efforts as Crews entered the home. They began removing gifts from under the tree as well as other miscellaneous items and bringing them to the homeowner in an attempt to save them from water damage. This home had a roof over with tin over the existing shingle roof, the bulk of the fire load was between the two making it very difficult to fully extinguish the fire. Crews worked extensively, pulling the ceiling in almost every room in the home in an attempt to get water on the fire, the bulk of the fire was knocked down, at this time however, there was still smoke coming from the eve on both ends of the home. At this time, it was decided that ventilation was the only alternative. Crews worked from a ladder on the edge of the roof cutting ventilation into the roof and almost immediately the smoke was cleared. The hotspots were found and extinguished. Situation under control at this time. Red Cross was contacted to assist the family. Homeowner states fire was likely caused by a candle near the living room window on the front porch. All trucks were reloaded with hose replenished with water and released by command.

Incident Log # 24-006409

Unit Reports

E44

Type

(1) - Suppression

Responding from

Priority

Emergent

Response Delays

Distance

Dispatch Time

08:23:34, 12/23/2024

Enroute Time

08:24:23, 12/23/2024

Arrival Time

08:46:55, 12/23/2024

At Patient Time

Clear Time

12:05:40, 12/23/2024

In District Time

Actions Taken

Provide manpower, Provide apparatus, Provide equipment, Provide water

Person 1: HENDERSON, SHAWN

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(73) - Provide manpower

Person 2: FRISINA, CHANDLER

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(73) - Provide manpower

Action Taken 3

(76) - Provide water

Unit Narrative

E-44 was paged to an attic fire. E-44 went en route and arrived on scene to find smoke and flames coming from both ends of the roof line. 1619 was assigned to fire attack and overhaul. 1301 was assigned to assist with water supply and personnel equipment. E-44 was released by command. E-44 cleared and returned to station.

Incident Number: 24-006409

T46

File	Responding From	Priority
(1) - Suppression		Emergent
Response Delay		
None/No Delay		
Dispatch Time	Enroute Time	Arrival Time
08:23:34, 12/23/2024	08:33:25, 12/23/2024	08:41:11, 12/23/2024
At Patient Time	Clear Time	In District Time
	12:36:51, 12/23/2024	
Actions Taken		
Provide manpower, Provide apparatus, Provide equipment, Provide water		

Person 1: SHALLAR III, LARRY

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(73) - Provide manpower

Action Taken 3

(12) - Salvage & overhaul

Patient Contact?	Medical PPE Worn
No	None
Fire Products Exposed To	
Debris/Runoff, Smoke, Fire, Gases/CO, Heat	
PPE Worn During Incident	
Firefighting Gloves, Hood, Boots, SCBA, Structure Firefighting Helmet, Pant, Coat, Mask	

PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth
No	No	No	No

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas

Person 2: HECKMAN, JULES

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(73) - Provide manpower

Person 2: HECKMAN, JULES

Action Taken 2

(12) - Salvage & overhaul

Patient Contact 1

No

Medical PPE Worn

None

Exposure(s) Exposed to

Smoke, Debris/Runoff, Heat, Gases/CO, Fire

PPE Worn During Incident

Mask, Hood, Firefighting Gloves, Coat, Pant, Structure Firefighting Helmet, SCBA, Boots

SPE Markings Used

No

Burner Breach

No

Black Soot Around

No

Black Soot Around

No

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas**Unit Narrative**

T-46 responded to the address given in reference to an attic fire. T-46 arrived on-scene with E-45, T-45 and Battalion 48 to a double wide mobile home with heavy smoke showing and flames coming out the attic space on the B and D side of the structure. T-46 crew with a pre-connect (200ft. 1.75 with fog nozzle) started fire extinguishment with a quick knock down on the D-side. Same actions were taken for the B-side of the structure. T-46 crew assisted with this incident by fire extinguishment, providing manpower, checking for fire extension, ventilation, salvage and overhaul. Fire was extinguished with no additional hazards present. Salvage and overhaul were complete. T-45 was released by command. T-45 assignment complete, became available. See main and unit narratives for any additional information regarding to this incident.

T45

Unit

(1) - Suppression

Responding From

Priority

Emergent

Sequence Delays

None/No Delay

Dispatch Time

08:23:33, 12/23/2024

Enroute Time

08:25:15, 12/23/2024

Arrival Time

08:40:30, 12/23/2024

Air Release Time

Clear Time

12:36:51, 12/23/2024

In District Time

Action Taken

Provide manpower, Provide apparatus, Provide equipment, Provide water**Person 1: BEDENBAUGH, STEVE**

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(12) - Salvage & overhaul**Unit Narrative**

E-45 and T-45 was paged to an attic fire. 45 Units went en route and arrived on scene to find smoke and flames coming from both ends of the roof line. 1312 began supply setup and asked BC to Be command and 360 the scene. 1611 Packed out for offensive attack. Additional Units arrived and fire was extinguished and overhaul performed. scene was turned back over to homeowner and all units, cleared. SBB

Unit Narrative

Unit 24-006409 - 12/23/2024

E46

Use	Responding From	Priority
(1) - Suppression		Emergent

Response Object

None/No Delay

Dispatch Time	Enroute Time	Arrival Time
08:23:33, 12/23/2024	08:33:23, 12/23/2024	08:41:56, 12/23/2024

At Patient Time	Clear Time	In District Time
	12:36:51, 12/23/2024	

Actions Taken

Provide manpower, Provide apparatus, Provide equipment

Person 1: ALVEY, DYLAN

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(73) - Provide manpower

Action Taken 4

(12) - Salvage & overhaul

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Gases/CO, Fire, Heat, Smoke, Debris/Runoff

PPE Worn During Incident

Structure Firefighting Helmet, Hood, Boots, SCBA, Mask, Firefighting Gloves, Pant, Coat

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around

Nose

No

Black Soot Around

Mouth

No

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas

Person 2: Dale, Brett

Action Taken 1

(73) - Provide manpower

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(12) - Salvage & overhaul

Patient Contact?

No

Medical PPE Worn

None

Person 2: Dale, Brett

Fire Products Exposed To

Debris/Runoff, Heat, Smoke, Gases/CO, Fire

PPE Worn During Incident

Pant, Hood, Structure Firefighting Helmet, Coat, Boots, Mask, Firefighting Gloves, SCBA

PPE Malfunction?

No

Barrier breach

No

Black Soot Around
Neck

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas

Unit Narrative

E-46 responded to a stated address, reference a structure fire. E-46 arrived on scene and reported to command. 46 crews assisted in extinguishment of the fire until released by command. E-46 assignment complete.

Unit released to the scene.

E45

Use

(1) - Suppression

Responding From

Priority

Emergent

Response Delays

None/No Delay

Dispatch Time

08:23:32, 12/23/2024

Enroute Time

08:25:12, 12/23/2024

Arrival Time

08:40:30, 12/23/2024

At Patient Time

Clear Time

12:36:51, 12/23/2024

In District Time

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment, Provide water

Person 1: LEDGER, OLIVIA

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(12) - Salvage & overhaul

Unit Narrative

E-45 and T-45 was paged to an attic fire. 45 Units went en route and arrived on scene to find smoke and flames coming from both ends of the roof line. 1312 began supply setup and asked BC to be command and 360 the scene. 1611 Packed out for offensive attack. Additional Units arrived and fire was extinguished and overhaul performed. scene was turned back over to homeowner and all units cleared. SBB

Unit released to the scene.

E48

Use

(1) - Suppression

Responding From

Priority

Emergent

Response Delays

None/No Delay

E48

Dispatch Time

08:23:34, 12/23/2024

Enroute Time

08:27:16, 12/23/2024

Arrival Time

08:45:28, 12/23/2024

At Patient Time

Clear Time

In District Time

12:36:51, 12/23/2024

Actions Taken

Fire control or extinguishment, other, Salvage & overhaul, Provide manpower**Person 1: FRY, BENJAMIN**

Action Taken 1

(10) - Fire control or extinguishment, other

Action Taken 2

(12) - Salvage & overhaul

Action Taken 3

(73) - Provide manpower

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Smoke, Heat, Fire

PPE Worn During Incident

Pant, Hood, Structure Firefighting Helmet, Coat, Mask, Boots, Firefighting Gloves, SCBA

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around

None

Black Soot Around

Mouth

Decontamination Procedures Completed

Wet brush gear with soap**Person 2: Stermer, Luke**

Action Taken 1

(10) - Fire control or extinguishment, other

Action Taken 2

(12) - Salvage & overhaul

Action Taken 3

(73) - Provide manpower

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Fire, Smoke, Heat

PPE Worn During Incident

Structure Firefighting Helmet, Firefighting Gloves, Coat, Hood, Mask, SCBA, Boots, Pant

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around

None

Black Soot Around

Mouth

Person 2: Stermer, Luke

Decontamination Procedures Completed

Wet brush gear without soap

Unit Narrative

Engine 48 was dispatched to stated address for a structure fire, once on scene reporte to command and began fire fighting efforts until released.

Columbia County Fire Rescue

BAT48

Type	Responding From	Priority
(0) - Other		Emergent

Response Delays

None/No Delay

Dispatch Time

08:23:34, 12/23/2024

Enroute Time

08:27:15, 12/23/2024

Arrival Time

08:41:01, 12/23/2024

At Patient Time

Clear Time

12:36:51, 12/23/2024

In District Time

Actions Taken

Incident command, Investigate, Provide manpower

Person 1: MCCAULEY, CAMERON

Actions Taken

(81) - Incident command

Actions Taken

(86) - Investigate

Patient Contact?

No

Medical PPE Worn

None

Size of Patients Exposed To

None

PPE Worn During Incident

None

Fire Medication?

No

Barrier Breach

No

Black Soot Around

None

Black Soot Around

Mouth

No

Decontamination Procedures Completed

Unit Narrative

SEE MAIN NARRATIVE

Columbia County Fire Rescue

T48

Type	Responding From	Priority
(1) - Suppression		Emergent

T48

Response Delays

Distance

Dispatch Time

08:23:34, 12/23/2024

Enroute Time

08:27:17, 12/23/2024

Arrival Time

08:46:21, 12/23/2024

At Patient Time

Clear Time

12:36:51, 12/23/2024

In District Time

Actions Taken

Provide water, Provide manpower

Person 1: WOODARD, DUSTIN

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(12) - Salvage & overhaul

Action Taken 3

(76) - Provide water

Fire Products Exposed To

Fire, Smoke, Heat

PPE Worn During Incident

Coat, Pant, Firefighting Gloves, Boots, Mask, SCBA, Hood, Structure Firefighting Helmet

Fire Mattress(es)

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Wet brush gear without soap

Unit Narrative

TANKER 48 REPORTED TO COMMAND AND ASSISTED WITH FIRE FIGHTER EFFORTS AS WELL AS PROVIDED WATER SUPPLY TO MAIN ENGINE, REMAINED ON SCENE UNTIL RELEASED

Commander: [Signature]

FM1

Type

(0) - Other

Responding From

Priority

Non-Emergent

Response Delays

None/No Delay

Dispatch Time

08:47:58, 12/23/2024

Enroute Time

08:47:58, 12/23/2024

Arrival Time

08:56:06, 12/23/2024

At Patient Time

Clear Time

11:21:18, 12/23/2024

In District Time

Actions Taken

Provide manpower, Operate apparatus or vehicle

STRUCTURE

Fire Spread

(4) - Confined to building of origin

Room Containing Most of Flame Spread

(10) - Structural component or finish, other

Type of Material

(70) - Fabric, textile, fur, other**Number of Stories with Damage**

Minor Damage

Significant Damage

Heavy Damage

Extreme Damage

Total Stories

1**PROTECTIVE SYSTEMS**

Presence of Detector

(1) - Present

Detector Type

(1) - Smoke

Power Supply

(1) - Battery only

Detector Operations

(2) - Detector operated

If Occupants Not Aware of Alarm

(1) - Detector alerted occupants, occupants responded

Presence of Auto Extinguishing System

(N) - None Present

System Type

System Operation

of Sprinklers

Reason for System Failure