



# Columbia County

## BUILDING DEPARTMENT

### Inspection Affidavit



Permit Number: 31858

I Mary Carol Johnson, licensed as a(n) Contractor\* /Engineer/Architect,  
(please print name and circle Lic Type) FS 468 Building Inspector\*

License #: CCC 1330073 On or about 04-04-14,  
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal  
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 304 Spring Hollow Blvd., LC FL 32055  
(Job Site Address)

Based upon that examination I have determined the installation was done according to the  
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Carol Johnson

Signature

OK  
1c. 5-1-14

STATE OF FLORIDA  
COUNTY OF

Sworn to and subscribed before me this 1 day of May, 2014

By Laurie Hodson, Notary Public, State of Florida

Personally known ☒ or

Produced Identification \_\_\_\_\_ Type of identification produced. \_\_\_\_\_

(Print, type or stamp name)



\* Include photographs of each plane of the roof with the permit number  
clearly shown marked on the deck for each inspection. Place a tape  
measure next to the nailing pattern to show distance between nails.

\* Photographs must clearly show all work and have the permit number  
indicated on the roof.

\* Affidavit and Photographs must be provided when final inspection is  
requested.

\* Metal overlay & purlin installations shall have photographs of purlins  
or underlayment, whichever applies.