## John R Feeney - Construction LLC

2841 SE 46th Way Trenton, FL 32693

November 12, 2013

## Columbia County Building Department

To whom it may concern,

I am submitting a permit application for a Non-Structural Remodel Permit for the single family residence located at 185 SE Greg Place. I am going to list below the work to be performed.

- -Replace existing fence with new PT posts and 8' fence panels in same location as existing
- Remove existing porch covering
- -Add concrete to bring both existing rear slabs to same level (averages less than 2" difference now)
- Build new 2x6 wall on rear porch, perpendicular to rear wall of home, which will serve as a place to mount new electrical service (Remainder of porch will have aluminum screen enclosure)
  - o Pt. bottom plate and double top plate 2x6 wall stude 16" o c.
  - Secure bottom plate to slab with 3/8" wedge bolts within 8" of each end and max 24"
    o c.
  - Sheet both sides with 7/16 osb
  - House-wrap and side with concrete based lap siding.
- Cover porch with composite aluminum panels and screen in (submitting 2 copies of engineering)
- Re-Roof with 30 year architectural shingle
- Replace HVAC with new heat pump unit
- Replace electrical service with new 200amp Overhead Feed and relocate mast
  - o Add necessary receptacle to bring kitchen and baths to code
  - Add GFCI's at front and rear entrances as necessary
  - Add interconnected smoke detectors to all bedrooms and hall
- Encapsulate lead paint in carport, front entrance, and all soffits Lead Supervisor to perform work
- Interior drywall repair

27395 00 326 2000 73824 510 029/ 800 10/ 289 0 21848 7185E かんそそと 2379 S 1966 M 90 CA TOTAL LOAD 7, OLE REPORTED Total Latent Heat R-45 25 Z R-30 2 100 Ć. Adjusted Subtotal 13.8 25 P S 8 2400 0.32 2.7 47% x cooling subtotal 94 × 15% x cooling subtotal 24% x cooling subtotal 70% x cooling subtotal 11 6% x cooling subtotal Firsplace CFM Fireplace CFM Total CFIL Ce27 336 17.5 30 7.31 0.47 3 8 ь Average 12% X heating subtotal 24% X heating subtotal 0 insul 7.38 35% X heafing subfotal O Insui 6% X heating subtotal 9% X heating subtotal 0 Insul 53.0 20.3 1.92 280 330 28.1 n n \*\* Cooling Lafert Load Cooling full CFI Cooling Inflitration CFM Cooling Home Laskage Factor Heating Heating Heating Cooling 6,49 6,25 0.32 0.16 Š. 24 × × 24% Supply Air Duxt Leakage and 47% Return Air Duct Leakage 12% Supply Air Duct Leakage and 24% Return Air Duct Leakage 9% Supply Air Duct Leakage and 15% Return Air Duct Leakage 35% Supply Air Duct Leakage and 70% Return Air Duct Leakage 6% Supply Air Duct Leakage and 6% Return Air Duct Leakage 8 Cooling Heating 8 Grains 30 Area 18 135 74 Pecole Length . 20 Height Michigan 西田 Ø Copyright@ 2011 HVAC Learning Solutions × Slab on Grade Heavy Bry of Light Wet Soil Vertical Eggelhaul 3' below grade Floor Over Open Craw Space or Garage Floor Over Enclosed Unconditioned Grawl Space or Unconditioned Basement 1000 Supply & Remm NumberofiReople 20" Shortest Side 1430 Fireplaces Celling Area Infiltration

• Page 2 November 12, 2013

- Interior painting
- Interior flooring replacement
- Add insulation to R-38 in attic
- Replace some interior doors

Feel free to contact me with any questions.

Sincerely, John Feeney State Certified Building Contractor CBC1257883 (352) 682-4660