

Rebuild Florida Housing Repair and Replacement Program

Insured: Clarence Pender Home: (985) 640-0653

Property: 195 SW Knight Ter

Fort White, FL 32038

Claim Rep.: Bruce Jackson

Estimator: Bruce Jackson

Reference:

Company: Modular Home

Claim Number: 007530 Policy Number: 007530 Type of Loss: Hurricane

Date Contacted: 9/25/2019 1:00 AM

Date of Loss: 9/10/2017 1:00 AM Date Received: 9/10/2019 1:00 AM Date Inspected: 10/4/2019 12:00 AM Date Entered: 10/5/2019 12:06 PM

Price List: FLGA8X_OCT20

Restoration/Service/Remodel

Estimate: 007530_PENDER_MOD

For homes being rehabilitated, the HUD Green Building Retrofit Checklist (GBR Checklist) is a Federal construction standard requiring that work performed when receiving Federal funds must meet certain energy efficiency standards, whenever feasible. All eligible repairs must be performed in line with the GBR Checklist to the extent practicable. The Scope of Work Estimate (SWE) for remaining construction was written to the applicable specifications of the GBR Checklist and Program guidelines, including considerations for HUD Housing Quality Standards, and the Rebuild Florida Program Resilient Home Construction Standards (RHCS).

If the summary for SWE total, excluding any RHCS, exceeds 75% of the cost of the Program estimate to rebuild a new home, as determined by the Program, the home will be reconstructed. The Federal government requires that reconstructed homes meet the ENERGY STAR Certified Home standards and that the home meets applicable Program standards.



Rebuild Florida Housing Repair and Replacement Program

007530_PENDER_MOD

007530_PENDER_MOD

DESCRIPTION QTY UNIT PRICE TOTAL

Confirmed cause of damage: The dwelling has confirmed damage from Hurricane Irma. **CRE Damages:** Home was Demolished because of the severe damage after Hurricane IRMA.

SWE Damages: Home was Demolished due to Hurricane IRMA

Other: Reasonable Accommodations Request has been addressed in estimate

HQS: N/A RHCS: N/A

Main Level

Main Level

| DESCRIPTION | QTY | UNIT PRICE | TOTAL |
|---|---------------|------------|-----------|
| CONTENT | | | |
| 1. Job-site moving/storage container - 16' long - per month | 3.00 MO @ | 174.99 = | 524.97 |
| Three months rental of one job-site storage containers for Modular Home | | | |
| 2. Job-site moving container - pick up/del. (ea. way) 12'-20' | 2.00 EA @ | 79.99 = | 159.98 |
| One container for Modular Home (delivery and pick-up) - 1 to 3 Bedroom | | | |
| DEMO AND REPLACE | | | |
| 3. Demolish/remove home (1001 sf - 2000 sf) | 1,040.00 SF@ | 5.60 = | 5,824.00 |
| 4. Modular Home with 3BD/2BA Configuration | 1,325.00 SF @ | 41.76 = | 55,332.00 |

Quality: Overall quality is of an average grade.

Note: The bedroom bathroom configuration matches the standardized program configuration from applicant's original eligible structure of $3\ BD/\ 2\ BTH$

Average life expectancy 38 years

Average depreciation 2.63% per year

Maximum depreciation 100%

Replacement modular home must be within 100 square feet of the eligible standardized program configuration.

- **For the purpose of Accessibility, the following is required:
- 1. One wheelchair accessible bathroom including:
- 1. Low threshold shower with one grab bar.
- 2. Comfort height toilet with one grab bar.
- 3. 36" door with outward swing pattern.
- 2. One bedroom with 36" door with outward swing pattern and one grab bar.
- 3. Exterior ramp up to six feet in vertical height.
- 4. Exterior lift when elevation height is required above six feet. **

-----MEP CONNECTIONS-----

5. Central air conditioning system - 2.5 ton - 14-15 SEER 1.00 EA @ 2,818.00 = 2,818.00





Rebuild Florida Housing Repair and Replacement Program

CONTINUED - Main Level

DESCRIPTION QTY UNIT PRICE TOTAL

Includes: Central air condensing unit and installation labor.

Quality: (1 ton per 400 SQ FT), 14 SEER

Reference: A 2.5 ton unit will approximately service 1200 to 1650 SF. Factors such as climate, structure design, and overall cooling needs may influence the sizing requirements for the structure. A load calculation should be performed by a professional HVAC tradesman to accurately calculate the AC unit sizing.

Green: Air conditioning units may contribute to LEED fundamental commissioning, minimum energy performance, fundamental refrigerant management and thermal comfort credits.

Note: Typically, new condensing units are factory charged and may include refrigerant for approximately 15' of line set depending on manufacturer specifications and system requirements. If additional refrigerant is needed see item HVC ACR. One pound of refrigerant will supply approximately 26.67 lineal feet of 3/8" line set.

Average life expectancy 15 years

Average depreciation 6.67% per year

Maximum depreciation 100%

| 6. Meter base - 200 amp | 1.00 | EA@ | 316.51 = | 316.51 |
|---|---------------|-------------|---------------------|----------|
| 7. Utility pole - composite - 25' | 1.00 | EA@ | 1,389.48 = | 1,389.48 |
| 8. Floor drain system | 1,325.00 | SF@ | 0.90 = | 1,192.50 |
| LANDSCAPING | | | | |
| 9. Lawn - sod | 486.00 | SF@ | 0.61 = | 296.46 |
| Linear feet of floor perimeter multiplied by 3. | | | | |
| REASONABLE ACCOMMODATIONS REQUEST | | | | |
| 10. UFAS compliant 1:12 slope - Handicap Accessible Ramp \$1600 per Verticle Foot | 3.00 | EA@ | 1,600.00 = | 4,800.00 |
| Accessibility Ramp must be built on site. | | | | |
| 11. Low threshold shower with one grab bar | 1.00 | EA@ | 1,295.00 = | 1,295.00 |
| 12. Comfort height toilet with one grab bar | 1.00 | EA@ | 350.00 = | 350.00 |
| 13. 36" door with outward swing pattern | 2.00 | EA@ | 320.00 = | 640.00 |
| One bedroom with 36" door with outward swing pattern and One bathroon | n with 36"doo | or with out | ward swing pattern. | |



Rebuild Florida Housing Repair and Replacement Program

Grand Total Areas:

| , | SF Walls SF Floor | | SF Ceiling SY Flooring | | SF Walls and Ceiling LF Floor Perimeter |
|---|------------------------------------|---|--|----------|--|
| , | SF Long Wall | | SF Short Wall | 162.00 | LF Ceil. Perimeter |
| , | Floor Area Exterior Wall Area | , | Total Area Exterior Perimeter of Walls | 1,296.00 | Interior Wall Area |
| | Surface Area Total Ridge Length | | Number of Squares Total Hip Length | 0.00 | Total Perimeter Length |



Rebuild Florida Housing Repair and Replacement Program

Summary for SWE

| Line Item Total | | 74,938.90 |
|------------------------|---------------|-------------|
| Material Sales Tax | | 253.77 |
| Manuf. Home Tax | | 3,319.92 |
| Storage Rental Tax | | 41.10 |
| Replacement Cost Value | | \$78,553.69 |
| Net Claim | | \$78,553.69 |
| | | |
| | | |
| | | |
| | Bruce Jackson | |



Rebuild Florida Housing Repair and Replacement Program

Recap by Room

Estimate: 007530_PENDER_MOD

| Area: Main Level | 74,938.90 | 100.00% |
|---------------------------|-----------|---------|
| Area Subtotal: Main Level | 74,938.90 | 100.00% |
| Subtotal of Areas | 74,938.90 | 100.00% |
| Total | 74,938.90 | 100.00% |



Rebuild Florida Housing Repair and Replacement Program

Recap by Category

| Items | Total | % |
|--------------------------------|-----------|---------|
| CONTENT MANIPULATION | 684.95 | 0.87% |
| GENERAL DEMOLITION | 5,824.00 | 7.41% |
| DOORS | 640.00 | 0.81% |
| ELECTRICAL | 1,705.99 | 2.17% |
| HEAT, VENT & AIR CONDITIONING | 2,818.00 | 3.59% |
| LANDSCAPING | 296.46 | 0.38% |
| MOBILE HOMES, SKIRTING & SETUP | 55,332.00 | 70.44% |
| PLUMBING | 2,837.50 | 3.61% |
| USER DEFINED ITEMS | 4,800.00 | 6.11% |
| Subtotal | 74,938.90 | 95.40% |
| Material Sales Tax | 253.77 | 0.32% |
| Manuf. Home Tax | 3,319.92 | 4.23% |
| Storage Rental Tax | 41.10 | 0.05% |
| Total | 78,553.69 | 100.00% |



Rebuild Florida Housing Repair and Replacement Program

1 Exterior/Front - 1-Front Date Taken: 10/4/2019 Taken By: Bruce Jackson



2 Exterior/Front - 2-Front Date Taken: 10/4/2019 Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

3 Exterior/Front - 3-Front Date Taken: 10/4/2019 Taken By: Bruce Jackson



4 Exterior/Front - 4-Front Date Taken: 10/4/2019 Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

5 Exterior/Front - 5-Front Date Taken: 10/4/2019 Taken By: Bruce Jackson



6 Exterior/Front - 6-Front Date Taken: 10/4/2019 Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

7 Exterior/Left - 7-Left Date Taken: 10/4/2019 Taken By: Bruce Jackson



8 Exterior/Left - 8-Left
Date Taken: 10/4/2019
Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

9 Exterior/Left - 9-Left Date Taken: 10/4/2019 Taken By: Bruce Jackson



10 Exterior/Left - 10-Left
Date Taken: 10/4/2019
Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

11 Exterior/Left - 11-Left Date Taken: 10/4/2019 Taken By: Bruce Jackson



12 Exterior/Left - 12-Left
Date Taken: 10/4/2019
Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

13 Exterior/Left - 13-LeftDate Taken: 10/4/2019Taken By: Bruce Jackson



14 Exterior/Rear - 14-Rear Date Taken: 10/4/2019 Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

15 Exterior/Rear - 15-RearDate Taken: 10/4/2019Taken By: Bruce Jackson



16 Exterior/Rear - 16-RearDate Taken: 10/4/2019Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

17 Exterior/Right - 17-Right Date Taken: 10/4/2019 Taken By: Bruce Jackson



18 Exterior/Right - 18-Right Date Taken: 10/4/2019 Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

Exterior/Right - 19-RightDate Taken: 10/4/2019Taken By: Bruce Jackson



20 Exterior/Right - 20-Right Date Taken: 10/4/2019 Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

21 Exterior/Right - 21-Right Date Taken: 10/4/2019 Taken By: Bruce Jackson



22 Exterior/Right - 22-Right
Date Taken: 10/4/2019
Taken By: Bruce Jackson





Rebuild Florida Housing Repair and Replacement Program

23 Main Level - 23-Address Date Taken: 10/4/2019 Taken By: Bruce Jackson



 Main Level - 24-Applicant Submitted Photo
 Date Taken: 9/15/2017
 Taken By: Applicant





Rebuild Florida Housing Repair and Replacement Program

Main Level - 25-Applicant Submitted PhotoDate Taken: 9/15/2017Taken By: Applicant




 Main Level - 26-Applicant Submitted Photo
 Date Taken: 9/15/2017
 Taken By: Applicant






Rebuild Florida Housing Repair and Replacement Program

 Main Level - 27-Applicant Submitted Photo
 Date Taken: 9/15/2017
 Taken By: Applicant



28 Main Level - 28-Applicant Submitted Photo Date Taken: 9/15/2017 Taken By: Applicant





Rebuild Florida Housing Repair and Replacement Program

Main Level - 29-Applicant
 Submitted Photo
 Date Taken: 9/15/2017
 Taken By: Applicant



30 Main Level - 30-Applicant Submitted Photo Date Taken: 9/15/2017 Taken By: Applicant





Rebuild Florida Housing Repair and Replacement Program

Main Level - 31-Applicant Submitted PhotoDate Taken: 9/15/2017Taken By: Applicant



Main Level - 32-Applicant Submitted PhotoDate Taken: 9/15/2017Taken By: Applicant





Rebuild Florida Housing Repair and Replacement Program

Main Level - 33-Applicant Submitted PhotoDate Taken: 9/15/2017Taken By: Applicant



 Main Level/Footprint - 34-ScreenShot
 Date Taken: 10/4/2019
 Taken By: Bruce Jackson
 Street View from google.






Rebuild Florida Housing Repair and Replacement Program

35 Main Level/Footprint - 35-ScreenShot

> Date Taken: 10/4/2019 Taken By: Bruce Jackson

Unable to attain footprint from google earth.



Main Level

Footprint South

Main Level

007530_PENDER_MOD Page: 26