



# Columbia County

## BUILDING DEPARTMENT

### Inspection Affidavit

Permit Number: 0000031036

I Gary Southard, licensed as a(n) Contractor\*/Engineer/Architect,  
(please print name and circle Lic. Type) FS 468 Building Inspector\*

License #: CCC/330010 On or about 5-15-13 / 9:45,  
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal  
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 163 SE Croft St Lulu FL 32025  
(Job Site Address)

Based upon that examination I have determined the installation was done according to the  
Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Signature Gary Southard

NOTARY PUBLIC-STATE OF FLORIDA  
Cynthia R. Long  
Commission # EE005812  
Expires: JUNE 30, 2014  
BONDED THRU ATLANTIC BONDING CO., INC.

STATE OF FLORIDA  
COUNTY OF Alachua

Sworn to and subscribed before me this 15 day of May, 2013

By Gary Southard, Notary Public, State of Florida

Cynthia R. Long  
(Print, type or stamp name)

Personally known \_\_\_\_\_ or  
Produced Identification \_\_\_\_\_ Type of identification produced, \_\_\_\_\_

\* Include photographs of each plane of the roof with the permit number  
clearly shown marked on the deck for each inspection. Place a tape  
measure next to the nailing pattern to show distance between nails.

\* Photographs must clearly show all work and have the permit number  
indicated on the roof.

\* Affidavit and Photographs must be provided when final inspection is  
requested.

\* Metal overlay & purlin installations shall have photographs of purlins  
or underlayment, whichever applies.

OK  
1.c.  
5-30-13

