




Order Summary

dba: RENEWAL BY ANDERSEN OF FLORIDA

Legal Name: JLM Windows, LLC | License # CGC1527613
997 West Kennedy Blvd. Suite A1 | Orlando, FL 32810
Phone: 904-267-1270 | Fax: 407-386-8262 | concierge@rbafla.com
Measure Tech: Nathan Henry,

Cindi Southwell
8701 SE CR245
Lake City, FL 32025
H: (706)587-1002

FLOORPLAN - 1ST FLOOR



UNIT NOTES

JOB PHOTOS



Order Summary

dba: RENEWAL BY ANDERSEN OF FLORIDA

Legal Name: JLM Windows, LLC | License # CGC1527613
997 West Kennedy Blvd. Suite A1 | Orlando, FL 32810
Phone: 904-267-1270 | Fax: 407-386-8262 | concierge@rbafia.com
Measure Tech: Nathan Henry,

Cindi Southwell
8701 SE CR245
Lake City, FL 32025
H: (706)587-1002

ID#	ROOM	SIZE		DETAILS
JOB				
101	Office	28" 27-1/2"	48" 45-1/2"	Window: Acclaim™ Double-Hung (DG), 1:1, Flat Sill, Insert Frame, Traditional Checkrail, Exterior Terratone, Interior Terratone Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Stone Screen: Fiberglass, Full Screen Grille Style: No Grille Misc: None Construction: None Material: 2.25" x 5/8" L-Trim, (12 ft), Terratone (2), Caulk - Terratone Exterior (1), #10 X 3.5" Deck Screws (Wood Frame) (0.25), 1/16 Flat Shims (1), 1/32 Flat Shims (1), Flashing Tape (0.5), Foam: Low Expansion Polyurethane (1), Raw pine brick mold (2)
102	Bedroom	28" 27-1/2"	48" 45-1/2"	Window: Acclaim™ Double-Hung (DG), 1:1, Flat Sill, Insert Frame, Traditional Checkrail, Exterior Terratone, Interior Terratone Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Stone Screen: Fiberglass, Full Screen Grille Style: No Grille Misc: None Construction: None Material: 2.25" x 5/8" L-Trim, (12 ft), Terratone (2), Caulk - Terratone Exterior (1), #10 X 3.5" Deck Screws (Wood Frame) (0.25), 1/16 Flat Shims (1), 1/32 Flat Shims (1), Flashing Tape (0.5), Foam: Low Expansion Polyurethane (1), Raw pine brick mold (2)
103	Bedroom	28" 27-1/2"	48" 45-1/2"	Window: Acclaim™ Double-Hung (DG), 1:1, Flat Sill, Insert Frame, Traditional Checkrail, Exterior Terratone, Interior Terratone Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Stone Screen: Fiberglass, Full Screen Grille Style: No Grille Misc: None Construction: None Material: 2.25" x 5/8" L-Trim, (12 ft), Terratone (2), Caulk - Terratone Exterior (1), #10 X 3.5" Deck Screws (Wood Frame) (0.25), 1/16 Flat Shims (1), 1/32 Flat Shims (1), Flashing Tape (0.5), Foam: Low Expansion



Order Summary

dba: RENEWAL BY ANDERSEN OF FLORIDA

Legal Name: JLM Windows, LLC | License # CGC1527613
997 West Kennedy Blvd. Suite A1 | Orlando, FL 32810
Phone: 904-267-1270 | Fax: 407-386-8262 | concierge@rbafla.com
Measure Tech: Nathan Henry,

Cindi Southwell
8701 SE CR245
Lake City, FL 32025
H: (706)587-1002

ID#	ROOM	SIZE		DETAILS
				Polyurethane (1), Raw pine brick mold (2)
104	Dining	28" 27-1/2"	53" 53-1/2"	Window: Acclaim™ Double-Hung (DG), 1:1, Flat Sill, Insert Frame, Traditional Checkrail, Exterior Terratone, Interior Terratone Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Stone Screen: Fiberglass, Full Screen Grille Style: No Grille Misc: None Construction: None Material: 2.25" x 5/8" L-Trim, (12 ft), Terratone (2), Caulk - Terratone Exterior (1), #10 X 3.5" Deck Screws (Wood Frame) (0.25), 1/16 Flat Shims (1), 1/32 Flat Shims (1), Flashing Tape (0.5), Foam: Low Expansion Polyurethane (1), Raw pine brick mold (2)
105	Dining	28" 27-1/2"	53" 53-1/2"	Window: Acclaim™ Double-Hung (DG), 1:1, Flat Sill, Insert Frame, Traditional Checkrail, Exterior Terratone, Interior Terratone Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Stone Screen: Fiberglass, Full Screen Grille Style: No Grille Misc: None Construction: None Material: 2.25" x 5/8" L-Trim, (12 ft), Terratone (2), Caulk - Terratone Exterior (1), #10 X 3.5" Deck Screws (Wood Frame) (0.25), 1/16 Flat Shims (1), 1/32 Flat Shims (1), Flashing Tape (0.5), Foam: Low Expansion Polyurethane (1), Raw pine brick mold (2)
107	Kitchen	24" 23-1/2"	37" 37-1/2"	Window: Acclaim™ Double-Hung (DG), 1:1, Flat Sill, Insert Frame, Traditional Checkrail, Exterior Terratone, Interior Terratone Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Stone Screen: Fiberglass, Full Screen Grille Style: No Grille Misc: None Construction: None Material: 2.25" x 5/8" L-Trim, (12 ft), Terratone (1), Caulk - Terratone Exterior (1), #10 X 3.5" Deck Screws (Wood Frame) (0.25), 1/16 Flat Shims (1), 1/32 Flat Shims (1),



Order Summary

dba: RENEWAL BY ANDERSEN OF FLORIDA

Legal Name: JLM Windows, LLC | License # CGC1527613
997 West Kennedy Blvd. Suite A1 | Orlando, FL 32810
Phone: 904-267-1270 | Fax: 407-386-8262 | concierge@rbafla.com
Measure Tech: Nathan Henry,

Cindi Southwell
8701 SE CR245
Lake City, FL 32025
H: (706)587-1002

ID#	ROOM	SIZE		DETAILS
				Flashing Tape (0.5), Foam: Low Expansion Polyurethane (1), Raw pine brick mold (2)
106	Kitchen	24" 23-1/2"	37" 37-1/2"	Window: Acclaim™ Double-Hung (DG), 1:1, Flat Sill, Insert Frame, Traditional Checkrail, Exterior Terratone, Interior Terratone Performance Calculator: PG Rating: 40 DP Rating: + 40 / - 40 Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Stone Screen: Fiberglass, Full Screen Grille Style: No Grille Misc: None Construction: None Material: 2.25" x 5/8" L-Trim, (12 ft), Terratone (1), Caulk - Terratone Exterior (1), #10 X 3.5" Deck Screws (Wood Frame) (0.25), 1/16 Flat Shims (1), 1/32 Flat Shims (1), Flashing Tape (0.5), Foam: Low Expansion Polyurethane (1), Raw pine brick mold (2)

PRODUCTS: 7 WINDOWS: 7 PATIO DOORS: 0 ENTRY DOORS: 0 SPECIALTY: 0 MISC: 0

Updated 2/16/24

JOB NOTES

Very old home

Replacing all brickmold due to rot.

Replacing rotted sill on all windows

Customer advised of siding issues that need to be addressed, you can see insulation and framing from exterior

Ac unit may not fit in the opening due to size of new window framing

All the wood on the job is pine, home owner may have extra material he would like you to use to lower his collection.

Estimated Duration: 2½ days