

Personally known  $\checkmark$ 

## Columbia County BUILDING DEPARTMENT Inspection Affidavit

Permit Number: 31382 licensed as a(n) Contractor\* /Engineer/Architect, FS 468 Building Inspector\* (please print name and circle Lic Type) License #; 5950 On or about 9/5/13 did personally inspect the Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions Roof deck attachment Secondary water barrier Roof to wall connection work at 1575 Frontier Dr Lake City, FL 32055 Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.) MAMARA Signature STATE OF FLORIDA COUNTY OF COLUMBIA
Sworn to and subscribed before me this of day of SEPTEMBER. 2013 Notary Public, State of Florida **REGINA G. TIMMONS** 

\* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

Produced Identification Type of identification produced.

- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.