



COLUMBIA COUNTY
BUILDING DEPARTMENT
Roof Inspection Affidavit

Permit Number: 41774

I John G. O'Neal, licensed as a(n) Contractor* /Engineer/Architect,
(please print name and circle Lic. Type) FS 468 Building Inspector*

License #: CCC1329495 On or about 6/24/21, did
personally inspect the (Date & time)

- ☐ Metal attachment per manufacturer's instructions ☐ Nailing of purlin per metal manufacturer's instructions
☒ Roof deck attachment ☒ Secondary water barrier ☒ Roof to wall connection

work at 438 SE Lillian Loop Lake City, FL 32025
(Job Site Address) Bldg. #438


Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Signature 9/7/21

STATE OF FLORIDA
COUNTY OF

Sworn to and subscribed before me this 1 day of July, 2021

By Ashley Hickerson, Notary Public, State of Florida



Ashley Hickerson
(Print, type or stamp name)

Personally known X or

Produced Identification _____ Type of identification produced. _____

* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

* Photographs must clearly show all work and have the permit number indicated on the roof.

* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.