

NO CHARGE

4

T.S. Debby flood water

PERMIT APPLICATION / MANUFACTURED HOME INSTALLATION APPLICATION

For Office Use Only (Revised 1-11) Zoning Official RLK 8 Aug. 2012 Building Official T.C. 8-6-12

AP# 1208-01 Date Received 8-1-12 By CH Permit # 50355

Flood Zone X Development Permit N/A Zoning RSF-2 Land Use Plan Map Category Res Low Dev.

Comments Voluntarily raising existing MH

FEMA Map# N/A Elevation N/A Finished Floor N/A River N/A In Floodway N/A

☒ Site Plan with Setbacks Shown ☒ EH # final only ☐ EH Release N/A ☒ Well letter ☒ Existing well

☒ Recorded Deed or Affidavit from land owner ☒ Installer Authorization ☒ State Rd Access ☒ 911 Sheet

☒ Parent Parcel # N/A ☒ STUP-MH N/A ☒ F W Comp. letter N/A ☒ App Fee Pd ☒ VF Form

IMPACT FEES: EMS N/A Fire N/A Corr N/A Out County N/A In County N/A

Road/Code N/A School N/A = TOTAL N/A Suspended March 2009 N/A Ellisville Water Sys N/A

Property ID # 22-45-16-63086-203 Subdivision Lobolly Addition S/D Lot 3

▪ New Mobile Home N/A Used Mobile Home ☒ MH Size 26x60 Year 95

▪ Applicant Carlos Rodriguez Phone # 623-2197

▪ Address N/A

▪ Name of Property Owner Carlos Rodriguez Phone# 623-2197

▪ 911 Address 183 SW Lamboy Circle Lake City FL 32024

▪ Circle the correct power company - FL Power & Light - Clay Electric
(Circle One) - Suwannee Valley Electric - Progress Energy

▪ Name of Owner of Mobile Home Same Phone # N/A

Address N/A

▪ Relationship to Property Owner Owner

▪ Current Number of Dwellings on Property 1

▪ Lot Size 1 Ac Total Acreage 1 Ac

▪ Do you : Have Existing Drive or Private Drive or need Culvert Permit or Culvert Waiver (Circle one)
(Currently using) (Blue Road Sign) (Putting in a Culvert) (Not existing but do not need a Culvert)

▪ Is this Mobile Home Replacing an Existing Mobile Home Yes

▪ Driving Directions to the Property 341 S, @ Tunsil St., @ Sparrow Terr., @ Lamboy Cir., 3rd on Right

▪ Name of Licensed Dealer/Installer Ronnie Norris Phone # 752-3571

▪ Installers Address N/A

▪ License Number EH1025451 Installation Decal # 112419

* Water did not get inside the M/H. See Pictures