

## Columbia County BUILDING DEPARTMENT Inspection Affidavit



Permit Number: 3/030
I Robert Feasel ,licensed as a(n) Contractor* /Engineer/Architect, (please print name and circle Lic. Type)  FS 468 Building Inspector*
License #; $\frac{Re}{coo32600}$ On or about $\frac{5/25/13}{\text{(Date & time)}}$ ,
Metal attachment per manufacturer's instructions  Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 359 N.W. Schole Lake drive (Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)  1.C.  Signature  6-3-13
STATE OF FLORIDA COUNTY OF Sworn to and subscribed before me this day of day of love
Personally known or Produced Identification Type of identification produced.

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.