



## Columbia County BUILDING DEPARTMENT

Gilmer

Inspection Affidavit

Permit Number: 31729
I Down Red I teensed as a(n) Contractor* /Engineer/Architect,  (please print name and circle Lie. Type)  FS 468 Building Inspector*
License #; $CCC1330117$ On or about $34/9$ (Date & time)
Metal attachment per manufacturer's instructions Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 18 SE CUSIEN Way lake (14y Ft 3-2055
Based upon that examination I have determined the installation was done according to the Hurricand Mitigation Retrofit Manual (Based on 553.844 F.S.)  3-5-19
Signature
STATE OF FLORIDA COUNTY OF Sworn/to and subscribed before me this
(Print, type or stamp name)
Personally known or Produced Identification Type of identification produced Identification Type of identification produced Identification Type 01 identification produced Identification Involve Identification Produced Identification Identification Produced Identification Ident
* Include photographs of each plane of the roof with plants of the popular points of the clearly shown marked on the deck for each inspection plants between mails.
measure next to the nailing pattern to show distance between nails.

- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.