



Cal-Tech Testing, Inc.

• Engineering P.O. Box 1625 • Lake City, FL 32057
• Geotechnical Tel. (386) 755-3633 • Fax (386) 752-5456
• Environmental 2907 Spring Glen Rd. Jacksonville, FL 32207
• Structural Steel Tel. (904) 381-8901 • Fax (904) 381-8902
LABORATORIES

REINFORCING STEEL INSPECTION

REPORT NO.: 2648001RSI07082026AB

DATE: 7/8/2026
PROJECT #: 26-480-01
PROJECT: FPL Columbia Storm Processing Facility P2
LOCATION: 1855 NW County Road 25A Lake City, FL
CAL-TECH P.M.: Chad Day

CLIENT: Florida Power & Light Company
CONTRACTOR: Pinnacle / Williams-Brown Inc.
INSPECTOR: Andrew Broughton
JURISDICTION: Columbia County/ Permit Number: 000055813
WEATHER: Clear TEMP: 95

Visual inspection was performed of reinforcing steel placement for continuation of footing construction located along Grid Lines B and C, between Grid Lines 1 and 3. The inspected footings were identified as Type WF-6.5 in the footing schedule. Inspection included observation of reinforcing steel size, quantity, spacing, configuration, support, clearances, and general placement in accordance with the approved project construction documents and applicable project details.

Reinforcing steel within the inspected areas was observed to be properly positioned, tied, and supported to maintain required placement during concrete placement. Based on conditions accessible and observed at the time of inspection, the reinforcing steel placement was found to be in accordance with the approved project documents.

Reviewed by: 

To the best of my knowledge, the above WAS performed in accordance with the approved plans. Specification and regulatory requirements.

Superintendent/Representative:

Technician:

X

X Andrew Broughton ICC#9947481



Pictures of Examination

Page 2 of 2



Picture 1: Overall view of WF-6.5 footing reinforcing steel placement within the inspected area.



Picture 2: Overall view of WF-6.5 footing reinforcing steel configuration and placement prior to concrete placement.



Picture 3: Verification of reinforcing steel spacing within the WF-6.5 footing.



Picture 4: Verification of reinforcing steel support and clearance from the footing subgrade.