**From:** Matt Forsyth
**To:** Jeremy Robbins and Jessica Lolo
**Subject:** Construction Test 52257
**Date:** Monday, March 10, 2025 10:29:22 AM

**External Sender** - From: (Matt Forsyth <dccmforsyth@icloud.com>)

This message came from outside your organization.

*WARNING: This message has originated from an External Source. This may be a phishing email that can result in unauthorized access. Please use proper judgment and caution when opening attachments, or clicking links.*

Sent from my iPhone

Cal-Tech Testing, Inc. — FOUNDATIONS • ASPHALT • SOILS • CONCRETE • ENGINEERING • GEOTECHNICAL • ENVIRONMENTAL

# CAL-TECH TESTING, INC.

**ENGINEERING & TESTING LABORATORY**
P.O. Box 1625, Lake City, FL 32056-1625
7540 103rd St. Suite 215 • Jacksonville, FL 32210

Lake City • (386) 755-3633
Fax • (386) 752-5456

Jacksonville • (904) 381-8901
Fax • (904) 381-8902

**JOB NO.:**
**DATE TESTED:** 3-4-25

## REPORT OF IN-PLACE DENSITY TEST

**ASTM METHOD:** ____(D-2922) Nuclear ____(D-2937) Drive Cylinder ____Other

PROJECT: 1165 NE Sheny Gln

52257

CLIENT: David Reyes

GENERAL CONTRACTOR: SAC

EARTHWORK CONTRACTOR:

SOIL USE (SEE NOTE): SAC

SPECIFICATION REQUIREMENTS: 95

TECHNICIAN: 1

MODIFIED (ASTM D-1557): ✓

STANDARD (ASTM D-698):

| TEST NO. | TEST LOCATION | TEST: ___DEPTH ___ELEV. ___LIFT | PROCTOR NO. | WET DENS. LBS.CU.FT. | DRY DENS. LBS.CU.FT. | MOIST PERCENT | % MAX. DENS |
|---|---|---|---|---|---|---|---|
| | SW Corner 10ft N of 5ft E | | | 116.7 | 110.8 | 5.3 | 101 |
| | Center of Pad | | | 113.7 | 108.7 | 4.7 | 99 |
| | NE Corner 10ft S of 5ft W | | | 115.7 | 110.4 | 4.8 | 101 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

REMARKS:

| PROCTOR NO. | SOIL DESCRIPTION | PROCTOR VALUE | OPT. MOIST |
|---|---|---|---|
| | | 109.6 | 11.6 |
| | | | |
| | | | |

NOTE: 1. Building Fill 2. Trench Backfill 3. Base Course 4. Subbase/Stabilized Subgrade 5. Embankment 6. Subgrade/Natural Soil 7. Other
The test results presented in this report are specific only to the samples tested at the time of testing. The tests were performed in accorda generally accepted methods and standards. Since material conditions can vary between test location and change with time, sound ju should be exercised with regard to the use and interpretation of the data.