



Columbia County Fire Rescue

INCIDENT

Incident Number	Incident Date	NFIRS Number	Incident Type	
25-001927	04/10/2025	0001860	(111) - Building fire	
FDID	Station	Shift	District	
29091	43	B Shift	D43	
Initial Dispatch Code				
STRUCTURE FIRE LVL 3				
Alarms	Working Fire?	COVID-19 was a factor	Critical Incident Team	
0				
Temporary Resident Involvement				
Hazardous Materials Released				
Action Taken 1				
(11) - Extinguishment by fire service personnel				
Action Taken 2				
(12) - Salvage & overhaul				
Action Taken 3				
(10) - Fire control or extinguishment, other				

AID

Aid Given/Received
(N) - None

LOCATION

Location Type
(1) - Street address

Address
243 Southwest REIGEL Court, LAKE CITY, Florida, 32024

Cross Street, USNG, or Directions	Latitude	Longitude	Census Tract
	0.00000000	0.00000000	

Detector Alerted Occupant

Property Use
(419) - 1 or 2 family dwelling

Mixed Use

TIMES

PSAP Received	Dispatch Notified Time	Alarm Time
06:43:06, 04/10/2025	06:43:06, 04/10/2025	06:43:06, 04/10/2025

🕒 TIMES

Arrival Time <u>06:53:39, 04/10/2025</u>	Water on Fire Time _____	At Patient Time _____
Loss Stop Time _____	Controlled Time _____	Last Unit Cleared Time <u>10:06:10, 04/10/2025</u>
Total On Scene Time <u>3 hrs 12 mins 31 sec</u>	Total Incident Time <u>3 hrs 23 mins 4 sec</u>	

📊 COUNTS

Counts Include Aid Received?
No

Suppression:		EMS:		Other:	
Apparatus	Personnel	Apparatus	Personnel	Apparatus	Personnel
<u>5</u>	<u>9</u>	<u>0</u>	<u>0</u>	<u>2</u>	<u>2</u>

💰 LOSS

Property:	Content:
Estimated Property Losses <u>\$65000</u>	Estimated Content Losses <u>\$30000</u>
Estimated Property Value <u>\$65000</u>	Estimated Content Value <u>\$30000</u>

👤 PERSON/OWNER

Person:

Name <u>Bryant, Gerald</u>	Business Name _____	Phone <u>(386) 389-0405</u>
-------------------------------	------------------------	--------------------------------

Address
243 Southwest REIGEL Court, LAKE CITY, Florida, 32024

📝 AUTHORIZATION

Report Writer:

Name <u>REDISH, COLLIN</u>	Employee Number <u>CF9</u>	Assignment <u>Collin</u>	Authorization Date <u>04/10/2025</u>
-------------------------------	-------------------------------	-----------------------------	---

Officer in Charge:

Name <u>REDISH, COLLIN</u>	Employee Number <u>CF9</u>	Assignment <u>Collin</u>	Authorization Date <u>04/10/2025</u>
-------------------------------	-------------------------------	-----------------------------	---

Quality Control:

Name <u>REDISH, COLLIN</u>	Authorization Date <u>04/10/2025</u>
-------------------------------	---

 INCIDENT NARRATIVE

Dispatched to the above location for a structure fire. I arrived on scene to a fully involved mobile home. Power was secured at the main panel while doing a 360, no other hazards seemed to be present. While 43 crews were packing out, two preconnect's were pulled. At this time the fire was deemed a defensive attack due to the degradation of the structure, so one crew began fire attack at the front of the home and another crew began extinguishment to add-on at the back. Other crews arrived on scene to assist with water management and manpower. The crews continued to work together to knock down the major fire areas and then proceeded to move into overhaul and extinguishment of hotspots. During fire attack the Fire Marshall was called to do an investigation along with Red Cross to assist with housing and clothing for the occupants of the home. After all hot spots looked secured the entire area was foamed, at this time the crews cleaned up and headed back to the station to put the trucks back in service. The reason for the fire was deemed undetermined by the Fire Marshall.

Created By: REDISH, COLLIN

 Unit Reports

E48

Use	Responding From	Priority
(1) - Suppression		Emergent

Response Delays
None/No Delay

Dispatch Time	Enroute Time	Arrival Time
06:45:09, 04/10/2025	06:47:13, 04/10/2025	07:06:07, 04/10/2025

At Patient Time	Clear Time	In District Time
	10:06:10, 04/10/2025	

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment

Person 1: WOODARD, DUSTIN

Action Taken 1

(73) - Provide manpower

Action Taken 2

(12) - Salvage & overhaul

Action Taken 3

(11) - Extinguishment by fire service personnel

Patient Contact?	Medical PPE Worn
Yes	

Fire Products Exposed To
Smoke, Heat

PPE Worn During Incident

Pant, Coat, Mask, SCBA, Hood, Boots, Structure Firefighting Helmet, Firefighting Gloves

PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth
No	No	No	No

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas, Used wet wipes

Person 2: FRY, BENJAMIN

Action Taken 1

(73) - Provide manpower

Action Taken 2

(74) - Provide apparatus

Action Taken 3

(58) - Operate apparatus or vehicle

Action Taken 4

(11) - Extinguishment by fire service personnel

Patient Contact?

No

Medical PPE Worn

Fire Products Exposed To

Smoke, Heat

PPE Worn During Incident

Structure Firefighting Helmet, Pant, Boots, Hood, Coat

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Used wet wipes, Cleaned neck, face, arms, and exposed areas

Person 3: BURNHAM, DEVEN

Action Taken 1

(73) - Provide manpower

Action Taken 2

(75) - Provide equipment

Action Taken 3

(11) - Extinguishment by fire service personnel

Patient Contact?

No

Medical PPE Worn

Fire Products Exposed To

Smoke, Heat, Fire, Gases/CO, Debris/Runoff, Class A Foam

PPE Worn During Incident

Coat, SCBA, Boots, Structure Firefighting Helmet, Mask, Firefighting Gloves, Pant, Hood

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas, Used wet wipes

Unit Narrative

E48 arrived on scene, Personnel split between Water supply and suppression for the remainder of the operation

Created By: WOODARD, DUSTIN

T51

Use (1) - Suppression	Responding From	Priority Emergent
---------------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

Dispatch Time 06:45:08, 04/10/2025	Enroute Time 06:47:29, 04/10/2025	Arrival Time 07:00:42, 04/10/2025
--	---	---

At Patient Time	Clear Time 10:06:10, 04/10/2025	In District Time
-----------------	---	------------------

Actions Taken:

Provide water, Provide manpower, Provide apparatus, Provide equipment

Person 1: Dowdy, Jonathan

Action Taken 1

(73) - Provide manpower

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(12) - Salvage & overhaul

Patient Contact? No	Medical PPE Worn None
-------------------------------	---------------------------------

Fire Products Exposed To
Smoke, Heat, Fire

PPE Worn During Incident

Coat, Hood, Boots, Pant, SCBA, Firefighting Gloves, Structure Firefighting Helmet, Mask

PPE Malfunction? No	Barrier Breach No	Black Soot Around Nose No	Black Soot Around Mouth No
-------------------------------	-----------------------------	--	---

Decontamination Procedures Completed

Wet brush gear with soap, Used wet wipes, Cleaned neck, face, arms, and exposed areas

Unit Narrative

T51 dispatched to above address for structure fire. T51 arrived on scene and established Tanker to engine connection. T51 crew relieved by D/E Woodard and began firefighting operations, reporting to OIC. T51 crew assisted in knockdown and overhaul. No incidents to note.

-Dowdy 1412

Created By: Dowdy, Jonathan

E51

Use (1) - Suppression	Responding From	Priority Emergent
---------------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

Dispatch Time 06:45:07, 04/10/2025	Enroute Time 06:47:25, 04/10/2025	Arrival Time 07:00:45, 04/10/2025
--	---	---

E51

At Patient Time

Clear Time

In District Time

10:06:10, 04/10/2025

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment

Person 1: BERTRAM, JASON

Action Taken 1

(73) - Provide manpower

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(12) - Salvage & overhaul

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Smoke, Heat

PPE Worn During Incident

SCBA, Firefighting Gloves, Hood, Boots, Structure Firefighting Helmet, Pant, Mask, Coat

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Wet brush gear without soap, Used wet wipes

Person 2: Ruiz, Robert

Action Taken 1

(73) - Provide manpower

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(12) - Salvage & overhaul

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Heat, Smoke

PPE Worn During Incident

Mask, Pant, Coat, Boots, Firefighting Gloves, Hood, Structure Firefighting Helmet, SCBA

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Used wet wipes, Wet brush gear without soap

Unit Narrative

51 arrived on scene and personnel reported to command packed out for assignment. Crew assisted 43 units with extinguishment and latter with salvage and overhaul operations. once the scene was 77 51 helped clean up and roll at which point we cleared and returned to station 48 to get trucks back in service and available for calls.

Created By: BERTRAM, JASON

T43

Use (1) - Suppression	Responding From	Priority Emergent
---------------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

Dispatch Time 06:45:06, 04/10/2025	Enroute Time 06:47:00, 04/10/2025	Arrival Time 06:57:00, 04/10/2025
--	---	---

At Patient Time	Clear Time 10:06:10, 04/10/2025	In District Time
-----------------	---	------------------

Actions Taken:
Provide water

Person 1: FRY, BENJAMIN

Action Taken 1
(73) - Provide manpower

Action Taken 2
(76) - Provide water

Patient Contact? No	Medical PPE Worn None
-------------------------------	---------------------------------

Fire Products Exposed To
Smoke, Heat

PPE Worn During Incident
SCBA, Pant, Structure Firefighting Helmet, Boots, Hood, Firefighting Gloves, Mask, Coat

PPE Malfunction? No	Barrier Breach No	Black Soot Around Nose No	Black Soot Around Mouth No
-------------------------------	-----------------------------	--	---

Decontamination Procedures Completed
Wet brush gear without soap, Used wet wipes

Unit Narrative

Provided manpower and water

Created By: BERTRAM, JASON

E43

Use (1) - Suppression	Responding From	Priority Emergent
---------------------------------	-----------------	-----------------------------

Response Delays
None/No Delay

E43

Dispatch Time

06:45:03, 04/10/2025

Enroute Time

06:48:45, 04/10/2025

Arrival Time

06:53:39, 04/10/2025

At Patient Time

Clear Time

10:06:10, 04/10/2025

In District Time

Actions Taken:

Provide apparatus, Provide manpower, Provide equipment

Person 1: Doyle, Jacob

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(12) - Salvage & overhaul

Patient Contact?

No

Medical PPE Worn

Fire Products Exposed To

Heat, Fire, Smoke, Debris/Runoff

PPE Worn During Incident

Mask, Coat, Hood, Firefighting Gloves, Structure Firefighting Helmet, SCBA, Pant, Boots

PPE Malfunction?

Barrier Breach

Black Soot Around
NoseBlack Soot Around
Mouth

Decontamination Procedures Completed

Wet brush gear without soap, Cleaned neck, face, arms, and exposed areas, Gear bagged, placed outside of cab, Used wet wipes

Person 2: Ingle, Justin

Action Taken 1

(11) - Extinguishment by fire service personnel

Action Taken 2

(12) - Salvage & overhaul

Action Taken 3

(58) - Operate apparatus or vehicle

Patient Contact?

No

Medical PPE Worn

Fire Products Exposed To

Fire, Smoke, Debris/Runoff, Heat

PPE Worn During Incident

Coat, Pant, Boots, SCBA, Firefighting Gloves, Hood, Structure Firefighting Helmet, Mask

PPE Malfunction?

Barrier Breach

Black Soot Around
NoseBlack Soot Around
Mouth

Decontamination Procedures Completed

Wet brush gear without soap, Used wet wipes, Cleaned neck, face, arms, and exposed areas, Gear bagged, placed outside of cab

Unit Narrative

Engine 43 responded to a private residence to a report of a structure fire. Engine 43 attempted to make access off of Placid Ln. but was unable to gain access due to fence. Engine 43 was advised by neighbor that the address of the fire was 243 SW Reigel Ct. Engine 43 turned around and began rerouting to Reigel Ct. Engine 43 found the mailbox and driveway posted with 243 Reigel Ct. but driveway was blocked by a down tree. Engine 43 had to reverse and make entry through a second driveway north of the posted address. Upon arrival Engine 43 found a single story double wide mobile home with an add on to the rear of the structure. Engine 43 noticed heavy fire and smoke on the Alpha and Charlie side of the structure. Engine 43 advised that the roof had self vented and the structure was approximately 70% involved. Engine 43 deployed two 1 3/4 preconnected handlines one to the Alpha side and one to the Charlie side. Engine 43 crews worked on fire extinguishment and containment. After fire was deemed under control Engine 43 assisted with salvage and overhaul. Once Overhaul was complete Engine 43 was released by command and went enroute to Station 48 for clean up. Engine 43 cleared station 48 and was back in service.

Created By: Doyle, Jacob

BAT48

Use	Responding From	Priority
(0) - Other		Emergent

Response Delays

None/No Delay

Dispatch Time

06:55:29, 04/10/2025

Enroute Time

06:55:29, 04/10/2025

Arrival Time

06:59:47, 04/10/2025

At Patient Time

Clear Time

10:06:10, 04/10/2025

In District Time

Actions Taken:

Incident command, Information, investigation & enforcement, other, Notify other agencies.

Personnel

COLLIN REDISH

Unit Narrative

Dispatched to structure fire. Arrived on scene and established command. Redcross and the Fire Marshall were called to the scene.

Created By: REDISH, COLLIN

CF2

Use	Responding From	Priority
(0) - Other		Emergent

Response Delays

None/No Delay

Dispatch Time

06:55:29, 04/10/2025

Enroute Time

06:55:29, 04/10/2025

Arrival Time

07:15:00, 04/10/2025

At Patient Time

Clear Time

08:55:00, 04/10/2025

In District Time

08:55:00, 04/10/2025

Actions Taken:

Provide manpower

Personnel

JEFFREY HILL



SITE INFO

Alarms	Acres Burned	Resident Units In Bldg	Buildings Involved
_____	_____	1	1
Hydrant Identifier	Estimated Water Usage		
_____	_____		

IGNITION

Area of Origin
(24) - Cooking area, kitchen

Heat Source
(UU) - Undetermined

Item First Ignited
(UU) - Undetermined

Fire Confined to Item?

Type of Material First Ignited
(UU) - Undetermined

Cause of Ignition
(U) - Cause undetermined after investigation

Factors Contributing to Ignition 1
(UU) - Undetermined

Human Factors Contributing to Ignition
(N) - None

Est. Age of Person Involved Gender of Person Involved

STRUCTURE

Structure Type
(1) - Enclosed building

Stories Above Grade	Stories Below Grade	Building Status	
1	0	(2) - In normal use	

Length	Width	Total Square Feet	Story of Fire Origin
52 ft	30 ft	1560 sq ft	1

Fire Spread
(4) - Confined to building of origin

Item Contributing Most to Flame Spread Type of Material

Number of Stories with Damage

Minor Damage	Significant Damage	Heavy Damage	Extreme Damage	Total Stories
_____	_____	_____	_____	_____

PROTECTIVE SYSTEMS

Presence of Detector Detector Type
(N) - None present

Power Supply Detector Operations

 **PROTECTIVE SYSTEMS**

Effectiveness (/Failure Reason)

Presence of Auto Extinguishing System
(N) - None Present

System Type

System Operation

of Sprinklers

Reason for System Failure
