



Columbia County Fire Rescue

INCIDENT

Incident Number	Incident Date	NFIRS Number	Incident Type	
23-003437	08/08/2023	0003302	(111) - Building fire	
FDID	Station	Shift	District	
29091	48	B Shift	D48	
Initial Dispatch Code				
Alarms	Working Fire?	COVID-19 was a factor	Critical Incident Team	
01	Yes	No, COVID-19 was not a factor		
Temporary Resident Involvement				
Hazardous Materials Released				
(N) - None				
Action Taken 1				
(11) - Extinguishment by fire service personnel				
Action Taken 2				
(51) - Ventilate				
Action Taken 3				
(12) - Salvage & overhaul				

AID

Aid Given/Received
(N) - None

LOCATION

Location Type			
(1) - Street address			
Address			
492 Southeast PEACOCK Terrace, LAKE CITY, Florida, 32025			
Cross Street, USNG, or Directions	Latitude	Longitude	Census Tract
	0.00000000	0.00000000	
Detector Alerted Occupant			
(U) - Unknown			
Property Use	Mixed Use		
(419) - 1 or 2 family dwelling			

TIMES

PSAP Received	Dispatch Notified Time	Alarm Time
15:20:41, 08/08/2023	15:20:41, 08/08/2023	15:20:41, 08/08/2023

 TIMES

Arrival Time <u>15:29:44, 08/08/2023</u>	Water on Fire Time _____	At Patient Time _____
Loss Stop Time _____	Controlled Time _____	Last Unit Cleared Time <u>16:52:24, 08/08/2023</u>
Total On Scene Time <u>1 hrs 22 mins 40 sec</u>	Total Incident Time <u>1 hrs 31 mins 43 sec</u>	

 COUNTS

Counts Include Aid Received?

No

Suppression:

Apparatus	Personnel
<u>5</u>	<u>7</u>

EMS:

Apparatus	Personnel
<u>0</u>	<u>0</u>

Other:

Apparatus	Personnel
<u>2</u>	<u>2</u>

 LOSS

Property:

Estimated Property Losses

50000

Estimated Property Value

130000

Content:

Estimated Content Losses

None

Estimated Content Value

None PERSON/OWNER

Owner:

Name	Business Name	Phone
<u>Kuck, Emily</u>	_____	_____

Insurance Company	Total Insurance Amount
<u>Universal Property</u>	_____

Address
492 Southeast PEACOCK Terrace, LAKE CITY, Florida, 32025

 AUTHORIZATION

Report Writer:

Name	Employee Number	Assignment	Authorization Date
<u>SHALLAR III, LARRY</u>	<u>1207</u>	_____	<u>08/08/2023</u>

Officer in Charge:

Name	Employee Number	Assignment	Authorization Date
<u>SHALLAR III, LARRY</u>	<u>1207</u>	_____	<u>08/08/2023</u>

Quality Control:

Name	Authorization Date
<u>SHALLAR III, LARRY</u>	<u>08/08/2023</u>

 INCIDENT NARRATIVE

Batt. 48 responded with E-48 and T-48 to the above location in reference to a structure fire. Enroute dispatch advised the homeowner was burning yard debris and it spread to the residents. Batt. 48 arrived on-scene with E-48 and T-48 to a single-family dwelling with heavy smoke coming from the eaves. E-48 crew pulled 200ft of 1.75" pre-connect with fog nozzle and made access through the front door of the residents to search for active fire in the attic. E-48 crew member advised power was shut off at the main breaker and no active fire was inside of the residents. E-48 crew with an attic ladder gained access into the attic and advised there was no signs of active fire, just insulation smoldering. All additional incoming units arrived on-scene with assignments to check for fire extension, ventilate, salvage and overhaul. PPV fan was established at the front door to clear smoke out of the residents. Smoke was cleared out of the residents using the PPV fan and opening windows. Homeowner advised to CF2 that she was burning yard debris in an open fire pit near the residents. She advised the A/D corner of the residents was involved with active fire and it worked its way up into the attic space. Homeowner advised she tried extinguishing the flames using her garden hose until the pump shut off. E-48 crew member checked resident multiple times using a thermal image camera. Salvage and overhaul were complete by all fire units on-scene. No additional hazards were present. Batt. 48 advised to dispatch that the situation was under control, all fire unit's assignment complete, available and scene turn over to homeowner. See unit narratives for any additional information pertaining to each personnel actions on-scene.

Created By: SHALLAR III, LARRY

 Unit Reports

E51

Use (1) - Suppression	Responding From	Priority Emergent
Response Delays None/No Delay		
Dispatch Time 15:22:04, 08/08/2023	Enroute Time 15:23:48, 08/08/2023	Arrival Time 15:36:05, 08/08/2023
At Patient Time	Clear Time 16:50:38, 08/08/2023	In District Time
Actions Taken: Provide manpower, Provide apparatus, Provide equipment		
Person 1: ARCHER, MIKEL		
Action Taken 1 (51) - Ventilate		
Action Taken 2 (12) - Salvage & overhaul		
Action Taken 3 (73) - Provide manpower		
Patient Contact? No	Medical PPE Worn None	
Fire Products Exposed To Heat, Smoke		
PPE Worn During Incident Coat, Pant, Boots, Hood, Mask, Firefighting Gloves, Structure Firefighting Helmet, SCBA		
PPE Malfunction? No	Barrier Breach No	Black Soot Around Nose No
		Black Soot Around Mouth No

Person 1: ARCHER, MIKEL

Decontamination Procedures Completed

Dry brush gear, Cleaned neck, face, arms, and exposed areas

Person 2: FRISINA, CHANDLER

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(51) - Ventilate

Action Taken 3

(12) - Salvage & overhaul

Action Taken 4

(73) - Provide manpower

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Smoke, Heat

PPE Worn During Incident

Coat, Pant, Boots, Hood, Mask, SCBA, Structure Firefighting Helmet, Firefighting Gloves

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Dry brush gear, Cleaned neck, face, arms, and exposed areas

Unit Narrative

Engine 51 was dispatched for a structure fire. Upon our arrival light smoke was showing from the A/D corner eaves. 51 crew used a roof ladder to get access to the peak of the eve on the D side and made an inspection hole in the siding to check and vent the attic. The siding was removed from the burnt corner, no active fire was found. After clean-up, Engine 51 cleared the scene and went to Station 48 to help with putting 48 back in service. Engine 51 went available.

Created By: ARCHER, MIKEL

E45

Use
(1) - Suppression

Responding From

Priority
Emergent

Response Delays
Distance

Dispatch Time
15:22:03, 08/08/2023

Enroute Time
15:25:27, 08/08/2023

Arrival Time
15:36:14, 08/08/2023

At Patient Time

Clear Time
16:52:24, 08/08/2023

In District Time

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment

Person 1: VICKERY, TYLER

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(73) - Provide manpower

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Smoke, Heat, Gases/CO

PPE Worn During Incident

SCBA, Coat, Boots, Firefighting Gloves, Hood, Mask, Structure Firefighting Helmet, Pant

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas

Unit Narrative

E45 dispatched to above location for structure fire, arrived on scene FF Vickery assisted with ventilating the structure and overhaul. Once assignment complete released by Batt48. E45 assignment complete available.

Created By: DOHRN, DYLAN

T45

Use

(1) - Suppression

Responding From

Priority

Emergent

Response Delays

Distance

Dispatch Time

15:22:03, 08/08/2023

Enroute Time

15:25:24, 08/08/2023

Arrival Time

15:36:10, 08/08/2023

At Patient Time

Clear Time

16:52:24, 08/08/2023

In District Time

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment

Person 1: DOHRN, DYLAN

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(73) - Provide manpower

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

None

Person 1: DOHRN, DYLAN

PPE Worn During Incident

Pant, Boots

PPE Malfunction?

No

Barrier Breach

NoBlack Soot Around
Nose**No**Black Soot Around
Mouth**No**

Decontamination Procedures Completed

Cleaned neck, face, arms, and exposed areas**Unit Narrative**

T45 dispatched to above location for structure fire, arrived on scene DE Dohrn was instructed by LT Shallar to set up rehab. Once rehab was set up DE Dohrn assisted with bottle swaps and gathering equipment. once assignment completed released by Batt 48. T45 assignment complete available

Created By: DOHRN, DYLAN

BAT48

Use

(0) - Other

Responding From

Priority

Emergent

Response Delays

None/No Delay

Dispatch Time

15:22:02, 08/08/2023

Enroute Time

15:24:43, 08/08/2023

Arrival Time

15:30:00, 08/08/2023

At Patient Time

Clear Time

16:52:24, 08/08/2023

In District Time

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment**Person 1: SHALLAR III, LARRY**

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(81) - Incident command

Action Taken 3

(51) - Ventilate

Action Taken 4

(12) - Salvage & overhaul

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

None

PPE Worn During Incident

Pant, Boots

PPE Malfunction?

No

Barrier Breach

NoBlack Soot Around
Nose**No**Black Soot Around
Mouth**No**

Person 1: SHALLAR III, LARRY

Decontamination Procedures Completed
Cleaned neck, face, arms, and exposed areas

Unit Narrative

See main narrative.
Created By: SHALLAR III, LARRY

E48

Use	Responding From	Priority
(1) - Suppression		Emergent

Response Delays

None/No Delay

Dispatch Time	Enroute Time	Arrival Time
15:22:02, 08/08/2023	15:24:10, 08/08/2023	15:29:44, 08/08/2023
At Patient Time	Clear Time	In District Time
	16:48:25, 08/08/2023	

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment

Person 1: FRY, BENJAMIN

Action Taken 1
(73) - Provide manpower

Action Taken 2
(74) - Provide apparatus

Action Taken 3
(58) - Operate apparatus or vehicle

Action Taken 4
(11) - Extinguishment by fire service personnel

Patient Contact?	Medical PPE Worn
No	None

Fire Products Exposed To
Debris/Runoff, Gases/CO, Fire, Smoke, Heat

PPE Worn During Incident
SCBA, Firefighting Gloves, Coat, Structure Firefighting Helmet, Pant, Boots, Mask, Hood

PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth
No	No	No	No

Decontamination Procedures Completed
Used wet wipes, Cleaned neck, face, arms, and exposed areas

Person 2: Dowdy, Jonathan

Action Taken 1
(73) - Provide manpower

Person 2: Dowdy, Jonathan

Action Taken 2

(12) - Salvage & overhaul

Action Taken 3

(11) - Extinguishment by fire service personnel

Action Taken 4

(75) - Provide equipment

Patient Contact?

No

Medical PPE Worn

None

Fire Products Exposed To

Debris/Runoff, Gases/CO, Heat, Smoke, Fire

PPE Worn During Incident

Pant, Coat, Boots, Firefighting Gloves, Mask, Structure Firefighting Helmet, Hood, SCBA

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around
Nose

No

Black Soot Around
Mouth

No

Decontamination Procedures Completed

Used wet wipes, Cleaned neck, face, arms, and exposed areas

Unit Narrative

E48 arrived on scene and took offensive action by stretching 1.75" preconnect, extinguishing visible fire and then transitioned to salvage and overhaul.

Created By: WOODARD, DUSTIN

T48

Use

(1) - Suppression

Responding From

Priority

Emergent

Response Delays

None/No Delay

Dispatch Time

15:22:02, 08/08/2023

Enroute Time

15:25:17, 08/08/2023

Arrival Time

15:30:46, 08/08/2023

At Patient Time

Clear Time

16:48:26, 08/08/2023

In District Time

Actions Taken:

Provide manpower, Provide apparatus, Provide equipment, Provide water

Person 1: WOODARD, DUSTIN

Action Taken 1

(73) - Provide manpower

Action Taken 2

(74) - Provide apparatus

Action Taken 3

(76) - Provide water

Action Taken 4

(12) - Salvage & overhaul

Person 1: WOODARD, DUSTIN

Fire Products Exposed To
Smoke, Heat, Fire, Gases/CO, Debris/Runoff

PPE Worn During Incident
Boots, Coat, Hood, Mask, Pant, Firefighting Gloves, Structure Firefighting Helmet, SCBA

PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth
No	No	No	No

Decontamination Procedures Completed
Cleaned neck, face, arms, and exposed areas, Used wet wipes

Unit Narrative

T48 arrived after E48 and supplied water via 3" line to E48 pump panel.
Created By: WOODARD, DUSTIN

CF2

Use (0) - Other	Responding From	Priority Emergent
--------------------	-----------------	----------------------

Response Delays
None/No Delay

Dispatch Time 15:20:41, 08/08/2023	Enroute Time 15:21:00, 08/08/2023	Arrival Time 15:35:00, 08/08/2023
At Patient Time	Clear Time 16:30:00, 08/08/2023	In District Time

Actions Taken:
Provide manpower, Provide apparatus, Provide equipment

Person 1: HILL, JEFFREY

Action Taken 1
(58) - Operate apparatus or vehicle

Action Taken 2
(81) - Incident command

Action Taken 3
(86) - Investigate

Action Taken 4
(73) - Provide manpower

Patient Contact?	Medical PPE Worn
No	None

Fire Products Exposed To
None

PPE Worn During Incident
None

Person 1: HILL, JEFFREY

PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth
<div></div>	<div></div>	<div></div>	<div></div>

Decontamination Procedures Completed
Cleaned neck, face, arms, and exposed areas

Unit Narrative

See main narrative.
Created By: SHALLAR III, LARRY

 Fire Module

 SITE INFO

Alarms	Acres Burned	Resident Units In Bldg	Buildings Involved
<div></div>	<div></div>	1	1
Hydrant Identifier	Estimated Water Usage		
<div></div>	30		

 IGNITION

Area of Origin
(76) - Wall surface: exterior

Heat Source
(80) - Heat spread from another fire, other

Item First Ignited	Fire Confined to Item?
(72) - Light vegetation - not crop, including grass	<div></div>

Type of Material First Ignited

Cause of Ignition
(2) - Unintentional

Factors Contributing to Ignition 1
(73) - Outside/open fire for debris or waste disposal

Human Factors Contributing to Ignition
(3) - Unattended or unsupervised person

Est. Age of Person Involved	Gender of Person Involved
<div></div>	<div></div>

 STRUCTURE

Structure Type
(1) - Enclosed building

Stories Above Grade	Stories Below Grade	Building Status	
1	0	(2) - In normal use	
Length	Width	Total Square Feet	Story of Fire Origin
<div></div>	<div></div>	1575 sq ft	1

 STRUCTURE

Fire Spread
(4) - Confined to building of origin

Item Contributing Most to Flame Spread
(UU) - Undetermined

Type of Material
(UU) - Undetermined

Number of Stories with Damage

Minor Damage

Significant Damage

Heavy Damage

Extreme Damage

Total Stories

 PROTECTIVE SYSTEMS

Presence of Detector
(1) - Present

Detector Type
(U) - Undetermined

Power Supply
(U) - Undetermined

Detector Operations
(U) - Undetermined

Effectiveness (/Failure Reason)
(1) - Detector alerted occupants, occupants responded

Presence of Auto Extinguishing System
(N) - None Present

System Type

System Operation

of Sprinklers

Reason for System Failure