

**PERMANENT NOTICE OF
TERMITE PROTECTION**
(as required by Florida Building Code (FBC) 104.2.7)

Aspen Pest Control, Inc.
(386) 755-3611

This structure has been treated for the prevention of subterranean termites by the above named company. An annual inspection and a renewal of the annual termite protection contract is necessary for continued protection. Call the phone number above for inspection and contract renewal.

9/2025
Expiry Date:

5808 SE COUNTRY CLUB RD, LAL
Address or Location of Treatment

Envelope Leakage Test Report (Blower Door Test)
Residential Prescriptive, Performance or ERI Method Compliance
2023 Florida Building Code Energy Conservation, 8th Edition

Jurisdiction:	Columbia	Permit #: 52608	
Job Information			
Builder:	Amber 12115	Community:	Lot:
Address:	5808 Country Club Rd	Unit:	
City:	Lake City	State:	FL Zip: 32025
Air Leakage Test Results			
X PRESCRIPTIVE METHOD - The building is designed to meet the prescriptive requirements of the 2023 Florida Building Code Energy Conservation, 8 th Edition, Section 104.2.7. The building is designed to meet the prescriptive requirements of the 2023 Florida Building Code Energy Conservation, 8 th Edition, Section 104.2.7. The building is designed to meet the prescriptive requirements of the 2023 Florida Building Code Energy Conservation, 8 th Edition, Section 104.2.7.			
Method for Calculating Building Volume: ☐ Removed from architectural plans ☐ Cold software calculated ☒ Field measured and calculated			
When ACH (50) is less than 5, Mechanical Ventilation Installation must be verified by building inspection.			
1002.4.1.2 Testing. The building or dwelling unit shall be tested as follows: a) The test shall be performed in accordance with the prescriptive requirements of the 2023 Florida Building Code Energy Conservation, 8 th Edition, Section 104.2.7. The test shall be performed in accordance with the prescriptive requirements of the 2023 Florida Building Code Energy Conservation, 8 th Edition, Section 104.2.7. The test shall be performed in accordance with the prescriptive requirements of the 2023 Florida Building Code Energy Conservation, 8 th Edition, Section 104.2.7.			
During testing: 1. All exterior windows and doors, (if present) and some exterior walls shall be closed, but not sealed beyond intended infiltration control measures. 2. Damper including exhaust, intake, make-up, boiler, and air duct dampers shall be closed, but not sealed beyond intended infiltration control measures. 3. Interior doors, if installed at the time of the test, shall be open. 4. Exterior doors for continuous ventilation systems shall be closed and sealed. 5. Heating and cooling systems shall be set to normal operating conditions. 6. All air conditioning systems, if installed at the time of the test, shall be turned off. 7. If an air conditioner is installed at the time of the test, the air conditioner shall be set to normal operating conditions. 8. If an air conditioner is installed at the time of the test, the air conditioner shall be set to normal operating conditions. 9. If an air conditioner is installed at the time of the test, the air conditioner shall be set to normal operating conditions.			
Testing Company			
Company Name: T.C. Testing LLC Phone: 386-365-2049			
I hereby verify that the above Air Leakage results are in accordance with the 2023 Florida Building Code Energy Conservation (8 th Edition) requirements, according to the compliance method selected above.			
Signature of Tester: Will Sikes Date of Test: 9-19-25			
Printed Name of Tester: Will Sikes			
License/Certification #: 5059952 Issuing Authority: BPI			

Created 12/2023