

Building and Zoning Department

Storage Building Application

Invoice

72548

Applicant Information

ANNA SMITH 5745 SW 75TH ST GAINESVILLE, FL 32608

Invoice Date

08/18/2025

Job Location

Parcel: 31-2S-17-04804-107 Owner: SMITH ANNA,

Address:

Permit #	

Amount Due

\$219.00

Contractor Information

ANNA SMITH 5745 SW 75TH ST GAINESVILLE, FLORIDA 32608-

Contact Us

Phone: (386) 758-1008

Customer Service Hours: Monday-Friday From 8:00 A.M. to 4:30 P.M.

bldginfo@columbiacountyfla.com

Website:

http://www.columbiacountyfla.com/Bu ildingandZoning.asp

Address:

Building and Zoning Ste. B-21 135 NE Hernando Ave. Lake City, FL 32055

Invoice History

<u>Date</u>	<u>Description</u>	<u>Amount</u>
08/18/2025	Fee: Application Fee	\$15.00
08/18/2025	Fee: Building Permit Fee Based on Construction Cost	\$100.00
08/18/2025	Fee: Plan Review	\$25.00
08/18/2025	Fee: Certificate Fee	\$2.00
08/18/2025	Fee: DBPR - Surcharge / Radon	\$2.00
08/18/2025	Fee: Flood Zone Certification Fee	\$25.00
08/18/2025	Fee: Zoning Certification Fee	\$50.00
	Amount Due:	\$219.00

Credit card payments can be made online here (fees apply)

Fee balances are not immediately updated using online Credit Card. If you have paid permit fees using the online application site or by another method such as check or cash, please allow time for your payment to be processed.

Inspection Office Hours

Monday - Friday From 8:00 AM to 10:00 AM From 1:30 PM to 3:00 PM

Regular Inspection Schedules

All areas North of County Road 242 From 10:00 AM to Noon

All areas South of County Road 242 From 3:00 PM to 5:00 PM

Inspection Requests

Online: (Preferred Method) Voice Mail: 386-719-2023 or Phone: 386-758-1008

www.columbiacountyfla.com/InspectionRequest.asp

All Driveway Inspections: 386-758-1019 Septic Release Inspections: 386-758-1058

IMPORTANT NOTICE:

Any inspection requested after 4:30 pm, no matter the method, will be received the next business day and will be scheduled by the earliest time slot.

All Inspections require 24 hours notice.

Emergencies will be inspected as soon as possible.