

Building Department

Receipt Of Payment

Applicant Information

JOYCE COLLINS 471 SW STEWART LOOP LAKE CITY, FL 32024 Method
Check 5146

11/12/2025

Payment # 772086

Amount of Payment

\$235.62

AppID: 73565 Permit #: Storage Building

Parcel: 25-4S-16-03165-001

Owner: BRAUN WILLIAM PAUL, COLLINS JOYCE E

Address: 471 SW STEWART LOOP

LAKE CITY FL 32024

Contractor Information

COLLINS JOYCE E

471 SW STEWART LOOP LAKE CITY, , FL 32024

Contact Us

Phone: (386) 758-1008

After Hours: (386) 758-1124

Customer Service Hours: Monday-Friday From 8:00 A.M. to 5:00 P.M.

Email:

laurie_hodson@columbiacountyfla.com

Website:

http://www.columbiacountyfla.com/Build ingandZoning.asp

Address:

Building and Zoning 135 NE Hernando Ave. Lake City, FL 32055

Payment History

<u>Date</u>	<u>Description</u>	<u>Amount</u>
11/11/2025	Fee: Application Fee	\$15.00
11/11/2025	Fee: Building Permit Fee Based on Construction Cost	\$113.20
11/11/2025	Fee: Plan Review	\$28.30
11/11/2025	Fee: Certificate Fee	\$2.00
11/11/2025	Fee: DBPR - Surcharge / Radon	\$2.12
11/11/2025	Fee: Flood Zone Certification Fee	\$25.00
11/11/2025	Fee: Zoning Certification Fee	\$50.00
11/12/2025	Payment: Check 5146	(\$235.62)
		\$0.00

Building Inspector Office Hours

Monday - Friday From 8:00 AM to 10:00 AM and From 1:30 PM to 3:00 PM

Regular Inspection Schedules

All areas North of County Road 242 From 10:00 AM to Noon

All areas South of County Road 242 From 3:00 PM to 5:00 PM To Request Inspections - (Residential, Commercial, Fire, Zoning, & County Driveway Access)

Online: (Preferred Method)

www.columbiacountyfla.com/InspectionRequest.asp

Ph: 386-758-1008, 386-758-1124, 386-719-2023, 386-758-1007 (Leave A Message)

To Call for an Access (Driveway) Inspection: 386-758-1019

Septic Release Inspections: 386-758-1058

IMPORTANT NOTICE:

Any inspection requested after 5:00 pm, no matter the method, will be received the next business day; then that inspection will be scheduled the following business day.

All Inspections require 24 hours notice.

Emergencies will be inspected as soon as possible.