

## COLUMBIA COUNTY BUILDING DEPARTMENT Roof Inspection Affidavit

Permit Number: 43848
I
License #; C C i 330U10 On or about 3 - 8 - 22 3pm , did personally inspect the (Date & time)
Metal attachment per manufacturer's instructions  Nailing of purlin per metal manufacturer's instructions
Roof deck attachment Secondary water barrier Roof to wall connection
work at 284 Sw Waiter Ave (Job Site Address)
Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)  Contractor's Signature
STATE OF FLORIDA COUNTY OF COLUMBIA Sworn to and subscribed before me this <u>8</u> day of <u>March</u> . 2012
By Notary Public, State of Fibrida
Personally known X or
Produced Identification Type of identification produced.

- \* Include photographs of each plane of the roof with the permit number clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.
- \* Photographs must clearly show all work and have the permit number indicated on the roof.
- \* Affidavit and Photographs must be provided when final inspection is requested.
- \* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.