

Envelope Leakage Test Report (Blower Door Test)

2020 F	tial Prescriptive, Perform Florida Building Code, Er	nergy Conservation,	/th Edition
Columb		1 44070	
Jurisdiction: Columb	oia	Permit #: 44070	
Job Information		at lowell ake	Lot: 13
Builder: Morey Doyle	Community: Res	serve at Jewel Lake	LOL.
Address: 160 SW Bre Lar	ne	Unit:	Zip: 32024
City: Lake City	Sta		
Air Leakage Test Results	Passing results must meet either the	e Performance, Prescriptive, or ER	I Method
	17 inch W d [3] DdaCalal		air leakage rate of not exceeding 7 air
PERFORMANCE OF ERI METH	HOD- The building or dwelling unit so yn on FORM R405-2020 (Performant d on Form R405-2020-Energy Calc (Pe	hall be tested and verified as hace) or R406-2020 (ERI), section l	aving an air leakage rate of not exceeding abeled as Infiltration, sub-section ACH50.
1383 × 60 ÷	$\frac{14334}{\text{Building Volume}} = \frac{5}{\text{ACH}(3)}$	79 Method 50)	for calculating building volume: Retrieved from architectural plans Code software calculated
When ACH(50) is less that installation must be verified	n 3, mechanical ventilation		Field measured and calculated
provided to the code official. Testing During testing:	blace and stove doors shall be close, makeup air, back draft and flue time of the test, shall be open.	sed, but not sealed, beyond the dampers shall be closed, but not sealed, beyond the dampers shall be closed all be turned off.	he intended weatherstripping or other infilt
esting Company			
	t Testing LLC	Phone:	386-365-3203
ereby verify that the above Air	Leakage results are in according to the complian		Edition Florida Building Code ve.
nature of Tester:	Frug Bedd	nbaughate o	of Test:
	Amy bederibadgii		nority: BPI
ense/Certification #:			arite