

Air Conditioner Replacement or Repair Application #72102



Wednesday, July 16, 2025 8:25 AM

Checklist:

<input type="checkbox"/> Address	<input type="checkbox"/> Application Submitted	<input type="checkbox"/> Legal Lot of Record
<input type="checkbox"/> Drive/ROW	<input type="checkbox"/> Zoning Review	<input type="checkbox"/> Flood Zone
<input type="checkbox"/> Septic	<input type="checkbox"/> Plans Reviewed	<input type="checkbox"/> FDEP Needed
<input type="checkbox"/> Site Use Approved	<input type="checkbox"/> Required Inspections Assigned	<input type="checkbox"/> Invoiced
<input type="checkbox"/> Docs Reviewed/Accepted		

APPLICANT: JEREMIAH COOK **PHONE:** (386) 752-8558

ADDRESS: 1955 SW MAIN BLVD LAKE CITY, FL 32025

OWNER: SENTER MATTHEW S, SENTER RITA **PHONE:** (386) 365-0705

ADDRESS: 159 SW ROBINSON CT LAKE CITY, FL 32024

PARCEL ID: 11-4S-16-02905-116 **SUBDIVISION:** WOODCREST

LOT: 16 **BLOCK:** A **PHASE:** **UNIT:** **ACRES:** 0.00

CONTRACTOR	TYPE	LIC#	BUSINESS NAME
JEREMIAH COOK	General		COOK'S AIR CONDITIONING AND HEATING

JOB DETAILS

Unit for? House

If "Other", please explain

Unit Type Split-System

Work details for job? Replacement Unit-Change Out(Only)

Exterior Equipment Location Ground

Roof top install:

Model RH2TY3617STANNJ

Seer 14.3

Size (Ton): 2.5

Total Estimated Cost 8500

Commercial or Residential Residential

Commercial type of Building:

Description of Work HVAC CHANGE OUT - Rheem 2.5 Ton 14.3Seer2 split heat pump

Matched systems are required. Select one of the following means: AHRI data

Review Notes: