Permut# 39491

## Mark Disosway, P.E.

163 SW Midtown Place, Suite 103 Lake City, FL 32025, Ph (386) 754-5419

5/29/20

Columbia County Building Department

Re: Edgley Construction | Fender, Wilbur & Sylvia Res.

To whom it may concern:

This letter is in reference to inspection issues on the above referenced project.

- 1. On the engineering we provided we called for (2) 1.75" x 9.25" lvl on the left side of the rear porch. The framer installed (2) 2x10 sp #2 instead.
  - a. The fix is to add (1) 1.75" x 9.25" lvl along side the existing (2) 2x10. New lvl must bear on post w/ (1) LSTA21 to post and at house bear on (2) studs in wall w/ HTS20 beam to studs.

THIS PDF HAS DIGITAL SIGNATURE AND ELECTRONIC SEAL. PRINTED COPIES ARE NOT CONSIDERED SIGNED OR SEALED. YOU MUST VERIFY SIGNATURE ON THIS PDF. CLICK HERE TO VERIFY.



Mark Disosway, PE Florida Professional Engineer #53915