



Building Department

Receipt Of Payment

Applicant Information

JAMES KETCHER
173 SW MILKWEED CT
LAKE CITY, FL 32024

Method

Check 920

Date of Payment

12/03/2025

Payment

772251

Amount of Payment

\$207.16

AppID: 73920 Permit #:
Storage Building
Parcel: 30-4S-17-08898-124
Owner: KETCHER LINDA ANN, KETCHER JAMES DOUGLAS
Address: 173 SW MILKWEED CT
LAKE CITY FL 32024

Contractor Information

KETCHER LINDA ANN,
KETCHER JAMES DOUGLAS

173 SW MILKWEED CT
LAKE CITY, FL 32024

Contact Us

Phone:
(386) 758-1008

After Hours:
(386) 758-1124

Customer Service Hours:
Monday-Friday
From 8:00 A.M. to 5:00 P.M.

Email:
laurie_hodson@columbiacountyfla.com

Website:
<http://www.columbiacountyfla.com/BuildingandZoning.asp>

Address:
Building and Zoning
135 NE Hernando Ave.
Lake City, FL 32055

Payment History

<u>Date</u>	<u>Description</u>	<u>Amount</u>
11/20/2025	Fee: Application Fee	\$15.00
11/20/2025	Fee: Building Permit Fee Based on Construction Cost	\$130.18
11/20/2025	Fee: Plan Review	\$32.54
11/20/2025	Fee: Certificate Fee	\$2.00
11/20/2025	Fee: DBPR - Surcharge / Radon	\$2.44
11/20/2025	Fee: Flood Zone Certification Fee	\$25.00
12/03/2025	Payment: Check 920	(\$207.16)
		\$0.00

Building Inspector Office Hours

Monday - Friday
From 8:00 AM to 10:00 AM
and
From 1:30 PM to 3:00 PM

Regular Inspection Schedules

All areas North of County Road 242
From 10:00 AM to Noon

All areas South of County Road 242
From 3:00 PM to 5:00 PM

To Request Inspections - (Residential, Commercial, Fire, Zoning, & County Driveway Access)

Online: (Preferred Method)

www.columbiacountyfla.com/InspectionRequest.asp

Ph: 386-758-1008, 386-758-1124, 386-719-2023, 386-758-1007 (Leave A Message)

To Call for an Access (Driveway) Inspection: 386-758-1019

Septic Release Inspections: 386-758-1058

IMPORTANT NOTICE:

Any inspection requested after 5:00 pm, no matter the method, will be received the next business day; then that inspection will be scheduled the following business day.

All Inspections require 24 hours notice.

Emergencies will be inspected as soon as possible.