



**COLUMBIA COUNTY  
BUILDING DEPARTMENT  
Roof Inspection Affidavit**

**Permit Number:** 42802

I Tyler Turner, licensed as a(n) Contractor\* /Engineer/Architect,  
Print name FS 468 Building Inspector\*

License #: CCC1330410 On or about 11/1/21,  
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal  
manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 523 NW Brinkley Terr  
(Job Site Address)


Based upon that examination I have determined the installation was done according  
to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

[Signature]  
Contractor's Signature

STATE OF FLORIDA  
COUNTY OF COLUMBIA

Sworn to and subscribed before me this 3 day of November, 2021

By Tyler Turner, Notary Public, State of Florida



Katelynn Hickman  
(Print, type or stamp name)

Personally known ☒ or  
Produced Identification \_\_\_\_\_ Type of identification produced. \_\_\_\_\_

**\* Include photographs of each plane of the roof with the permit  
number clearly shown marked on the deck for each inspection.  
Place a tape measure next to the nailing pattern to show distance  
between nails.**

**\* Photographs must clearly show all work and have the permit  
number indicated on the roof.**

**\* Affidavit and Photographs must be provided when final  
inspection is requested.**

**\* Metal overlay & purlin installations shall have photographs of  
purlins or underlayment, whichever applies.**