

Columbia County Fire Rescue

incident Number 24-003765		Incident Date 08/05/2024	NF(RS Number 0003684	Incident Type (111) - Building	fire	
FDID 29091	Station 48	24/499944499841444444444		Shift B Shift	District D48	
Initial Dispatch Cod FIRE	de					THE CONTRACT OF THE CONTRACT O
Alarms Wor	king Fire? S	COVID-19 was a factor No, COVID-19 was not		ncident Team		
Temporary Resider	nt Involvement	V		н е у се во се объективе на постори в се объективе на постори в се объективе на постори в се объективе на постори		
Hazardous Materia	ils Released	n ngapa na na ngapa na na ngapa na				
Action Taken 1 (10) - Fire contro	l or extinguishmen	t, other				
Action Taken 2 (11) - Extinguish	ment by fire service	personnel				
Action Taken 3 (12) - Salvage & c	overhaul				Meletinista varianteen en seure	
AID Aid Given/Received (N) - None				The second secon		erio de la compositione Distribuir de la compositione
Description -					en e	
Location Type (1) - Street addre	ess					
Address 1240 Southwest	RIDGE Street, LAKE	CITY, Florida, 32024				
Cross Street, USNG	, or Directions			Latitude 0.00000000	Longitude 0.00000000	Census Tract
Detector Alerted Oc	ccupant					
Property Use (400) - Residentia	al, other	A Marie Mari		Mixed Use		
TIMES						
PSAP Received 20:48:55 08/05/2	2024	Dispatch Notified Time	Alarm Ti	me 5 09/05/2024		

INCIDENT NARRATIVE

DISPATCHED TO ADDRESS LISTED FOR A CONFIRMED STRUCTURE FIRE. ARRIVED ON SCENE WITH ENGINE 44 TO A WORKING STRUCTURE. A SINGLE STORY HOME THAT HAD ALREADY VENTED THROUGH THE ROOF. A 360 WAS COMPLETED OF THE STRUCTURE TO LOOK FOR HAZARDS. NO HAZARDS WERE FOUND. TWO PRECONNECTD WERE PULLED TO THE FRONT OF THE STRUCTURE FROM ENG 44. FIRE EXTINGUISMENT BEGAN AFTER ENG44 CREW GOT PACKED OUT. ENTRY WAS MADE THROUGH THE FRONT DOOR. AS OTHER CREWS ARRIVED ON SCENE THEY PACKED OUT AND ASSISTED EXTINGUISHMENT UTILIZING THE OTHER PRECONNECT. THE FIRE HAD SPREAD THROUGH A SIGNIFICANT AMOUNT OF THE ATTIC CAUSING EXTENSIVE OVERHAUL ASWELL AS CAUSING SMOKE DAMAGE THROUGH OUT THE REST OF THE STRCUTURE. AFTER THE HEAVY FIRE WAS EXTINQUISHED THE CREWS MOVED TO ASSESING AND EXTINGUISHING HOT SPOTS. CREWS CLEANED UP AND PUT THEIR TRUCKS BACK IN SERVICE AFTER EXTINGUISMENT WAS COMPLETED.

Created By: REDISH, COLLIN

Unit Reports

None/No Delay Dispatch Time			Responding From					
•		Response Delays None/No Delay						
20:49:54, 08/05/2024	Enroute 20:49:	Time 54, 08/05/2024	Arrival Time 20:56:55, 08/05/2024	Sand-Berg General States (Sand-Berg States) (Sand-B				
At Patient Time	Clear Tir 00:29:0	ne 00, 08/06/2024	in District Time					
Actions Taken: Provide manpower, Pro	vide apparatus, Provid	e equipment, Provide wate	er					
Person 1: WOODARD, DI	JSTIN			The state of the s				
Action Taken 1								
(73) - Provide manpowe	·	NAME OF THE OWNER OWNER OF THE OWNER		MANAGE PARAMETER AND				
Action Taken 2								
(75) - Provide equipmen	t							
Action Taken 3 (11) - Extinguishment by	fire service personnel			To destroy the format of the Color of the Co				
Action Taken 4 (12) - Salvage & overhau	l			AND CONTRACT OF THE PROPERTY O				
Patient Contact? No	Medical PPE Worn							
Fire Products Exposed To Smoke, Heat, Fire, Gase	s/CO, Debris/Runoff							
PPE Worn During Incident Hood, Pant, Coat, Boots,	Mask, Firefighting Glo	ves, Structure Firefighting	Helmet, SCBA	9945 com municipal sem (AMANA AMANA AMANA SEM PANA AMANA SE SE ANTI-SENSE SEM PANA AMANA AMANA AMANA AMANA AMA				
PPE Maifunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Moutin					
		· No	No					