Jimmy Patronis CHIEF FINANCIAL OFFICER

Julius Halas DIVISION DIRECTOR



John Gatlin BUREAU CHIEF

John Walker INSPECTION CHIEF

FLORIDA DEPARTMENT OF FINANCIAL SERVICES DIVISION OF STATE FIRE MARSHAL

200 EAST GAINES STREET - Tallahassee, Florida 32399-0342 Tel. 850-413-3644

November 16, 2022

Mark Winger Culpepper Construction Company 1538 Metropolitan Blvd

Tallahassee, FL 32308

Attention:

Dear Sir/Madam:

FIRE INSPECTION

Parcel #: S-29-0206

Site Name: Florida department of transportation

Inspection Date: 11/15/2022

County: Columbia

Permit #: SFM21-000151

In the interest of life safety for the above named facility a Construction Final Inspection was conducted on 11/15/2022.

I am pleased to report there were no major fire safety violations found during this inspection. Thank you for sharing our fire safety concerns.

The inspection below was conducted in accordance to Florida Statutes, Florida Administrative Rules, current adopted version of the Florida Fire Prevention Code and 4.3.3.I BFP Annual Life Safety Procedures.

Sincerely,

Bradley Dukes, Fire Protection Specialist

Office of Chief Financial Officer Jimmy Patronis

Florida Department of Financial Services

Division of State Fire Marshal

200 East Gaines Street. Tallahassee, FL 32399-0342

Phone: 850-413-3726 Fax: 850-414-6119 Email: bradley.dukes@myfloridacfo.com

cc: File



DEPARTMENT OF FINANCIAL SERVICES

Division of State Fire Marshal - Bureau of Fire Prevention

Fire Safety Inspection Report

Site Address: Agency Address:

Parcel #: S-29-0206	Florida Department of Transportation
Florida department of transportation	
SR 8 I-10	
,	,
	Phone:
	Fax:
Inspection Date: 11/15/2022	
Inspector: Bradley Dukes	

Inspections Performed

File #: 21-000817 Building Name: SR 8(I-10) REST AREA RECONSTRUCTION - COLUMBIA (29170)

Inspection Type: Construction Final Inspection Building #:

Inspection Status: Pass

Inspection Notes: a construction final was performed on the Colombia County WB rest area, I met with Greg Birdsong from Gray Construction, all life safety devices and equipment were operable and tested

No Violations Found