
LANDS OF SYAN RESORT, LLC TAX PARCEL NO. 26-3S-02308-001 ORB 1458, PAGE 1468 NOT A PART

PROPOSED PLOT PLAN FOR GARAGE APARTMENT ON LOT 1, "FAIRWAY VIEW, "UNIT 1 A"", ACCORDING TO THE PLAT THEREOF RECORDED IN PLAT BOOK 4, PAGES 89-89A, PUBLIC RECORDS OF COLUMBIA COUNTY, FLORIDA.





SIGNED: 2

MARK D. DUREN, LS 4708

SURVEYOR'S NOTES: 1. BOUNDARY BASED ON MONUMENTATION FOUND IN ACCORDANCE WITH THE RETRACEMENT OF THE RECORD TITLE BOUNDARIES OF THIS PARCEL TO THE BEST OF MY ABILITY TO INTERPRET AND LOCATE SAID BOUNDARIES BASED ON THE EVIDENCE OF PRIOR SURVEYS AND RECORDS PROVIDED TO OR OTHERWISE OBTAINED BY THIS OFFICE.

OR OTHERWISE OBTAINED BY THIS OFFICE.

2. BEARINGS BASED ON DEED OF RECORD USING MONUMENTS FOUND
ON THE WEST LINE OF THIS PARCEL.

3. PART OF THIS PARCEL IS IN ZONE "X" AND IS DETERMINED TO BE OUTSIDE
THE 500 YEAR FLOOD PLAIN AS PER FLOOD INSURANCE RATE MAP, DATED
NOVEMBER 2, 2018, COMMUNITY PANEL NO. 12023C0280D. HOWEVER, PART OF
THIS PARCEL IS IN FLOOD ZONES "AE" AND "X—SHADED".

4. NO EASEMENT FOR UTILITY AND/OR DRAINAGE IS SHOWN ON THIS LOT
IN RECORDS IN THE POSSESSION OF THIS OFFICE.

5. THE IMPROVEMENTS, IF ANY, INDICATED ON THIS SURVEY DRAWING ARE
AS LOCATED ON DATE OF FIFLD SURVEY AS SHOWN HEREON

AS LOCATED ON DATE OF FIELD SURVEY AS SHOWN HEREON.

6. IF THEY EXIST, NO UNDERGROUND ENCROACHMENTS AND/OR UTILITIES WERE LOCATED FOR THIS SURVEY EXCEPT AS SHOWN HEREON.

"NOT VALID WITHOUT THE ORIGINAL SIGNATURE AND SEAL OF A FLORIDA

LICENSED SURVEYOR AND MAPPER."

CLOSURE OF FIELD SURVEY IS BETTER THAN 1/7500. BOUNDARY AND CONTROL MONUMENTS CAN BE EXPECTED TO HAVE BEEN MEASURED TO APPROXIMATELY THAT RATIO OF PRECISION. BUILDINGS AND, SIMILAR IMPROVEMENTS ARE LOCATED WITHIN ± 0.2 FEET OF THE ACTUAL LOCATION UNLESS OTHERWISE NOTED. OTHER IMPROVEMENTS SUCH AS UTILITY POLES, SEPTIC TANKS, TREES, INTERON FENCES, ETC. ARE NORMALLY WITHIN ± 0.5 FEET UNLESS OTHERWISE NOTED.

9. EXCEPTION IS MADE HEREON REGARDING EASEMENTS, RESERVATIONS, RESTRICTIONS, AND/OR TITLE CONFLICTS OF RECORD, IF ANY, NOT PROVIDED BY THE CLIENT OR HIS AGENTS OR DISCOVERED BY THIS OFFICE. AN EFFORT HAS BEEN MADE IN GOOD FAITH TO SHOW PHYSICAL EVIDENCE OF EASEMENTS, OCCUPATION AND USE BY OTHER PARTIES, HOWEVER PHYSICAL CONDITIONS ON THE PARCEL MAY HAVE PREVENTED DISCOVERY OF ALL SUCH EVIDENCE.

10. CERTIFIED TO:

WALTER DAVA LYNN

SYMBOL LEGEND O.R.I. OFFICIAL RECORD INSTRUMENT

CONCRETE MONUMENT FOUND CONCRETE MONUMENT SET, LS 4708

■ CONCRETE MONUMENT SET, LS 4/08

■ IRON PIN OR PIPE FOUND

■ 5/8" IRON ROD SET, LS 4708

— x— WIRE FENCE

— E— ELECTRIC UTILITY LINE (OVERHEAD)

— UGE — UNDERGROUND ELECTRIC SERVICE

— CIV — CABLE TV LINE (OVERHEAD)


CMP CORRUGATED METAL PIPE RCP REINFORCED CONCRETE PIPE LS LAND SURVEYOR

PRM PERMANENT REFERENCE MONUMENT

- - CHAIN LINK FENCE

LAND SURVEYOR

LICENSED BUSINESS ORB OFFICIAL RECORD BOOK



ASSOCIATES, INC.

LB 7620

1604 SW SISTERS WELCOME ROAD LAKE CITY, FLA. 32025 (386) 758-9831 OFFICE (386) 758-8010 FAX

FIELD SURV DATE DRAW FOR <i>LY</i> A	N JUNE 2	6. 2023		
FIELD BOOK			6	
WO#	2.3-	- 18	8	

(D) DEED, AS IN "DEED DIMENSION"). (P) PLAT, AS IN "PLAT DIMENSIÓN"). (R) RECORD, AS IN "RECORD DIMENSION"). (C) RECORD, AS IN "CALCULATED

DIMENSION").

PCP PERMANENT CONTROL POINT UTILITY POLE R/W RIGHT-OF-WAY NO IDENTIFICATION FLA. D.O.T. FLA. DEPT. OF TRANSPORTATION CENTERLINE CONCRETE MONUMENT IRON ROD

LB

IRON PIPE STATE ROAD DEPARTMENT