



Building and Zoning Department

Remodel Application

Invoice

74099

Applicant Information
TYLER STEVENS 139 SE DUSTIN TER LAKE CITY, FL 32025

Invoice Date
11/07/2025

Permit #

Amount Due
\$169.00

Job Location
 Parcel: 33-3S-17-06768-000
 Owner: STEVENS TYLER ALAN
 Address: 139 SE DUSTIN TER
 LAKE CITY, FL 32025

Contractor Information
CODY BARRS BARRS PLUMBING INC 476 SW BARRS GLEN LAKE CITY, FL 32024

Invoice History

Date	Description	Amount
11/07/2025	Fee: Application Fee	\$15.00
11/07/2025	Fee: Building Permit Fee Based on Construction Cost	\$100.00
11/07/2025	Fee: Plan Review	\$25.00
11/07/2025	Fee: DBPR - Surcharge / Radon	\$2.00
11/07/2025	Fee: Certificate Fee	\$2.00
11/07/2025	Fee: Flood Zone Certification Fee	\$25.00
Amount Due:		\$169.00

Contact Us
Phone: (386) 758-1008
Customer Service Hours: Monday-Friday From 8:00 A.M. to 4:30 P.M.
Email: bldginfo@columbiacountyfla.com
Website: http://www.columbiacountyfla.com/BUILDINGandZoning.asp
Address: Building and Zoning Ste. B-21 135 NE Hernando Ave. Lake City, FL 32055

[Credit card payments can be made online here \(fees apply\)](#)

Fee balances are not immediately updated using online Credit Card. If you have paid permit fees using the online application site or by another method such as check or cash, please allow time for your payment to be processed.

Inspection Office Hours
Monday - Friday From 8:00 AM to 10:00 AM and From 1:30 PM to 3:00 PM

Inspection Requests	
Online: (Preferred Method) www.columbiacountyfla.com/InspectionRequest.asp	Voice Mail: 386-719-2023 or Phone: 386-758-1008
All Driveway Inspections: 386-758-1019	Septic Release Inspections: 386-758-1058

Regular Inspection Schedules
<u>All areas North of County Road 242</u> From 10:00 AM to Noon
<u>All areas South of County Road 242</u> From 3:00 PM to 5:00 PM

IMPORTANT NOTICE:
 Any inspection requested after 4:30 pm, no matter the method, will be received the next business day and will be scheduled by the earliest time slot.
All Inspections require 24 hours notice.
 Emergencies will be inspected as soon as possible.