

# **Columbia County Fire Rescue**

Incident Number 24-004987	Incident Date 10/02/2024	NFIRS Number 0004802	Incident Type (111) - Building	; fire	
FDID Stat 29091 46	ion		Shift C Shift	District D46	
nitial Dispatch Code STRUCTURE FIRE LVL 3					
Alarms Working Fire?  O1 Yes	COVID-19 was a factor Unknown	Critical	Incident Team		
emporary Resident Involvemer	t				
Hazardous Materials Released					
Action Taken 1 (11) - Extinguishment by fire	service personnel				
Action Taken 2 (12) - Salvage & overhaul					
AID					
Aid Given/Received (N) - None					
LOCATION					
Location Type (1) - Street address					
Address 492 Southeast ROBINHOOD	Place, HIGH SPRINGS, Florida, 3	2643			
Cross Street, USNG, or Directions			Latitude <b>0.0000000</b> 0	Longitude <b>0.00000000</b>	Census Tract
Detector Alerted Occupant					
Property Use (419) - 1 or 2 family dwelling	)		Mixed Use		
TIMES					
PSAP Received 20:43:23, 10/02/2024	Dispatch Notified Time 20:43:23, 10/02/2024	Alarm 7 20:43	Time :23, 10/02/2024		
Arrival Time 21:03:00, 10/02/2024	Water on Fire Time	At Pati	ent Time		

PRINTED ON 10/15/2024 AT 3:27 PM

TIMES						
Loss Stop Time	Controll	ed Time		23:47:00, 10/02/202		
Total On Scene Time 2 hrs 44 mins 0 sec		ident Time mins 37 sec				
OF COUNTS						
Counts Include Aid Received?						
Suppression: Apparatus Personnel 7 9	EMS: Apparatus 0	Personnel 0	Other: Apparatus 1	Personnel  1		
\$\preceq Loss						
Property: Estimated Property Losses \$50000  Estimated Property Value \$75000		\$25000	ontent Losses ontent Value		-	
₽ PERSON/OWNER						
Person: Name AMWAKE, JESSICA		Business Na	me		Phone (352) 317-7	066
Address 492 Southeast ROBINHOOD I	Place, HIGH SPRI	NGS, Florida, 320	643			
<b>∯</b> AUTHORIZATION						
Report Writer:						
Name THOMAS, JAMES	Employe CF10	ee Number		Assignment		Authorization Date 10/03/2024
Officer in Charge:						
Name THOMAS, JAMES	Employe CF10	ee Number		Assignment		Authorization Date 10/03/2024
Quality Control:						
Name	Authoria	zation Date				

# **INCIDENT NARRATIVE**

10/03/2024

SHALLAR III, LARRY

RESPONDED FROM STATION TO SAID ADDRESS FOR A STRUCTURE FIRE. ARRIVED ON SCENE BEHIND E-46, E-45, T-45. THEY ADVISED MOBILE HOME WAS HALF INVOLVED. TWO 1 3/4 PRECONNECTS WAS PULLED TO EXTINGISH THE FIRE. CF-10 SPOKE WITH HOMEOWNERS THEY ADVISED THEY WERE OUT EATING AND DID NOT HAVE POWER. WHEN THEY CHECKED THEIR PHONE ON THE APP IT SAID THEY HAD POWER. WHEN THEY ARRIVED HOME THE FIRE WAS IN THE KITCHEN AREA OF THE HOUSE. THREE DOGS WERE ABLE TO GET. TWO DOGS PASSED IN THE FIRE. IT APPEARS THE FIRE MAY HAVE STARTED FROM THE STOVE AREA. CCSO NOTIFIED RED CROSS FOR THE FAMILY. FIRE EXTINGUISHED AND MOP UP COMPLETE, ALL CCFR UNITS RETURNED TO STATION. JAT



Created By: THOMAS, JAMES



3AT48				
Use (0) - Other	Respor	Responding From		Priority Emergent
Response Delays None/No Delay				
Dispatch Time 20:44:30, 10/02/2024	Enrout 20:46	e Time :57, 10/02/2024	Arrival Time 21:03:00, 10/02/2024	_
At Patient Time Clear 23:4		ime :00, 10/02/2024	In District Time	_
Actions Taken: Incident command, I	nvestigate			
Person 1: THOMAS, JA	AMES			
Action Taken 1 (81) - Incident comma	and			
Action Taken 2 (86) - Investigate				
Patient Contact?	Medical PPE Worn None			
Fire Products Exposed To	0			
PPE Worn During Incide None	nt			
PPE Malfunction?	Barrier Breach	Black Soot Around Nose	Black Soot Around Mouth	
Decontamination Proce	dures Completed			

# **Unit Narrative**

RESPONDED FROM STATION TO SAID ADDRESS FOR A STRUCTURE FIRE. ARRIVED ON SCENE BEHIND E-46, E-45, T-45. THEY ADVISED MOBILE HOME WAS HALF INVOLVED. TWO 1 3/4 PRECONNECTS WAS PULLED TO EXTINGISH THE FIRE. CF-10 SPOKE WITH HOMEOWNERS THEY ADVISED THEY WERE OUT EATING AND DID NOT HAVE POWER. WHEN THEY CHECKED THEIR PHONE ON THE APP IT SAID THEY HAD POWER. WHEN THEY ARRIVED HOME THE FIRE WAS IN THE KITCHEN AREA OF THE HOUSE. THREE DOGS WERE ABLE TO GET. TWO DOGS PASSED IN THE FIRE. IT APPEARS THE FIRE MAY HAVE STARTED FROM THE STOVE AREA. CCSO NOTIFIED RED CROSS FOR THE FAMILY. FIRE EXTINGUISHED AND MOP UP COMPLETE, ALL CCFR UNITS RETURNED TO STATION. JAT

Created By: THOMAS, JAMES

E44		
Use	Responding From	Priority
(1) - Suppression		Emergent

14				
Response Delays None/No Delay				
Dispatch Time 20:44:30, 10/02/202	Enroute 4 20:46:	e Time 49, 10/02/2024	Arrival Time 21:11:00, 10/02/2024	_
t Patient Time	Clear Ti 23:47:	me 00, 10/02/2024	In District Time	_
ctions Taken: Provide manpower,	Provide apparatus, Provic	le equipment		
erson 1: LEDGER, O	LIVIA			
action Taken 1 (58) - Operate appar	atus or vehicle			
ction Taken 2 (11) - Extinguishmer	t by fire service personne	el		
atient Contact?	Medical PPE Worn  None			
ire Products Exposed 7 Smoke, Heat, Fire, G	o Gases/CO, Debris/Runoff			
PE Worn During Incide		loves, Mask, Structure Fir	efighting Helmet	
PE Malfunction? <b>No</b>	Barrier Breach <b>No</b>	Black Soot Around Nose	Black Soot Around Mouth	
		No No		
Pecontamination Proc Cleaned neck, face,	edures Completed arms, and exposed areas	;		
Jnit Narrative				
E44 crew assisted v		ushing the fire and mop u	p.	
8				
Jse (1) - Suppression	Respon	ding From		Priority <b>Emergent</b>
esponse Delays None/No Delay				
Dispatch Time	Enroute 4 20:46:	Time 54, 10/02/2024	Arrival Time 21:03:00, 10/02/2024	

In District Time

PRINTED ON 10/15/2024 AT 3:27 PM

Clear Time

Provide manpower, Provide apparatus, Provide equipment, Provide water

23:47:00, 10/02/2024

At Patient Time

Actions Taken:

## Person 1: CHASE, JOSHUA

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

(12) - Salvage & overhaul

Patient Contact?

Medical PPE Worn

No

None

Fire Products Exposed To

Smoke, Heat, Fire, Debris/Runoff, Gases/CO

PPE Worn During Incident

Hood, Firefighting Gloves, Coat, Boots, Mask, SCBA, Structure Firefighting Helmet, Pant

PPE Malfunction?

No

Barrier Breach

No

**Black Soot Around** 

Black Soot Around

Nose No Mouth No

**Decontamination Procedures Completed** 

Cleaned neck, face, arms, and exposed areas

#### **Unit Narrative**

Tanker 48 was dispatched to the above location for a structure fire. Tanker 48 responded from station. T48 arrived on scene and crew reported to command for assignments. T48 crew assisted other CCFR crews with extinguishment, mop up, and overhaul. T48 was then released from the scene by command. T48 cleared the scene, went available, and returned to station.

Created By: HARRELL, LUCAS

48			
Use (1) - Suppression	Responding From		Priority <b>Emergent</b>
Response Delays None/No Delay			
Dispatch Time	Enroute Time	Arrival Time	
20:44:28, 10/02/202	20:46:38, 10/02/2024	21:03:00, 10/02/2024	_
At Patient Time	Clear Time 23:47:00, 10/02/2024	In District Time	_
Actions Taken:			
Provide manpower, I	Provide apparatus, Provide equipment, Provide	e water	
Person 1: HARRELL,	LUCAS		
Action Taken 1			
(11) - Extinguishmen	t by fire service personnel		
Action Taken 2			
(12) - Salvage & over	haul		
Patient Contact?	Medical PPE Worn		
No	None		

#### Person 1: HARRELL, LUCAS

Fire Products Exposed To

Smoke, Heat, Fire, Gases/CO, Debris/Runoff

# Mask, SCBA, Hood, Pant, Firefighting Gloves, Coat, Boots, Structure Firefighting Helmet

**Decontamination Procedures Completed** 

Cleaned neck, face, arms, and exposed areas

# Person 2: BONDS, ANDREW

Action Taken 1

(58) - Operate apparatus or vehicle

Action Taken 2

(11) - Extinguishment by fire service personnel

Action Taken 3

## (12) - Salvage & overhaul

Patient Contact? Medical PPE Worn

No None

Fire Products Exposed To

Debris/Runoff, Heat, Smoke, Gases/CO, Fire

PPE Worn During Incident

## Structure Firefighting Helmet, Hood, Pant, Boots, Coat, Firefighting Gloves, Mask, SCBA

No Nose Mouth No No

Black Soot Around

**Decontamination Procedures Completed** 

Cleaned neck, face, arms, and exposed areas

Barrier Breach

## **Unit Narrative**

PPE Malfunction?

Engine 48 was dispatched to the above location for a structure fire. Engine 48 responded from station. E48 arrived on scene and crew reported to command for assignments. 48 crew assisted other CCFR crews with extinguishment, mop up, and overhaul. Engine 48 was then released from the scene by command. E48 cleared the scene, went available, and returned to station.

Black Soot Around

Created By: HARRELL, LUCAS

#### T45 Use **Responding From** Priority Emergent (1) - Suppression Response Delays None/No Delay Dispatch Time **Enroute Time** Arrival Time 20:44:28, 10/02/2024 20:46:46, 10/02/2024 21:56:00, 10/02/2024 At Patient Time Clear Time In District Time 23:47:00, 10/02/2024

45					
Actions Taken: Provide manpower, Provi	de apparatus, Provide equ	uipment, Provide wate	er		
erson 1: AVAKIAN, JASO	N				
ction Taken 1					
73) - Provide manpower					
ction Taken 2					
74) - Provide apparatus					
ction Taken 3 <b>76) - Provide wate</b> r					
ction Taken 4 <b>75) - Provide equipment</b>					
atient Contact?	Medical PPE Worn				
No	None				
ire Products Exposed To Fire, Heat, Gases/CO, De	bris/Runoff, Smoke				
PE Worn During Incident					
irefighting Gloves, Pant,	Structure Firefighting He	lmet, Hood, Boots, SC	BA, Mask, Coat		
PE Malfunction?	Barrier Breach	Black Soot Around	Black Soot Around		
No	No	Nose No	Mouth <b>No</b>		
econtamination Procedure	es Completed				
nit Narrative					
	46 eng helped set up wat	er supply and then fire	e attack		
Created By: AVAKIAN, JASON					
5					
se 1) - Suppression	Responding F	rom		Priority Emergent	
esponse Delays None/No Delay					
ispatch Time	Enroute Time		Arrival Time		
	20.47.02 1	0/02/2024	21:56:00, 10/02/2024		
10.44:27, 10/02/2024	20:47:02, 10				
20:44:27, 10/02/2024 t Patient Time	Clear Time 23:47:00, 10	0/02/2024	In District Time		
Patient Time	Clear Time	0/02/2024		_	
t Patient Time ctions Taken:	Clear Time		In District Time		
t Patient Time ctions Taken: Provide manpower, Provi	Clear Time 23:47:00, 10 de apparatus, Provide equ		In District Time		
t Patient Time ctions Taken:	Clear Time 23:47:00, 10 de apparatus, Provide equ		In District Time		

# Person 1: ARCHER, MIKEL

Action Taken 2

(73) - Provide manpower

Action Taken 3

(11) - Extinguishment by fire service personnel

Action Taken 4

(12) - Salvage & overhaul

Patient Contact?

Medical PPE Worn

No

None

Fire Products Exposed To

Fire, Smoke, Heat, Gases/CO, Debris/Runoff

PPE Worn During Incident

Firefighting Gloves, Pant, Boots, SCBA, Mask, Coat, Structure Firefighting Helmet, Hood

PPE Malfunction?

No

Barrier Breach

No

Black Soot Around

Black Soot Around

Nose No Mouth No

**Decontamination Procedures Completed** 

Cleaned neck, face, arms, and exposed areas

#### **Unit Narrative**

T46 dispatched to a residential structure fire with multiple other fire units. T46 arrived on scene to provide water and manpower in assistance with firefighter operations. Once under control, and no hazards present, T46 cleared scene and returned to station to assist E46 in clean up, allowing E46 to return to service.

Created By: SELBE, CLIFFORD

45			
Use (1) - Suppression	Responding From		Priority Emergent
(1) - Suppression	_		Lineigent
Response Delays			
None/No Delay			
Dispatch Time	Enroute Time	Arrival Time	
20:44:27, 10/02/2024	20:46:43, 10/02/2024	21:03:00, 10/02/2024	_
At Patient Time	Clear Time	In District Time	
	23:47:00, 10/02/2024		
Actions Taken:			
Provide manpower, Provide	apparatus, Provide equipment, Provide v	vater	
Person 1: PEACE, ERIC			
Action Taken 1			
(73) - Provide manpower			
A.V. T.L. 2			
Action Taken 2			
(58) - Operate apparatus or	vehicle		
Patient Contact? Me	dical PPE Worn		
No			

#### Person 1: PEACE, ERIC

Fire Products Exposed To

Smoke, Gases/CO, Heat, Fire, Debris/Runoff

PPE Worn During Incident

Coat, Boots, SCBA, Mask, Hood, Firefighting Gloves, Structure Firefighting Helmet, Pant

PPE Malfunction?
No

Barrier Breach No Black Soot Around Nose

No

Black Soot Around

Mouth **No** 

**Decontamination Procedures Completed** 

Used wet wipes

**Unit Narrative** 

arrived on scene behind 46 unit and provided manpower for fire attack

Created By: AVAKIAN, JASON

46			
Use (1) - Suppression	Responding From		Priority <b>Emergent</b>
Response Delays None/No Delay			
Dispatch Time 20:44:26, 10/02/2024	Enroute Time 20:47:00, 10/02/2024	Arrival Time 21:56:00, 10/02/2024	_
At Patient Time	Clear Time 23:47:00, 10/02/2024	In District Time	_
Actions Taken: Provide manpower, Pr	rovide apparatus, Provide equipment, Provide v	vater	
Action Taken 1 (58) - Operate apparat Action Taken 2 (73) - Provide manney			
(73) - Provide manpow Action Taken 3 (11) - Extinguishment	by fire service personnel		
Action Taken 4 (12) - Salvage & overh	aul		
Patient Contact? <b>No</b>	Medical PPE Worn  None		
Fire Products Exposed To Smoke, Heat, Fire, Ga	ses/CO, Debris/Runoff		
PPE Worn During Inciden Coat, Pant, Mask, Hoo	nt od, Firefighting Gloves, SCBA, Boots, Structure I	Firefighting Helmet	

#### Person 1: GREENE, JOHN

PPE Malfunction? Black Soot Around Barrier Breach Black Soot Around Nose Mouth Nο Nο No No **Decontamination Procedures Completed** Cleaned neck, face, arms, and exposed areas Person 2: SELBE, CLIFFORD Action Taken 1 (86) - Investigate Action Taken 2 (73) - Provide manpower Action Taken 3 (11) - Extinguishment by fire service personnel Action Taken 4 (12) - Salvage & overhaul Patient Contact? Medical PPF Worn Nο None Fire Products Exposed To Smoke, Heat, Debris/Runoff, Fire, Gases/CO PPE Worn During Incident Coat, Pant, Boots, SCBA, Mask, Hood, Structure Firefighting Helmet, Firefighting Gloves PPF Malfunction? Barrier Breach **Black Soot Around Black Soot Around** Nose Mouth Nο No No No **Decontamination Procedures Completed** 

#### **Unit Narrative**

Cleaned neck, face, arms, and exposed areas

E46 dispatched to a possible residential structure fire reported to have started on the back porch.

46 arrived on scene finding a double wide mobile home, front porch fully involved and impeding into the front of the structure. EMS personnel on scene assisted in flaking out the 1 3/4 jump line to the front of the home. Due to the fallen tin roof of the front porch, entry was inaccessible at this time. D/E Selbe proceeded to do an initial 360, securing power on the delta side, advising all further incoming of an open septic tank in that area as well. Advancing to the Charlie side fire was seen coming out of the 2 windows sitting center of the home and asked for a second line at this time to be advanced around back. Fire began to spread into an open air laundry area as well as through the back door. The beta side of the home was showing light smoke at this time from the eaves.

Returning back to the rear of the structure, a hose line was advanced and used for an offensive fire attack. 20 lb propane tanks had been compromised and began to vent but was quickly cooled and taken out of the hot zone. At this time all units had arrived on scene and all began firefighting operations from the front and the rear of the home. Once under control, mop up and over haul of the home began. With the fire out and the situation under control, the scene was left with the home owner.

Created By: SELBE, CLIFFORD



i SITE INFO					
Alarms	Acres Burned	Resident Units In Bldg	Buildings Involved  1		
Hydrant Identifier	Estimated	Water Usage			
4 IGNITION					
Area of Origin (24) - Cooking area, k	kitchen				
Heat Source (UU) - Undetermined					
Item First Ignited (UU) - Undetermined					Fire Confined to Item?
Type of Material First Ig	nited				
Cause of Ignition (U) - Cause undeterm	lined after investigation				
Factors Contributing to (UU) - Undetermined					
Human Factors Contrib (N) - None	uting to Ignition				
Est. Age of Person Involv	ved Gender of	Person Involved			
STRUCTURE					
Structure Type (2) - Fixed portable o	r mobile structure				
Stories Above Grade	Stories Below Grade 0	Building Status (2) - In normal use			
Length 28 ft	Width 60 ft	Total Square Feet 1680 sq ft	Story of Fire Origin		
Fire Spread (4) - Confined to build	ding of origin				
Item Contributing Most	t to Flame Spread		Type of Material		
Number of Stories w	ith Damage				
Minor Damage	Significant Damage	Heavy Damage	Extreme Damage	Total Stories	
要 PROTECTIVE SYS	TEMS				
Presence of Detector (N) - None present	Detector 1	Гуре			
Power Supply			Detector Operations		

PROTECTIVE SYSTEMS						
Effectiveness (/Failure Reason)						
Presence of Auto Extinguishing System		System Type				
(N) - None Present						
System Operation	# of Sprinklers	Reason for System Failure				