

Materials Testing
Geotechnical Engineering
Environmental
Building Sciences & Safety
Inspections & Code Compliance
Virtual Design Consulting

Certificate of Authorization No. 549 Project No.: 0210.2200049.0000

Report No.: 1114305

Date: February 13, 2024

REPORT ON SITE INSPECTION

Client: Gray Construction Services, Inc.

222 West Wade Street Trenton, FL 32693

Project: Courtyard Marriott - Lake City, FL

Location: 3004 W US Hwy 90, Lake City, Columbia County, FL

Inspected By: Seamless Quality Solutions, LLC

Date Inspected: February 7, 2024

OBSERVATIONS:

Universal Engineering Sciences Subconsultant, Seamless Quality Solutions, LLC, performed a welding inspection for the referenced project. A copy of their report has been attached for your review.



DN: c=US, o=UNIVERSAL ENGINEERING SCIENCES INC., dnQualifier=A01410D000 0018D0E93F533001F1AC B, cn=Keith L Butts

Date: 2024.02.13 16:24:54 -05'00'

Keith L. Butts, P.E. Regional Manager FL Professional Engineer No. 53986

This item has been electronically signed and sealed by Keith L. Butts, P.E. using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.



Inspection Report (UES Gainesville)

Client Information

Client Name	UES Gainesville
Inspection Requested By	Lacy McKettrick
Location	Gainesville, FL
Phone Number	352-372-3392
Email Address	LMcKettrick@teamues.com

Project Information


Point of Contact	Ashton Rush
Phone Number	352-221-4158
Project Name	Courtyard Marriot Lake City
Project Number	0210.2400049.0000
Location	Lake City FI

Inspection

mapedion	
Report Number	240055
Date of Service	02/07/2024
Time of Service	10:30
Reference Documents	Contract Documents
Reference Codes	AWS D1.1
Drawings	Structural drawings
Inspection Performed	In-Process/At Completion
Inspection Frequency	Periodic
Area of Inspection / Column Lines	Re-inspection of RFI welds on elevator shaft.



Inspection Report (UES Gainesville)



Additional Notes

Compliance Results	In compliance
Observation Results	Based on our visual observations, the connections observed at the referenced locations appeared to be the proper size, type, in the proper location and placed in general accordance with the identified referenced documents.
Comments	Visually inspected welds on RFI#71 after completion.
Exceptions	None
Attached File (1)	Click to Download

Signoff

Statement	Thank you for allowing SQS, LLC the opportunity to provide construction inspection services for this project. Should you have any questions and/or comments, please contact us at any time.
Inspector Name	Robert Evans
CWI Number	23022871



Inspection Report (UES Gainesville)

Signature of Inspector	49
------------------------	----