

Air Conditioner Replacement or Repair Application #75215



Tuesday, March 3, 2026 4:16 PM

Checklist:

| | | |
|---|--|--|
| <input type="checkbox"/> Address | <input type="checkbox"/> Application Submitted | <input type="checkbox"/> Legal Lot of Record |
| <input type="checkbox"/> Drive/ROW | <input type="checkbox"/> Zoning Review | <input type="checkbox"/> Flood Zone |
| <input type="checkbox"/> Septic | <input type="checkbox"/> Plans Reviewed | <input type="checkbox"/> FDEP Needed |
| <input type="checkbox"/> Site Use Approved | <input type="checkbox"/> Required Inspections Assigned | <input type="checkbox"/> Invoiced |
| <input type="checkbox"/> Docs Reviewed/Accepted | | |

APPLICANT: Casey Dailey **PHONE:** (407) 593-4618

ADDRESS: 2559 NE 18th Terrace Suite 20, Gainesville, FL 32609

OWNER: NORTH CENTRAL FLORIDA HOSPICE INC **PHONE:** (386) 752-9191

ADDRESS: 6037 W US HIGHWAY 90 LAKE CITY, FL 32055

PARCEL ID: 29-3S-16-02382-006 **SUBDIVISION:**

LOT: _____ **BLOCK:** _____ **PHASE:** _____ **UNIT:** _____ **ACRES:** 6.79

| CONTRACTOR | TYPE | LIC# | BUSINESS NAME |
|-------------|---------|-----------|--------------------|
| James Grady | General | CAC057724 | TWC Services, INC. |

| JOB DETAILS | |
|------------------------------|-----------------------------------|
| Unit for? | Business |
| If "Other", please explain | Haven Hospice |
| Unit Type | Split-System |
| Work details for job? | Replacement Unit-Change Out(Only) |
| Exterior Equipment Location | Ground |
| Roof top install: | |
| Model | Please see description |
| Seer | Please see description |
| Size (Ton): | 12.5 |
| Total Estimated Cost | 297980.60 |
| Commercial or Residential | Commercial |
| Commercial type of Building: | Haven Hospice |

Description of Work

Split AC System #1
Exterior Equipment Location – Ground
Model – AHU: V3-BRB-3-0-462C-7CS:BF1B-HHH-000-
0A0-B0A00V0-00-D0000B000 CU:CFA-011-B-A-3-
LA00N:0-00-E0-A0-AN0-L-QE0A-0000G00-0A000DB
Seer – EER 11
Ton - 6
Valuation \$95,232.97

Split AC System #2
Exterior Equipment Location - Ground
Model – CHL121LMA0A000/FHL120L2AA0AUA
Seer – EER 11
Ton - 10
Valuation \$42,540.35

Split AC System #6
Exterior Equipment Location - Ground
Model - CHL091LMA0A000/FHL091L2AA0AUA
Seer – EER 11.2
Ton - 7.5
Valuation - \$33,573.41

Split AC System #14
Exterior Equipment Location - Ground
Model – AHU: V3-CRB-3-0-462C-7BS:B12B-HHH-000-
0A0-B0A0020-00-DA000B0000 CU:CFA-020-C-A-3-
LA00N: 0-00-E0-A0-AN0-L-QE0A-0000G00-0A000DB
Seer – EER 11.4
Ton – 12.5
Valuation \$126,633.87

Matched systems are required. Select one of the following means:

AHRI data

Review Notes: