

Walker, Henry



Columbia County
BUILDING DEPARTMENT
Inspection Affidavit

Permit Number: 31869

Don Reed licensed as a(n) Contractor* / Engineer / Architect,
(please print name and circle 1 i.e. type) FS 468 Building Inspector*

License #: CCC1330117 On or about May 23, 2014
did personally inspect the (Date & time)

☒ Metal attachment per manufacturer's instructions ☒ Nailing of purlin per metal manufacturer's instructions

☐ Roof deck attachment ☐ Secondary water barrier ☐ Roof to wall connection

work at 175 St. Mohawk Way, Lakeland, FL 32025
(Job Site Address)

Based upon that examination I have determined the installation was done according to the Hurricane Mitigation Retrofit Manual (Based on 553.844 F.S.)

Signature Don Reed

OK
rc.
6-2-14


STATE OF FLORIDA
COUNTY OF

Sworn to and subscribed before me this 23 day of May, 2014

By Ivy Denise Milligan-Boose Notary Public, State of Florida

Ivy Denise Boose
(Print, type or stamp name)

Personally known ☒ or
Produced Identification ☐ Type of identification produced



* Include photographs of each plane of the roof clearly shown marked on the deck for each inspection. Place a tape measure next to the nailing pattern to show distance between nails.

* Photographs must clearly show all work and have the permit number indicated on the roof.

* Affidavit and Photographs must be provided when final inspection is requested.

* Metal overlay & purlin installations shall have photographs of purlins or underlayment, whichever applies.